

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Asset: P.S. 10 - BROOKLYN, 511 7TH AVENUE, New York, 11215

Inspection Id	Inspection Type	Time In	Last Edited
EE : K010	Electrical	2018-03-01 8:45 AM	2018-03-08 11:33 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Auditorium - Except (House Lighting), Gymnasium (LED Lighting), Partial Emergency Lighting (Battery Pack)
	Years: 2017
	Systems: Auditorium (LED Lighting), Computer Lab - Room 114 (Raceway with Receptacles)
	Years: 2016
	Systems: Fire Alarm System (Except Tamper Flow Switch/Chain)
	Years: 2014
	Systems: Interior Fluorescent Lighting - Except (Library, Science Labs), Kitchen (Retrofitted Fluorescent Lighting)
	Years: 2012
	Systems: Exit Lights (Battery Pack), Exit/Emergency Lights
	Years: 2011
	Systems: Science Labs, Telephone System, LAN
	Years: 2009
	Systems: Intercom System
	Years: 2007
	Systems: Emergency Light/Exit Light Panel, Security Lights
	Years: 2006
	Systems: Public Address System, Local Sound System
	Years: 2005
	Systems: Library, Intrusion Alarm System
	Years: 2004
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1994, 2000, 2014
	Systems: Most Fused Disconnect Switch Type Panel Board
	Years: 1994

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2017
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Question	Response
CAFETERIA	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	43
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
	Inspected
Instance on Room 114	Inspected
Power Panel	No
Lighting	Inspected
Instance on Room 114	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 114	Inspected
Pendant Mounted	
Instance on Room 114	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 114	Does not Exist
Recessed Mounted	
Instance on Room 114	Does not Exist
Lighting Fixture - HID	
Instance on Room 114	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 114	Does not Exist
Lighting Fixture - LED	
Instance on Room 114	Does not Exist
Raceway With Receptacles	
	Inspected
Instance on Room 114	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GYMNASIUM	
	Inspected
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Local Sound System	Inspected
Instance on 3rd Floor	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 3rd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 306	Inspected
Lighting	Inspected
Instance on Room 306	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 306	Inspected
Pendant Mounted	Inspected
Instance on Room 306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 306	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 306	Does not Exist
Lighting Fixture - HID	
Instance on Room 306	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 306	Inspected
Pendant Mounted	Does not Exist
Instance on Room 306	Does not Exist
Surface Mounted	Inspected
Instance on Room 306	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 306	Does not Exist
Lighting Fixture - LED	
Instance on Room 306	Does not Exist
Raceway With Receptacles	
Instance on Room 306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
LIBRARY	Inspected
Projection System	Does not Exist
Instance on Room 306	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 314	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 316	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 316	Inspected
Instance on Room 314	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 316	Inspected
Instance on Room 314	Inspected
Pendant Mounted	Inspected
Instance on Room 316	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 314	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Lighting Fixture - HID	
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Lighting Fixture - LED	
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
Emergency Shut-Off Power	Inspected
Instance on Room 316	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 314	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
SCIENCE LAB	
Power Supply	Inspected
Instance on Room 316	Inspected
Instance on Room 314	Does not Exist
Instructor Unit	
Instance on Room 316	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 316	Does not Exist
Meter Demonstration Unit	
Instance on Room 316	Does not Exist
Projection System	Does not Exist
Instance on Room 316	Does not Exist
Instance on Room 314	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	77,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CITY FIRE ALARM SYSTEM	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor By General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	77,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 3
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LAN	
Local Distribution Frame (I/LDF)	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
MOTOR CONTROL CENTER	
MOTOR STARTER/CONTACTOR	
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	
Fused Disconnect Switch Type	
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor (4th, 3rd, 2nd) Floor, Boiler Room
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor (4th, 3rd, 2nd) Floor, Cafeteria, Room 152
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K010

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	77,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland FAX 250
Installation Year	2005
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Does not Exist
Intrusion Alarm System	
	Inspected
Replacement Quantity	77,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2004
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	30
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	MAIN SWITCH 2000 AMP. FUSES
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	N/A
Capacity/Size Quantity	2,000

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K010

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1967
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist