

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

Asset: P.S. 29 - BROOKLYN, 425 HENRY STREET, New York, 11201

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|---------------------|
| EE : K029 | Electrical | 2018-02-09 8:45 AM | 2018-02-21 10:15 AM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: IPDVS/CCTV System |
| | Years: 2015 |
| | Systems: Security Lights, Exit/Emergency Lights |
| | Years: 2013 |
| | Systems: Telephone System, LAN |
| | Years: 2009 |
| | Systems: Auditorium (Local Sound System) |
| | Years: 2004 |
| | Systems: Interior Fluorescent Lighting |
| | Years: 2003 |
| | Systems: Emergency Light/Exit Light Panel |
| | Years: 2000 |
| | Systems: Intrusion Alarm System |
| | Years: 1998 |
| | Systems: Public Address System (Amplifier) |
| | Years: 1995 |
| | Systems: Partial Molded Case Circuit Breaker Panel Board |
| | Years: 1988, 1987, 2013 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---|-----------------------|---------------------------------|----------------------|--------------------|-----------------|-------------|------------|
| Yes | Local Sound System - Not Connected to Public Address System | N/A | AUDITORIUM Local Sound System | 2nd Floor | Emmanuel Torres | Custodian | Sent to DSF | |

Inspection

| Question | Response |
|---------------------------------------|----------------|
| Electrical | |
| AUDITORIUM | Inspected |
| Instance on 2nd Floor | Inspected |
| House Lighting | Inspected |
| Does a Chandelier exist? | No |
| Instance on 2nd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 2nd Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 2nd Floor | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|---|--|
| AUDITORIUM | |
| House Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | Inspected |
| Instance on 2nd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Recessed Mounted | Does not Exist |
| Instance on 2nd Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 2nd Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 2nd Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 2nd Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 2nd Floor | Inspected |
| Installation Year | 2004 |
| Source of Installation | Custodial Staff |
| Condition | 3 - Fair |
| Deficiency | NOT CONNECTED TO PUBLIC ADDRESS SYSTEM |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL CONNECTION |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Projection System | Inspected |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Instance on 2nd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | Inspected |
| Instance on 2nd Floor | Inspected |
| Dimming System | |
| Instance on 2nd Floor | Does not Exist |
| Theater Lighting | |
| Instance on 2nd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 35 |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|--|--------------------------|
| AUDITORIUM | |
| Theater Lighting System | |
| Theater Lighting | |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| CAFETERIA | |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Installation Year | 1990 |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Projection System | |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | |
| Instance on 1st Floor | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | |
| | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| COMPUTER LAB | Does not Exist |
| GYMNASIUM | Inspected |
| Instance on 4th Floor | Inspected |
| Lighting | Inspected |
| Instance on 4th Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 4th Floor | Inspected |
| Pendant Mounted | Inspected |
| Instance on 4th Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 4th Floor | Does not Exist |
| Local Sound System | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Projection System | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Scoreboard | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| KITCHEN | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|--|--------------------------|
| KITCHEN | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| LIBRARY | Inspected |
| Instance on Room 408 | Inspected |
| Lighting | Inspected |
| Instance on Room 408 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 408 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room 408 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room 408 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on Room 408 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 408 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 408 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 408 | Does not Exist |
| Raceway With Receptacles | Inspected |
| Instance on Room 408 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on Room 408 | Does not Exist |
| LOCKER ROOM | Does not Exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor - South, North | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor - South, North | Inspected |
| Lighting Fixture - Fluorescent | |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|--|--------------------------|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor - South, North | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor - South, North | Does not Exist |
| Surface Mounted | Inspected |
| Instance on 1st Floor - South, North | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor - South, North | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor - South, North | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor - South, North | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor - South, North | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor - South, North | Inspected |
| Installation Year | 1990 |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Projection System | Does not Exist |
| Instance on 1st Floor - South, North | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor - South, North | Does not Exist |
| SCIENCE DEMO ROOM | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|---|--|
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 78,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LESS THAN 20% SPARE CIRCUIT BREAKERS |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | 2nd Floor by Room 211, Auditorium, Cafeteria, Multipurpose Room North, Multipurpose Room South |
| Deficiency Quantity | 7 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 4 |
| Deficiency Photo1 | No photo recorded |
| Violations | 35260148P |
| Non Battery Pack | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|--|--------------------------|
| EMERGENCY LIGHTING | Inspected |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| CITY FIRE ALARM SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 78,000 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Does not Exist |
| Manual Pull Station | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not Exist |
| Duct Smoke Detector | Does not Exist |
| Area Smoke Detector | Does not Exist |
| CO Detector | Does not Exist |
| Heat Detector | Does not Exist |
| Elevator Recall | Does not Exist |
| Magnetic Door Holder/Contactor | Does not Exist |
| Fused Cutout Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Does not Exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Edwards |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|--|------------------------------------|
| FIRE ALARM SYSTEM | |
| Main Panel | |
| Fire Alarm Control Panel (Standard) | |
| Equipment | Fire Alarm Control Panel |
| Capacity/Size Quantity | 7 |
| Capacity/Size UOM | Circuits |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1960 |
| Source of Installation | Inspector Estimate |
| Deficiency | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity | 78,000 |
| Quantity Uom | S.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Sub-Panel | Does not Exist |
| Remote Annunciator | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Does not Exist |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|---|---|
| PANEL BOARD | |
| Fused Disconnect Switch Type | Does not Exist |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Corridor (5th, 4th, 3rd, 2nd, 1st) Floor, Kitchen |
| Deficiency Quantity | 8 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | Multipurpose Room North, Multipurpose Room South, 3rd Floor Corridor By Room 318 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 78,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | N/A |
| Installation Year | 1980 |
| Source of Installation | Inspector Estimate |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Classrooms and Corridors |
| Deficiency Quantity | 78,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | SPEAKER NOT OPERATIONAL |
| Deficiency Location/Instance | Rooms 323, 318 |
| Deficiency Quantity | 78,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|-------------------------------|--------------------------|
| PUBLIC ADDRESS SYSTEM | |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Replacement Quantity | 78,000 |
| Replacement Uom | S.F. |
| Installation Year | 2015 |
| Source of Installation | Custodial Staff |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | Inspected |
| Replacement Quantity | 78,000 |
| Replacement Uom | S.F. |
| Central Control Panel | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 50P |
| Installation Year | 1998 |
| Source of Installation | Inspector Estimate |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | Does not Exist |
| Lighting - Security | Inspected |
| Replacement Quantity | 14 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|---------------------------------|---------------------------|
| SECURITY | Inspected |
| Lighting - Security | |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Gallagher |
| Equipment | N/A |
| Capacity/Size Quantity | 1,000 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1960 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Challenger |
| Equipment | N/A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1960 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SWITCHBOARD | Inspected |
| Number of Spares | 0 |
| Air Circuit Breaker Type | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K029

| Question | Response |
|---|---------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | Does not Exist |
| Fused Knife Switch Type | Inspected |
| Instance | Electrical Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Gallagher Switchboard Co. |
| Equipment | Main AC Light Dist. |
| Capacity/Size Quantity | 1,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1960 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Gallagher Switchboard Co. |
| Equipment | 24 HR Fan Room SW Panel |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1960 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | CAFETERIA - 1st Floor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Molded Case Circuit Breaker Type | Does not Exist |
| TELEPHONE SYSTEM | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K029

| Question | Response |
|-------------------------|---------------------------|
| TELEPHONE SYSTEM | |
| PBX/Intercom | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not Exist |
| TV SYSTEM | Does not Exist |