

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

Asset: P.S. 158 - BROOKLYN, 400 ASHFORD STREET, New York, 11207

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| ME : K158 | Mechanical | 2018-02-01 8:57 AM | 2018-02-02 2:30 PM |

Asset Data

| Question | Answer |
|--|---|
| Are there fuel tanks? | Yes |
| Total # of above ground tanks | 1 |
| Total capacity of all above ground tanks in gal. | 8,000 |
| Total # of below ground tanks | 0 |
| Total capacity of all below ground tanks in gal. | 0 |
| Total # of water main service entries to the asset | 2 |
| MERs/Fan Rooms Locations | Basement MER |
| Are there any spaces with Missing or Defective CO Detectors? | No |
| Are there any Emergency Stop Switches with Missing Hammers? | No |
| Are there any Painted/Obstructed Sprinkler Heads? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Kitchen; Packaged / Rooftop Unit; Heating And Ventilating Unit; Unit Ventilators; Hydronic Heating; Fixtures - Student: Lavatory/Sinks (25%), Toilets (25%), Urinals (50%); Electric Domestic Water Heater; F&T/Steam Drip Traps; Terminal Unit Thermostatic Traps |
| | Years: 2017 |
| | Systems: Water Service (1 of 2); Fixtures - Student: Lavatory/Sinks (25%), Toilets (25%), Urinals (50%) |
| | Years: 2010 |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded | | | | | | | | |

Inspection

| Question | Response |
|---|-----------------|
| Mechanical | |
| AIR CONDITIONING | Inspected |
| Chilled Water System | Does not Exist |
| Condenser Water Distribution: Piping, Pumps and Auxiliaries | Does not Exist |
| Cooling Coil in Ductwork | Does not Exist |
| Cooling Tower | Does not Exist |
| DX Split System | Does not Exist |
| Dry Cooler | Does not Exist |
| Packaged / Rooftop Unit | Inspected |
| Instance | Cafeteria Roof |
| Instance Condition | 1 - Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Source of Heating | Gas |
| Instance Manufacturer | Daikin |
| Equipment | RTU-1 |
| Capacity/Size Quantity | 30 |
| Capacity/Size UOM | Tons |
| Source of Capacity/Size | Custodial Staff |
| Installation Year | 2017 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|---|--|
| AIR CONDITIONING | |
| Packaged / Rooftop Unit | |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Packaged Terminal A/C | Does not Exist |
| Refrigerant Piping | Does not Exist |
| Return Fan | Does not Exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | |
| CLIMATE CONTROL SYSTEM | |
| BMS | Does not Exist |
| Pneumatic System | |
| Instance | Throughout |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 81-100% |
| Deficiency | DEFECTIVE REFRIGERATED AIR DRYER |
| Deficiency Location/Instance | Boiler Room (pneumatic leaks) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PNEUMATIC TUBING:DEFECTIVE/LEAKS AIR |
| Deficiency Location/Instance | Gymnasium, Stairway adjacent to Exit 2, Room 402 |
| Deficiency Quantity | 30 |
| Quantity Uom | L.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL THERMOSTAT |
| Deficiency Location/Instance | Room 308 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Hybrid System | Does not Exist |
| Electric System | Does not Exist |
| COMPACTOR | Does not Exist |
| CONVEYING | Does not Exist |
| DOMESTIC WATER SYSTEM | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Mechanical Inspection

K158

| Question | Response |
|---|--------------------------------------|
| DOMESTIC WATER SYSTEM | |
| Domestic Cold Water System | Inspected |
| Gravity System | Does not Exist |
| Pressure Booster System | Inspected |
| Electric Pressure Booster System | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Federal Pump |
| Equipment | N/A |
| Capacity/Size Quantity | 3 |
| Capacity/Size UOM | Total # Pumps |
| Capacity/Size2 Quantity | 13 |
| Capacity/Size2 UOM | Total Pumps HP |
| Source of Capacity/Size | Documented |
| Installation Year | 2001 |
| Source of Installation | Documented |
| Deficiency | RUSTY/LEAKY VALVES AND PIPE FITTINGS |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | DEFECTIVE PUMP |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Hydraulic/Pneumatic Booster System | Does not Exist |
| Water Service | Inspected |
| Instance | Sub-Basement East |
| Instance Condition | 1 - Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Deficiency | No deficiencies recorded |
| Instance | Sub-Basement West |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Deficiency | No deficiencies recorded |
| Domestic Hot Water System | Inspected |
| Domestic Hot Water Remote Storage Tank | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|--|---------------------------|
| DOMESTIC WATER SYSTEM | |
| Domestic Hot Water System | |
| Domestic Hot Water Remote Storage Tank | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Domestic Water Heat Exchanger | Does not Exist |
| Electric Domestic Water Heater | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Gas Fired Domestic Water Heater | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Lochinvar |
| Equipment | N/A |
| Capacity/Size Quantity | 225 |
| Capacity/Size UOM | MBH Input |
| Capacity/Size2 Quantity | 0 |
| Capacity/Size2 UOM | Gallons |
| Source of Capacity/Size | Documented |
| Installation Year | 2001 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Oil Fired Domestic Water Heater | Does not Exist |
| Domestic Water Distribution Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Inspected |
| Interior Storm Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not Exist |
| Sump Pump | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Does not Exist |
| FIXTURES | Inspected |
| Staff And Other | Inspected |
| Janitor Sink | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|-------------------------------------|---|
| FIXTURES | |
| Staff And Other | Inspected |
| Toilet | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Urinal | Does not Exist |
| Student | Inspected |
| Drinking Fountain | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.) |
| Deficiency Location/Instance | 3rd Floor Boy's Toilet Room |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Locker Room Shower | Does not Exist |
| Sink And Fountain Combo Unit | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Urinal | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GAS FIRED FURNACE | Does not Exist |
| GAS SERVICE | Inspected |
| Gas Distribution Piping | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Exhaust Fan | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Vent | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Gas Pressure Booster | Does not Exist |
| CO/Gas Leak Detection | Inspected |
| Instance | Boiler Room and Gas Meter Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Installation Year | 2001 |
| Source of Installation | Documented |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|---|--|
| GAS SERVICE | |
| CO/Gas Leak Detection | |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room and Gas Meter Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| HEATING | |
| | Inspected |
| Heating Coil In Ductwork | Does not Exist |
| Hydronic Heating | Inspected |
| Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries | Inspected |
| Condition | 1 - Good |
| Deficiency | PUMP: DEFECTIVE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Backflow Preventer | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Hot Water Heat Exchanger | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Radiator/Convactor/Fin Tube | Inspected |
| Condition | 3 - Fair |
| Deficiency | RADIATOR/CONVECTOR: DEFECTIVE/DETERIORATED |
| Deficiency Location/Instance | Corridor adjacent to Custodial Office |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | AUXILIARY (VALVE, VENT): DEFECTIVE |
| Deficiency Location/Instance | 1st Floor Stairway D, Rooms 209, 303, 313 |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|---|--|
| HEATING | |
| Radiator/Convactor/Fin Tube | |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | RADIATOR/CONVECTOR: MISSING GUARD/SHIELD |
| Deficiency Location/Instance | Room 106 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Steam Heating | Inspected |
| F&T/Steam Drip Trap | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| MER Steam and Condensate Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Pumping System | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | DEFECTIVE MOTOR |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Steam Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Terminal Unit Thermostatic Trap | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Steam supplied by External Sources | Does not Exist |
| Unit Heater/Cabinet Heater | Inspected |
| Condition | 3 - Fair |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Basement Stairway C |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|--|---|
| HEATING | Inspected |
| Unit Heater/Cabinet Heater | |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| HEATING PLANT | Inspected |
| Replacement Quantity | 10,396 |
| Replacement Uom | MBH Net |
| Instance on Sub-Basement | Inspected |
| Burner Type | Dual Fuel (Gas/Oil) |
| Heating Plant Oil Number | 2 |
| Boiler Auxiliaries | Inspected |
| Instance on Sub-Basement | Inspected |
| Boiler Auxiliary Piping | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | DEFECTIVE BLOWDOWN PIPING |
| Deficiency Location/Instance | Boiler Room / Boiler #2 (isolation Valve) |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Boiler Emergency Stop Switch | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler Feedwater System | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler Feedwater Treatment(Automatic) | |
| Instance on Sub-Basement | Inspected |
| Condition | 3 - Fair |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Boiler Room (controls) |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Boiler Flue Exhaust | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler Make-up Water Backflow Preventer | |
| Instance on Sub-Basement | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|--|----------------------------|
| HEATING PLANT | Inspected |
| Boiler Auxiliaries | |
| Boiler Make-up Water Backflow Preventer | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler Room Steam And Condensate Piping | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler Safety Valve | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler System | Inspected |
| Instance on Sub-Basement | Inspected |
| Coal-fired Boiler | |
| Instance on Sub-Basement | Does not Exist |
| Hot Water Boiler | |
| Instance on Sub-Basement | Does not Exist |
| Modular Boiler | |
| Instance on Sub-Basement | Does not Exist |
| Steam Boiler | |
| Instance on Sub-Basement | Inspected |
| Instance | Boiler Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 5,198 |
| Instance Quantity Uom | MBH Net |
| Instance Manufacturer | A. L. Eastmond & Sons Inc. |
| Equipment | 8951-01 |
| Capacity/Size Quantity | 5,198 |
| Capacity/Size UOM | MBH Net |
| Source of Capacity/Size | Documented |
| Installation Year | 2001 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Boiler Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 5,198 |
| Instance Quantity Uom | MBH Net |
| Instance Manufacturer | A. L. Eastmond & Sons Inc. |
| Equipment | 8951-02 |
| Capacity/Size Quantity | 5,198 |
| Capacity/Size UOM | MBH Net |
| Source of Capacity/Size | Documented |
| Installation Year | 2001 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fuel System | Inspected |
| Instance on Sub-Basement | Inspected |
| Boiler Fresh Air Louver/Damper | |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Mechanical Inspection

K158

| Question | Response |
|--|---------------------------------|
| HEATING PLANT | |
| Fuel System | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Burner/Burner Control Panel | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fuel Oil Storage/Supply System | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | FUEL OIL LEVEL GAUGE: DEFECTIVE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo | No photo recorded |
| Violations | No violations recorded. |
| Gas Trains And Vent At The Boiler | |
| Instance on Sub-Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Enclosed IDF Room | |
| | Does not Exist |
| KITCHEN | |
| | Inspected |
| Instance on Basement | Inspected |
| CO Detector | |
| Instance on Basement | Not Required |
| Gas System | |
| Instance on Basement | Does not Exist |
| Grease Trap | |
| Instance on Basement | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Hood | |
| Instance on Basement | Does not Exist |
| Hood Exhaust Ductwork | |
| Instance on Basement | Does not Exist |
| Hood Exhaust Fan | |
| Instance on Basement | Does not Exist |
| Hood Fire Suppression System | |
| Instance on Basement | Does not Exist |
| Hot Water Temperature Booster | |
| Instance on Basement | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Kitchen Sink | |
| Instance on Basement | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Mechanical Inspection

K158

| Question | Response |
|---|--------------------------|
| KITCHEN | Inspected |
| Kitchen Sink | |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| MDF Room | Inspected |
| Instance on Room 402B | Inspected |
| Dedicated A/C Equipment | Inspected |
| Instance on Room 402B | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| SCIENCE DEMO ROOM | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | Inspected |
| Dry Sprinkler Alarm Valve Assembly | Does not Exist |
| Wet Sprinkler Alarm Valve Assembly | Does not Exist |
| Fire Booster Pump Assembly | Does not Exist |
| Roof Tank | Does not Exist |
| Siamese Connection | Does not Exist |
| Sprinkler Head | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Sprinkler Piping | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Standpipe System | Does not Exist |
| Water Gong | Does not Exist |
| SWIMMING POOL | Does not Exist |
| VENTILATION | Inspected |
| Exhaust Fan | Inspected |
| Approximate Total # of Fans | 1-25 |
| Condition | 3 - Fair |
| Deficiency | DEFECTIVE MOTOR |
| Deficiency Location/Instance | Main Roof |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Heating And Ventilating Unit | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Metal Ductwork | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Supply Fan | Does not Exist |
| Unit Ventilator | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K158

| Question | Response |
|------------------------------|-------------------------|
| VENTILATION | |
| Unit Ventilator | |
| Condition | 1 - Good |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Gymnasium |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |