

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Asset: P.S. 190 - BROOKLYN, 590 SHEFFIELD AVENUE, New York, 11207

Inspection Id	Inspection Type	Time In	Last Edited
EE : K190	Electrical	2019-01-25 8:40 AM	2019-02-12 12:37 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Exit/Emergency Lights, Exit Light (Battery Pack)
	Years: 2017
	Systems: Telephone System
	Years: 2016
	Systems: Local Sound System, Auditorium (Projection System)
	Years: 2014
	Systems: Science Lab - Room 402, Science Prep Room 418
	Years: 2011
	Systems: Intercom System (Elevator)
	Years: 2010
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1994, 2011
	Systems: All Other Electrical Systems and Components
	Years: 1994

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Meter Room C13 (Inside Mechanical Room C14)	Irwin Bonadie	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 2nd Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	
	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
	Inspected
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected
Instance on 1st Floor	Inspected
Lighting	
	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
GYMNASIUM	
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Inspected	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 403	Inspected
Lighting	Inspected
Instance on Room 403	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 403	Inspected
Pendant Mounted	Does not Exist
Instance on Room 403	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 403	Does not Exist
Recessed Mounted	Inspected
Instance on Room 403	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 403	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 403	Does not Exist
Lighting Fixture - LED	
Instance on Room 403	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 403	Does not Exist
Projection System	Does not Exist
Instance on Room 403	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting	Inspected
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - North, 1st Floor - South	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Local Sound System	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Projection System	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
Theater Lighting System	
Instance on 1st Floor - North, 1st Floor - South	Does not Exist
SCIENCE DEMO ROOM	
Instance on Room 507	Inspected
Power Panel	No
Alternative use	Yes
Lighting	
Instance on Room 507	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 507	Inspected
Pendant Mounted	
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 507	Does not Exist
Recessed Mounted	
Instance on Room 507	Does not Exist
Lighting Fixture - HID	
Instance on Room 507	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 507	Does not Exist
Lighting Fixture - LED	
Instance on Room 507	Does not Exist
Projection System	
Instance on Room 507	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 507	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	Inspected
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 507	Inspected
Instructor Unit	
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 507	Does not Exist
SCIENCE LAB	
Instance on Room 402	Inspected
Power Panel Alternative use	Yes No
Lighting	Inspected
Instance on Room 402	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 402	Inspected
Pendant Mounted	Inspected
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 402	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 402	Does not Exist
Lighting Fixture - LED	
Instance on Room 402	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 402	Does not Exist
Emergency Shut-Off Power	Inspected
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 402	Inspected
Instructor Unit	
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
SCIENCE LAB	
Power Supply	Inspected
Student Unit	
Instance on Room 402	Does not Exist
Meter Demonstration Unit	
Instance on Room 402	Does not Exist
Projection System	Does not Exist
Instance on Room 402	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 418	Inspected
Power Panel Alternative use	No No
Instance on Room 509	Inspected
Power Panel Alternative use	No Yes
Lighting	Inspected
Instance on Room 509	Inspected
Instance on Room 418	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 509	Inspected
Instance on Room 418	Inspected
Pendant Mounted	
Instance on Room 509	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Recessed Mounted	
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - HID	
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - LED	
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
SCIENCE PREP ROOM	Inspected
Power Supply	Does not Exist
Instance on Room 509	Does not Exist
Instance on Room 418	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	ATS#1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	ATS#2 - Fire Alarm
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	ATS#3
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	188
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	150
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	520
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Penthouse
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
FIRE ALARM SYSTEM	
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Fire Alarm Panel
Model	XP Series
Capacity/Size Quantity	32
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K190

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Condition	3 - Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Corridor by Room 508, Outside Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor 250
Installation Year	1994
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Rooms (418, 509, 330), Corridor by Room 403
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Does not Exist
Intrusion Alarm System	
	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	17
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room C13 (Inside Mechanical Room C14)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Service Disconnect
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Emergency Generator Room C20
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	EDP (Emergency Generator Switchboard)
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Closet - Room C06

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K190

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDP
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist