

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

Asset: I.S. 223 - BROOKLYN, 4200 16 AVENUE, New York, 11204

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : K223 | Electrical | 2019-02-25 8:29 AM | 2019-04-18 4:43 PM |

Asset Data

| Question | Answer |
|---|---|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Public Address System (Amplifier), Auditorium (Local Sound System), Science Lab Room 411 (Except Fluorescent Lighting) |
| | Years: 2018 |
| | Systems: Interior Lighting |
| | Years: 2014 |
| | Systems: Auditorium (Projection System), IPDVS/CCTV System |
| | Years: 2011 |
| | Systems: LAN, Telephone System |
| | Years: 2010 |
| | Systems: Fire Alarm System (Electronic Sub-Panel, Elevator Recall, Strobe, Remote Annunciator Panel, Sprinkler Flow/Air Pressure Switch), Intercom System (Elevator), Public Address System (Tuner), Transformer, Partial Switchboard |
| | Years: 2009 |
| | Systems: Emergency Light/Exit Light Panel, Partial Fused Disconnect Switch Type Panel Board, Local Sound System (Gymnasiums, Cafeteria) |
| | Years: 2001 |
| | Systems: Intrusion Alarm System |
| | Years: 1998 |
| | Systems: Security Lights |
| | Years: 1996, 2001, 2015 |
| | Systems: Partial Molded Case Circuit Breaker Panel Board |
| | Years: 1987, 1996, 2000, 2006, 2016 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---|-----------------------|-----------------------------------|---|--------------------|-----------------|-------------|------------|
| No | Emergency Lighting - Fixture Lamp Not Operational | N/A | EMERGENCY LIGHTING Battery Pack | Auditorium, 2nd Floor Corridor - By Room 204, 4th Floor Corridor - By (Gymnasium, Exit 4), Elevator Lobby (1st and 4th Floors), Boiler Room, Basement (By Exit 8, 10) | Joseph Cordero | Custodian | Sent to DSF | |
| No | Public Address System - Speakers Not Operational | N/A | PUBLIC ADDRESS SYSTEM | Auditorium, Principal's Office, Projector Room | Josean Crespo | Fireman | Sent to DSF | |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

Inspection

| Question | Response |
|---|-------------------------------------|
| Electrical | |
| AUDITORIUM | Inspected |
| Instance on 1st Floor | Inspected |
| House Lighting | Inspected |
| Does a Chandelier exist? | No |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor | Inspected |
| Installation Year | 2018 |
| Source of Installation | Custodial Staff |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Projection System | Inspected |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Instance on 1st Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | Inspected |
| Instance on 1st Floor | Inspected |
| Dimming System | |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting | |
| Instance on 1st Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|--|----------------------------------|
| AUDITORIUM | |
| Theater Lighting System | |
| Theater Lighting | |
| Deficiency Quantity | 27 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| CAFETERIA | |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| Local Sound System | |
| Instance on Basement | Inspected |
| Installation Year | 2001 |
| Source of Installation | Inspector Estimate |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Basement | Does not Exist |
| Theater Lighting System | |
| Instance on Basement | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|--|------------------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Surface Mounted | |
| Condition | Inspected |
| Deficiency | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Condition | Does not Exist |
| Lighting Fixture - HID | |
| Condition | Does not Exist |
| Lighting Fixture - Incandescent | |
| Condition | Does not Exist |
| Lighting Fixture - LED | |
| Condition | Does not Exist |
| COMPUTER LAB | |
| Instance on Room 105 | Inspected |
| Power Panel | Inspected |
| Instance on Room 405 | No |
| Instance on Room 405 | Inspected |
| Power Panel | Yes |
| Lighting | |
| Instance on Room 405 | Inspected |
| Instance on Room 105 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 405 | Inspected |
| Instance on Room 105 | Inspected |
| Pendant Mounted | |
| Instance on Room 405 | Inspected |
| Condition | Inspected |
| Deficiency | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 105 | Inspected |
| Condition | Inspected |
| Deficiency | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Does not Exist |
| Recessed Mounted | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|--|------------------------------------|
| COMPUTER LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on Room 105 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Does not Exist |
| Raceway With Receptacles | |
| Instance on Room 405 | Does not Exist |
| Instance on Room 105 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | |
| Instance on 3rd Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Lighting | Inspected |
| Instance on 4th Floor | Inspected |
| Instance on 3rd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 4th Floor | Inspected |
| Instance on 3rd Floor | Inspected |
| Pendant Mounted | |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---------------------------------------|---------------------------|
| GYMNASIUM | |
| Lighting | |
| Lighting Fixture - LED | |
| Pendant Mounted | Inspected |
| Instance on 3rd Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 3rd Floor | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 4th Floor | Inspected |
| Installation Year | 2001 |
| Source of Installation | Inspector Estimate |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on 3rd Floor | Inspected |
| Installation Year | 2001 |
| Source of Installation | Inspector Estimate |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Scoreboard | Inspected |
| Instance on 4th Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on 3rd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| KITCHEN | |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|--|---------------------------|
| KITCHEN | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | Inspected |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| LIBRARY | |
| Instance on Room 307 | Inspected |
| Instance on Room 307 | Inspected |
| Lighting | |
| Instance on Room 307 | Inspected |
| Instance on Room 307 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 307 | Inspected |
| Pendant Mounted | |
| Instance on Room 307 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 307 | Does not Exist |
| Recessed Mounted | |
| Instance on Room 307 | Does not Exist |
| Instance on Room 307 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 307 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 307 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 307 | Does not Exist |
| Raceway With Receptacles | |
| Instance on Room 307 | Inspected |
| Instance on Room 307 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Room 307 | Does not Exist |
| Instance on Room 307 | Does not Exist |
| LOCKER ROOM | |
| Instance on 4th Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Alternative use | Yes |
| Lighting | |
| Instance on 4th Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 4th Floor | Inspected |
| Pendant Mounted | |
| Instance on 4th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Surface Mounted | |
| Instance on 4th Floor | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|--|---------------------------|
| LOCKER ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | Inspected |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 4th Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 4th Floor | Does not Exist |
| MULTIPURPOSE ROOM | |
| | Does not Exist |
| SCIENCE DEMO ROOM | |
| | Inspected |
| Instance on Room 213 | Inspected |
| Power Panel Alternative use | No Yes |
| Instance on Room 313 | Inspected |
| Power Panel Alternative use | No No |
| Lighting | |
| | Inspected |
| Instance on Room 313 | Inspected |
| Instance on Room 213 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 313 | Inspected |
| Instance on Room 213 | Inspected |
| Pendant Mounted | |
| Instance on Room 313 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 213 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Recessed Mounted | |
| | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Lighting Fixture - LED | |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|---------------------------------------|---------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | Inspected |
| Lighting Fixture - LED | |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Emergency Gas Shut-Off Valve | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Emergency Shut-Off Power | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| Power Supply | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Instance on Room 213 | Does not Exist |
| SCIENCE LAB | Inspected |
| Instance on Room 128 | Inspected |
| Power Panel Alternative use | No No |
| Instance on Room 421 | Inspected |
| Power Panel Alternative use | No Yes |
| Instance on Rooms 411 | Inspected |
| Power Panel Alternative use | No No |
| Instance on Rooms 425, 427, 429 | Inspected |
| Power Panel Alternative use | No No |
| Lighting | Inspected |
| Instance on Rooms 425, 427, 429 | Inspected |
| Instance on Rooms 411 | Inspected |
| Instance on Room 421 | Inspected |
| Instance on Room 128 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 425, 427, 429 | Inspected |
| Instance on Rooms 411 | Inspected |
| Instance on Room 421 | Inspected |
| Instance on Room 128 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Rooms 425, 427, 429 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 411 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 421 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|--|---------------------------|
| SCIENCE LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | Inspected |
| Instance on Room 128 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Inspected |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Rooms 411 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 128 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Emergency Gas Shut-Off Valve | Inspected |
| Instance on Rooms 425, 427, 429 | Inspected |
| Condition | 3 - Fair |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|-------------------------------------|--------------------------|
| SCIENCE LAB | |
| Emergency Gas Shut-Off Valve | |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 128 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Power Supply | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Inspected |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Inspected |
| Instructor Unit | |
| Instance on Rooms 411 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 128 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Student Unit | |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| Meter Demonstration Unit | |
| Instance on Rooms 411 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 128 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Rooms 425, 427, 429 | Does not Exist |
| Instance on Rooms 411 | Does not Exist |
| Instance on Room 421 | Does not Exist |
| Instance on Room 128 | Does not Exist |
| SCIENCE PREP ROOM | |
| Instance on Room 128A | Inspected |
| Power Panel | Yes |
| Alternative use | No |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|--|---------------------------|
| SCIENCE PREP ROOM | |
| Instance on Room 211 | Inspected |
| Power Panel | No |
| Alternative use | Yes |
| Instance on Room 413 | Inspected |
| Power Panel | Yes |
| Alternative use | No |
| Lighting | Inspected |
| Instance on Room 413 | Inspected |
| Instance on Room 211 | Inspected |
| Instance on Room 128A | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 413 | Inspected |
| Instance on Room 211 | Inspected |
| Instance on Room 128A | Inspected |
| Pendant Mounted | |
| Instance on Room 413 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 211 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 128A | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| Recessed Mounted | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Inspected |
| Condition | 3 - Fair |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|---------------------------|
| SCIENCE PREP ROOM | |
| Emergency Gas Shut-Off Valve | Does not Exist |
| Deficiency | No deficiencies recorded |
| Instance on Room 128A | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | Does not Exist |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Power Supply | Does not Exist |
| Instance on Room 413 | Does not Exist |
| Instance on Room 211 | Does not Exist |
| Instance on Room 128A | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 121,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|---|
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium, 2nd Floor Corridor - By Room 204, 4th Floor Corridor - By (Gymnasium, Exit 4), Elevator Lobby (1st and 4th Floors), Boiler Room, Basement (By Exit 8, 10) |
| Deficiency Quantity | 12 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Does not Exist |
| CITY FIRE ALARM SYSTEM | Inspected |
| Condition | 5 - Poor |
| Deficiency | NOT OPERATIONAL |
| Deficiency Location/Instance | 2nd Floor Corridor - By Room 203 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 121,000 |
| Replacement Uom | S.F. |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|--|---------------------------|
| FIRE ALARM SYSTEM | |
| Bell/Horn | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not Exist |
| Duct Smoke Detector | Does not Exist |
| Area Smoke Detector | Does not Exist |
| CO Detector | Does not Exist |
| Heat Detector | Does not Exist |
| Elevator Recall | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Does not Exist |
| Fused Cutout Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Does not Exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ACME |
| Equipment | Fire Alarm Control Board |
| Capacity/Size Quantity | 7 |
| Capacity/Size UOM | Circuits |
| Source of Capacity/Size | Diagram |
| Installation Year | 1966 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 121,000 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|--|------------------------------------|
| FIRE ALARM SYSTEM | |
| Sub-Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Edwards System Technology |
| Equipment | Smoke Control Panel |
| Model | EST 2 |
| Capacity/Size Quantity | 6 |
| Capacity/Size UOM | Zones |
| Source of Capacity/Size | Diagram |
| Installation Year | 2009 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ACME |
| Equipment | Register Control Board |
| Capacity/Size Quantity | 2 |
| Capacity/Size UOM | Circuits |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1966 |
| Source of Installation | Documented |
| Deficiency | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 121,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Boiler Room |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|--|------------------------------------|
| FIRE ALARM SYSTEM | |
| Sub-Panel | |
| Fire Alarm Control Panel (Standard) | |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ACME |
| Equipment | Sprinkler Alarm Control Board |
| Capacity/Size Quantity | 2 |
| Capacity/Size UOM | Circuits |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1966 |
| Source of Installation | Documented |
| Deficiency | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 121,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Remote Annunciator | Inspected |
| Display Monitor | Does not Exist |
| Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Does not Exist |
| Punch Register | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|---|
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not Exist |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Fan Rooms (Inside Boiler Room, Basement - South MER) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fused Knife Switch Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Corridors By Rooms (127, 207, 217, 227, 307, 317, 327, 407, 417, 427) |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fused Toggle Switch Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|---|
| PANEL BOARD | |
| Fused Toggle Switch Type | Inspected |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | CIRCUIT BREAKER NOT OPERATIONAL |
| Deficiency Location/Instance | 2nd Floor Corridor by Exit 6 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE CIRCUIT BREAKER |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | Room 218A, Fan Room (Basement - South MER) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | 4th Floor Gymnasium, Room 218, Boiler Room |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | 1st Floor Corridor - By Room 104 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Auditorium, Kitchen, Custodian's Office, Fan Room (Basement - South MER), Corridor (1st, 2nd, 3rd and 4th Floors) |
| Deficiency Quantity | 19 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|--|
| PANEL BOARD | Inspected |
| Molded Case Circuit Breaker Type | Inspected |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 121,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | N/A |
| Installation Year | 1980 |
| Source of Installation | Inspector Estimate |
| Deficiency | SPEAKER NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium, Principal's Office, Projector Room |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Classrooms and Corridors |
| Deficiency Quantity | 42 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | General Office |
| Deficiency Quantity | 121,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Replacement Quantity | 121,000 |
| Replacement Uom | S.F. |
| Installation Year | 2011 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|-------------------------------|--|
| SECURITY | |
| IPDVS/CCTV System | Inspected |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | Inspected |
| Replacement Quantity | 121,000 |
| Replacement Uom | S.F. |
| Central Control Panel | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 50P |
| Installation Year | 1998 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | Does not Exist |
| Lighting - Security | Inspected |
| Replacement Quantity | 25 |
| Replacement Uom | EACH |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Location/Instance | On wall facing Courtyard, 42nd Street, 16th Avenue |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Empire Switchboard |
| Equipment | Service Switch |
| Capacity/Size Quantity | 2,000 |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K223

| Question | Response |
|-------------------------------------|--------------------------------------|
| SERVICE SWITCH | |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1965 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SWITCHBOARD | |
| Number of Spares | Inspected 1 |
| Air Circuit Breaker Type | Does not Exist |
| Fused Disconnect Switch Type | Inspected |
| Instance | Boiler Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | All City Switchboard |
| Equipment | DP (Emergency Generator Switchboard) |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Switchboard Mains Size |
| Installation Year | 2009 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Empire Switchboard |
| Equipment | N/A |
| Capacity/Size Quantity | 2,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 5 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1965 |
| Source of Installation | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K223

| Question | Response |
|---|---------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fused Knife Switch Type | |
| | Does not Exist |
| Molded Case Circuit Breaker Type | |
| | Does not Exist |
| TELEPHONE SYSTEM | |
| | Inspected |
| PBX/Intercom | |
| | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | |
| | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | |
| | Inspected |
| Instance | Elevator Machine Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Hammond |
| Equipment | N/A |
| Capacity/Size Quantity | 63 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2009 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| TV SYSTEM | |
| | Inspected |
| Cable System Exist? | Yes |
| Operational? | Yes |
| Main Equipment Rack | |
| | Does not Exist |