

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Asset: I.S. 318 - BROOKLYN, 101 WALTON STREET, New York, 11206

Inspection Id	Inspection Type	Time In	Last Edited
EE : K318	Electrical	2018-11-09 8:37 AM	2019-01-23 12:10 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Interior Lighting, Exit Lights (Battery Pack), Partial Emergency Lighting (Non-Battery Pack)
	Years: 2017
	Systems: Fire Alarm System, Public Address System, Local Sound System (Gymnasium, Cafeteria)
	Years: 2015
	Systems: IPDVS/CCTV System
	Years: 2013
	Systems: Security Lights
	Years: 2012
	Systems: Auditorium (Projection System, Local Sound System)
	Years: 2010
	Systems: Emergency Light/Exit Light Panel, Partial Fused Disconnect Switch Type Panel Board
	Years: 2000
	Systems: Intrusion Alarm System
	Years: 1999
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1987, 2003

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on Basement	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on Basement	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Cart
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Deficiency Quantity	104
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	
	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	1 - Good

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Surface Mounted	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 121	Inspected
Power Panel	No
Instance on Room 323	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 323	Inspected
Instance on Room 121	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 323	Inspected
Instance on Room 121	Inspected
Pendant Mounted	Inspected
Instance on Room 323	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 121	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 121	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 121	Does not Exist
Lighting Fixture - HID	
Instance on Room 323	Does not Exist
Instance on Room 121	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 323	Does not Exist
Instance on Room 121	Does not Exist
Lighting Fixture - LED	
Instance on Room 323	Does not Exist
Instance on Room 121	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 323	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
COMPUTER LAB	
Raceway With Receptacles	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 121	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not Exist
Scoreboard	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Inspected
Instance on Room 230	Inspected
Lighting	Inspected
Instance on Room 230	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 230	Inspected
Pendant Mounted	Inspected
Instance on Room 230	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 230	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 230	Does not Exist
Lighting Fixture - HID	
Instance on Room 230	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 230	Does not Exist
Lighting Fixture - LED	
Instance on Room 230	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 230	Does not Exist
Projection System	Does not Exist
Instance on Room 230	Does not Exist
LOCKER ROOM	Inspected
Instance on Basement - Boys, Basement - Girls	Inaccessible
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 222	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 222	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 222	Inspected
Pendant Mounted	Inspected
Instance on Room 222	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 222	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 222	Does not Exist
Lighting Fixture - HID	
Instance on Room 222	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 222	Does not Exist
Lighting Fixture - LED	
Instance on Room 222	Does not Exist
Projection System	Does not Exist
Instance on Room 222	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 222	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 222	Does not Exist
Power Supply	Does not Exist
Instance on Room 222	Does not Exist
SCIENCE LAB	Inspected
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Pendant Mounted	Inspected
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Emergency Gas Shut-Off Valve	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	Inspected
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
Projection System	Does not Exist
Instance on Rooms 200, 201, 202, 203, 204, 205, 206, 215	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 212	Inspected
Power Panel Alternative use	Yes No
Lighting	Inspected
Instance on Room 212	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 212	Inspected
Pendant Mounted	Inspected
Instance on Room 212	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 212	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 212	Does not Exist
Lighting Fixture - HID	
Instance on Room 212	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 212	Does not Exist
Lighting Fixture - LED	
Instance on Room 212	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 212	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Boiler Room, By Room B10, Basement by Exit G

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Non Battery Pack	
Condition	Inspected
Deficiency	2 - Between Good and Fair
EXIT LIGHT	
Condition	Inspected
Battery Pack	
Condition	Inspected
Deficiency	1 - Good
Non Battery Pack	
Condition	Does not Exist
EXIT/EMERGENCY LIGHT	
Condition	Does not Exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3 - Fair
FIRE ALARM SYSTEM	
Replacement Quantity	Inspected
Replacement Uom	151,000
Bell/Horn	
Condition	S.F.
Deficiency	Inspected
Strobe	
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	
Condition	Inspected
Deficiency	1 - Good
Fan Shutdown Control	
Condition	Inspected
Deficiency	1 - Good
Duct Smoke Detector	
Condition	Inspected
Deficiency	1 - Good
Area Smoke Detector	
Condition	Inspected
Deficiency	1 - Good
CO Detector	
Condition	Inspected
Deficiency	1 - Good
Heat Detector	
Condition	Inspected
Deficiency	1 - Good
Elevator Recall	
Condition	Does not Exist
Magnetic Door Holder/Contactor	
Condition	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	Fire Alarm Control Panel
Model	E3 Series
Capacity/Size Quantity	32
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium - Mechanical Room, Mechanical Rooms B2, B17, Boiler Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms 220, 249, Science Room 212, Cafeteria, Kitchen
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Electrical Room, Computer Lab - Room 323

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K318

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms 201, 202, 203, 204, 205, 206, 215,, Corridors (Basement, 1st, 2nd, and 3rd Floor), Kitchen, Gymnasium, Auditorium, Boiler Room
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	By Rooms 324, 310, 249, 241
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
SECURITY	
IPDVS/CCTV System	
Replacement Quantity	151,000
Replacement Uom	S.F.
Installation Year	2013
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1999
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not Exist
Lighting - Security	
	Inspected
Replacement Quantity	37
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metropolitan
Equipment	4000A 4W 25V Service SW 3500A FU
Capacity/Size Quantity	3,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
SERVICE SWITCH	
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metropolitan Electric
Equipment	Main SW BD
Capacity/Size Quantity	3,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	5
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K318

Question	Response
TV SYSTEM	
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist