

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K335**

**Asset:** P.S. 335 - BROOKLYN, 130 ROCHESTER AVENUE, New York, 11213

Inspection Id	Inspection Type	Time In	Last Edited
EE : K335	Electrical	2017-10-20 8:28 AM	2017-10-30 11:41 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Computer Lab - Room 235 (Raceway With Receptacles)
	Years: 2015
	Systems: Interior Fluorescent Lighting (Except Library, Science Lab - Room 302), LED Lighting (Gymnasium, Cafeteria)
	Years: 2014
	Systems: Intrusion Alarm System (Panic Switch)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: Science Lab - Room 302
	Years: 2010
	Systems: Library, LAN, Telephone System
	Years: 2009
	Systems: Public Address System, Local Sound System
	Years: 2006
	Systems: Intrusion Alarm System
	Years: 1995
	Systems: Emergency Light/Exit Light Panel, Partial Fused Disconnect Switch Type Panel Board
	Years: 1992
	Systems: Security Lights
	Years: 1990, 2001
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1985, 2000, 2014

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on Ground Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Does not Exist
<b>Local Sound System</b>	
Instance on Ground Floor	Inspected
Installation Year	2006
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Ground Floor	Does not Exist
<b>Theater Lighting System</b>	
Instance on Ground Floor	Inspected
<b>Dimming System</b>	
Instance on Ground Floor	Does not Exist
<b>Theater Lighting</b>	
Instance on Ground Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	
	Inspected
Instance on Ground Floor - Staff	Inspected
Instance on Ground Floor - Students	Inspected
<b>Lighting</b>	Inspected
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Inspected
<b>Pendant Mounted</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Surface Mounted</b>	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Ground Floor - Staff	Does not Exist
<b>Recessed Mounted</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Does not Exist
<b>Pendant Mounted</b>	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
<b>Surface Mounted</b>	Does not Exist
Instance on Ground Floor - Students	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Ground Floor - Students	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on Ground Floor - Students	Inspected
Installation Year	2006
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - Staff	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Inspected
Instance on Room 235	Inspected
Power Panel	Yes
<b>Lighting</b>	Inspected
Instance on Room 235	Inspected
<b>Lighting Fixture - Fluorescent</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 235	Inspected
<b>Pendant Mounted</b>	
Instance on Room 235	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 235	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 235	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 235	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 235	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 235	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 235	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on Ground Floor	Inspected
<b>Lighting</b>	
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Ground Floor	Does not Exist
<b>Recessed Mounted</b>	
Instance on Ground Floor	Does not Exist
<b>Local Sound System</b>	
Instance on Ground Floor	Inspected
Installation Year	2006
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>GYMNASIUM</b>	
<b>Projection System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>KITCHEN</b>	
<b>Lighting</b>	Inspected
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Does not Exist
<b>LIBRARY</b>	
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Raceway With Receptacles</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 302	Inspected
Power Panel Alternative use	No Yes
<b>Lighting</b>	Inspected
Instance on Room 302	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 302	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 302	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 302	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 302	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 302	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 302	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 302	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 302	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
Instance on Room 302	Inspected
<b>Instructor Unit</b>	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 302	Does not Exist
<b>Meter Demonstration Unit</b>	
Instance on Room 302	Does not Exist
<b>Projection System</b>	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist



**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor at Staircase A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Cafeteria
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35252600M
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (102, 120, 133)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Room 235
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>EXIT LIGHT</b>	Inspected
<b>Non Battery Pack</b>	
Violations	No violations recorded.
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Does not Exist
<b>Manual Pull Station</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Does not Exist
<b>Duct Smoke Detector</b>	Does not Exist
<b>Area Smoke Detector</b>	Does not Exist
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Does not Exist
<b>Elevator Recall</b>	Does not Exist
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Does not Exist
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm Control Board
Capacity/Size Quantity	6
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	107,000

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Standard)</b>	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Does not Exist
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Sprinkler Alarm Control Board
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	107,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
Does not Exist	
<b>LAN</b>	
Inspected	
<b>Local Distribution Frame (I/LDF)</b>	
Condition	2 - Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, 1st Floor Fan Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Room 235, Corridor by Room 6, Auditorium
Deficiency Quantity	3

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor by Rooms (6, 28, 103, 124, 147, 203, 224, 247, 303, 324), Cafeteria, Auditorium, Boiler Room
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2006
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	107,000

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

Question	Response
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
Replacement Quantity	107,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1995
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	
Condition	Does not Exist
<b>Lighting - Security</b>	
Replacement Quantity	19
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Main Switch
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	107,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Main SER SW
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	107,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SWITCHBOARD</b>	Inspected
Number of Spares	0
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Main SW BD
Capacity/Size Quantity	1,600

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K335

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1968
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	107,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	
	Inspected
<b>PBX/Intercom</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
	Does not Exist
<b>TV SYSTEM</b>	
	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not Exist