

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Asset: **PARKSIDE COMMUNITY COMPLEX - BROOKLYN, 713 CATON AVENUE, New York, 11218**

Inspection Id	Inspection Type	Time In	Last Edited
ME : K437	Mechanical	2021-01-26 8:27 AM	2021-02-12 5:16 PM

Asset Data

Question	Answer
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Fire Booster Pump Assembly Room C05
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Science Labs 430, 434
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Inspected
<b>Absorption Chiller</b>	Does not Exist
<b>Air Cooled Chiller</b>	Does not Exist
<b>Air Cooled Condenser</b>	Does not Exist
<b>Chilled Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	PUMP: DEFECTIVE
Deficiency Location/Instance	Boiler Room / Defective Controls
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Backflow Preventer</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room Above Chilled Water Pumps 3/4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Backflow Preventer</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Central Station Air Handler</b>	
Instance	Inspected
Instance Condition	Upper Roof
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Seasons.4
Capacity/Size Quantity	RTU-CR1
Capacity/Size UOM	19,195
Source of Capacity/Size	CFM
Installation Year	Documented
Source of Installation	2015
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Upper Roof
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Seasons.4
Capacity/Size Quantity	RTU-CR2
Capacity/Size UOM	22,085
Source of Capacity/Size	CFM
Installation Year	Documented
Source of Installation	2015
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Upper Roof
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Seasons.4
Capacity/Size Quantity	RTU-K/C
Capacity/Size UOM	12,000
Source of Capacity/Size	CFM
Installation Year	Documented
Source of Installation	2015
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Lower Roof
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Seasons.4
Capacity/Size Quantity	RTU-G
Capacity/Size UOM	14,000

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Central Station Air Handler</b>	
Capacity/Size UOM	CFM
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Lower Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Seasons.4
Equipment	RTU-GA
Capacity/Size Quantity	11,150
Capacity/Size UOM	CFM
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fan Coil Unit</b>	Does not Exist
<b>Packaged Air Cooled Chiller</b>	Inspected
Instance	Upper Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-2
Capacity/Size Quantity	128
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Upper Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-1A
Capacity/Size Quantity	177
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Upper Roof
Instance Condition	1 - Good
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Packaged Air Cooled Chiller</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-1B
Capacity/Size Quantity	177
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Water Cooled Chiller</b>	Does not Exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not Exist
<b>Cooling Coil in Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Cooling Tower</b>	Does not Exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not Exist
<b>Packaged / Rooftop Unit</b>	Does not Exist
<b>Packaged Terminal A/C</b>	Does not Exist
<b>Refrigerant Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not Exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not Exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Pneumatic System</b>	Does not Exist
<b>Hybrid System</b>	Does not Exist
<b>Electric System</b>	Does not Exist
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiter</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>CONVEYING</b>	
<b>Elevator</b>	Inspected
Are all the existing elevators operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not Exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Inspected
Are all the existing non-auditorium vertical handicap lifts operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non-auditorium Handicap Lift - Stair</b>	Does not Exist
<b>Ash Hoist</b>	Does not Exist
<b>Sidewalk Elevator</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not Exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Inspected
Instance	Room C01
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Liquitrol
Equipment	PP-C Domestic Water Pump
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size2 Quantity	10
Capacity/Size2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Hydraulic/Pneumatic Booster System</b>	Does not Exist
<b>Water Service</b>	Inspected
Instance	Room C01
Instance Condition	1 - Good
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3

**NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Domestic Water Heat Exchanger</b>	Does not Exist
<b>Electric Domestic Water Heater</b>	Does not Exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lochinvar
Equipment	N/A
Capacity/Size Quantity	500
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	0
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not Exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good

**NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>FIXTURES</b>	
<b>Staff And Other</b>	
<b>Lavatory/Sink</b>	
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Kitchen / Hand Wash Sink
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Toilet</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	
	Does not Exist
<b>Student</b>	
	Inspected
<b>Drinking Fountain</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	
	Does not Exist
<b>Sink And Fountain Combo Unit</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	
	Does not Exist
<b>GAS SERVICE</b>	
	Inspected
<b>Gas Distribution Piping</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	
	Does not Exist
<b>Gas Meter Room Vent</b>	
	Does not Exist
<b>Gas Pressure Booster</b>	
	Does not Exist
<b>CO/Gas Leak Detection</b>	
	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not Exist
<b>Hydronic Heating</b>	Inspected
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	PIPING: DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Backflow Preventer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hot Water Heat Exchanger</b>	Does not Exist
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Does not Exist
<b>Steam supplied by External Sources</b>	Does not Exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	8,346
Replacement Uom	MBH Net
Instance on 5th Floor	Inspected
Burner Type	Gas
Heating Plant Oil Number	N/A
<b>Boiler Auxiliaries</b>	Inspected
Instance on 5th Floor	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on 5th Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on 5th Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler Flue Exhaust</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler Make-up Water Backflow Preventer</b>	



**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler Safety Valve</b>	
Instance on 5th Floor	Does not Exist
<b>Boiler System</b>	
Instance on 5th Floor	Inspected
<b>Coal-fired Boiler</b>	
Instance on 5th Floor	Does not Exist
<b>Hot Water Boiler</b>	
Instance on 5th Floor	Does not Exist
<b>Modular Boiler</b>	
Instance on 5th Floor	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-05
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-01
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-02
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Modular Boiler</b>	
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-03
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-04
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,391
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	166715-06
Capacity/Size Quantity	2,000
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Steam Boiler</b>	
Instance on 5th Floor	Does not Exist
<b>Fuel System</b>	
Instance on 5th Floor	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on 5th Floor	Inspected
Condition	1 - Good

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>HEATING PLANT</b>	
<b>Fuel System</b>	
<b>Boiler Fresh Air Louver/Damper</b>	
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on 5th Floor	Does not Exist
<b>Fuel Oil Storage/Supply System</b>	
Instance on 5th Floor	Does not Exist
<b>Gas Trains And Vent At The Boiler</b>	
Instance on 5th Floor	Does not Exist
<b>Enclosed IDF Room</b>	Inspected
Instance on Rooms C28, 214, 414, 514	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Rooms C28, 214, 414, 514	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	Inspected
Instance on Basement	Inspected
<b>CO Detector</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas System</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>KITCHEN</b>	Inspected
<b>Kitchen Sink</b>	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	Inspected
Instance on Room 314	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Room 314	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Rooms 430, 434	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Inspected
Instance on Rooms 430, 434	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Instance on Rooms 430, 434	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Rooms 430, 434
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Emergency Shower</b>	Does not Exist
Instance on Rooms 430, 434	Does not Exist
<b>Eye Wash</b>	Inspected
Instance on Rooms 430, 434	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Does not Exist
Instance on Rooms 430, 434	Does not Exist
<b>Hood Exhaust Fan</b>	Does not Exist
Instance on Rooms 430, 434	Does not Exist
<b>Fixed Laboratory Hood</b>	Does not Exist
Instance on Rooms 430, 434	Does not Exist
<b>Laboratory Sink</b>	Inspected
Instance on Rooms 430, 434	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Does not Exist
Instance on Rooms 430, 434	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
Instance on Room 433	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Instance on Room 433	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shower</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Eye Wash</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fixed Laboratory Hood</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	Inspected
Instance on Room 433	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Does not Exist
Instance on Room 433	Does not Exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Booster Pump Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Roof Tank</b>	Does not Exist
<b>Siamese Connection</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K437

Question	Response
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Sprinkler Head</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Inspected
<b>Hose Valve Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Water Gong</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Approximate Total # of Fans	1-25
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not Exist
<b>Metal Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not Exist
<b>Unit Ventilator</b>	Does not Exist