

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

**Asset: PROSPECT HEIGHTS HS - K, 883 CLASSON AVENUE, New York, 11225**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K440	Electrical	2018-04-10 7:50 AM	2018-04-19 10:39 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Science Lab - Room 410 (Except Fluorescent Lighting)
	Years: 2017
	Systems: LED Lighting
	Years: 2016
	Systems: Exit Lights (Battery Pack), Telephone System
	Years: 2015
	Systems: 2nd Floor Gymnasium (Scoreboard)
	Years: 2014
	Systems: Science Lab - Rooms 216 (Projection System)
	Years: 2011
	Systems: IPDVS/CCTV System
	Years: 2010
	Systems: 3rd Floor Gymnasium (Scoreboard), Computer Lab (Raceway With Receptacles)
	Years: 2009
	Systems: Science Demo - Room 504 (Except Lighting), Science Lab - Rooms (216, 404, 603), Science Prep - Room 601, Security Lights, Most Recessed Fluorescent Lighting (Classroom)
	Years: 2007
	Systems: Auditorium (Local Sound System)
	Years: 2006
	Systems: Intrusion Alarm System
	Years: 2001
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1995, 2007, 2014
	Systems: All Other Electrical Systems and Components (Except Fire Alarm System Standard Sub-Panel)
	Years: 1995

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	No
Which rooms or areas have non-operational dedicated intercoms?	Rooms 212, 224, 312, 324, 412, 424, 512, 524

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Components Not Operational	One detector is missing	FIRE ALARM SYSTEM   Area Smoke Detector	Kitchen	Paul Mullins	Fireman	Sent to DSF	
No	Fire Alarm System - Not Connected to Central Station	N/A	FIRE ALARM SYSTEM   Fire Alarm Digital Communicator	Main Entrance Lobby	Paul Mullins	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

No	Intercom - Not Operational	NON OFFICIAL HOLDING ROOMS	Intercom System – Holding/Fire Rescue Area	Rooms 212, 224, 312, 324, 412, 424, 512, 524	Paul Mullins	Fireman	Sent to DSF
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	Corridor By Rooms 233, 307, 308, 434, 537, 520	Paul Mullins	Fireman	Sent to DSF
Yes	Intercom - Not Operational	N/A	INTERCOM SYSTEM   Elevator	Elevator - Device IDs: 3P907, 3P908	Paul Mullins	Fireman	Sent to DSF

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inaccessible
<b>CAFETERIA</b>	Inspected
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
<b>Lighting</b>	Inspected
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement - Students	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Staff	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Students	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Local Sound System</b>	
	Inspected
Instance on Basement - Students	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Staff	Does not Exist
<b>Projection System</b>	
	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Theater Lighting System</b>	
	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	
	Inspected
Does a Chandelier exist?	Yes
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room 332	Inspected
Power Panel	No
<b>Lighting</b>	Inspected
Instance on Room 332	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 332	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 332	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 332	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 332	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 332	Does not Exist
<b>Lighting Fixture - LED</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
Instance on Room 332	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 332	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 2nd Floor	Inspected
Instance on 3rd Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 3rd Floor	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 3rd Floor	Inspected
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 3rd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 3rd Floor	Inspected
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 3rd Floor	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	GYMNASIUM - 3rd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	GYMNASIUM - 3rd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>GYMNASIUM</b>	
<b>Projection System</b>	Does not Exist
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 3rd Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>KITCHEN</b>	
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>LIBRARY</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	No
Instance on 1st Floor - Girls	Inspected
Alternative use	No
Instance on 2nd Floor - Boys	Inspected
Alternative use	Yes
Instance on 4th Floor - Girls	Inspected
Alternative use	No
Instance on Room 251 - Girls	Inspected
Alternative use	No
Instance on Room 252 - Boys	Inspected
Alternative use	No
Instance on Room 351 - Boys	Inspected
Alternative use	Yes
Instance on Room 368 - Boys	Inspected
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 368 - Boys	Inspected
Instance on Room 351 - Boys	Inspected
Instance on Room 252 - Boys	Inspected
Instance on Room 251 - Girls	Inspected
Instance on 4th Floor - Girls	Inspected
Instance on 2nd Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 368 - Boys	Inspected
Instance on Room 351 - Boys	Inspected
Instance on Room 252 - Boys	Inspected
Instance on Room 251 - Girls	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor - Girls	Inspected
Instance on 2nd Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on Room 368 - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 351 - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 252 - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 251 - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 4th Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Girls	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
Instance on Room 368 - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 351 - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 252 - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 251 - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 4th Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor - Boys	Inspected
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 368 - Boys	Does not Exist
Instance on Room 351 - Boys	Does not Exist
Instance on Room 252 - Boys	Does not Exist
Instance on Room 251 - Girls	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 368 - Boys	Does not Exist
Instance on Room 351 - Boys	Does not Exist
Instance on Room 252 - Boys	Does not Exist
Instance on Room 251 - Girls	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 368 - Boys	Does not Exist
Instance on Room 351 - Boys	Does not Exist
Instance on Room 252 - Boys	Does not Exist
Instance on Room 251 - Girls	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 368 - Boys	Does not Exist
Instance on Room 351 - Boys	Does not Exist
Instance on Room 252 - Boys	Does not Exist
Instance on Room 251 - Girls	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 405	Inspected
Power Panel	Yes
Alternative use	No

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE DEMO ROOM</b>	
Instance on Room 504	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 504	Inspected
Instance on Room 405	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 504	Inspected
Instance on Room 405	Inspected
<b>Pendant Mounted</b>	
Instance on Room 504	Does not Exist
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 504	Inspected
Instance on Room 504	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 405	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 504	Does not Exist
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 504	Does not Exist
Instance on Room 405	Inspected
<b>Pendant Mounted</b>	
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 405	Inspected
Instance on Room 405	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 405	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 504	Does not Exist
Instance on Room 405	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Room 504	Inspected
Instance on Room 405	Inspected
<b>Instructor Unit</b>	
Instance on Room 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 216	Inspected
Power Panel Alternative use	Yes No
Instance on Room 401	Inspected
Power Panel Alternative use	Yes No
Instance on Room 404	Inspected
Power Panel Alternative use	No No
Instance on Room 410	Inspected
Power Panel Alternative use	Yes No

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
Instance on Room 507	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 603	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 603	Inspected
Instance on Room 507	Inspected
Instance on Room 410	Inspected
Instance on Room 404	Inspected
Instance on Room 401	Inspected
Instance on Room 216	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 603	Inspected
Instance on Room 507	Inspected
Instance on Room 410	Inspected
Instance on Room 404	Inspected
Instance on Room 401	Inspected
Instance on Room 216	Inspected
<b>Pendant Mounted</b>	
Instance on Room 603	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 216	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 603	Does not Exist
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 410	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Violations	No violations recorded.
Instance on Room 404	Does not Exist
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 216	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 603	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Does not Exist
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 603	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 216	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 603	Does not Exist
Instance on Room 507	Inspected
Instance on Room 410	Inspected
Instance on Room 404	Does not Exist
Instance on Room 401	Inspected
Instance on Room 216	Does not Exist
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 401	Does not Exist



**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	Inspected
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 410	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 401	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 603	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 216	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 603	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 410	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 404	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 603	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE LAB</b>	
<b>Emergency Shut-Off Power</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Does not Exist
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
	Does not Exist
Instance on Room 603	Does not Exist
Instance on Room 507	Inspected
Instance on Room 410	Does not Exist
Instance on Room 404	Does not Exist
Instance on Room 401	Inspected
Instance on Room 216	Inspected
<b>Instructor Unit</b>	
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 507	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 216	Does not Exist
<b>Meter Demonstration Unit</b>	
Instance on Room 507	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
	Does not Exist
Instance on Room 603	Does not Exist
Instance on Room 507	Does not Exist
Instance on Room 410	Does not Exist
Instance on Room 404	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	
	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE PREP ROOM</b>	
Instance on Room 403	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 408, 505	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 601	Inspected
Power Panel	Yes
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 601	Inspected
Instance on Rooms 408, 505	Inspected
Instance on Room 403	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 601	Inspected
Instance on Rooms 408, 505	Inspected
Instance on Room 403	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 601	Does not Exist
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 601	Does not Exist
Instance on Rooms 408, 505	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 403	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on Room 601	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 601	Does not Exist
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 601	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 601	Does not Exist
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
	Inspected
Instance on Room 601	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 408, 505	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Does not Exist
<b>Emergency Shut-Off Power</b>	
	Inspected
Instance on Room 601	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>Power Supply</b>	
	Does not Exist
Instance on Room 601	Does not Exist
Instance on Rooms 408, 505	Does not Exist
Instance on Room 403	Does not Exist
<b>SWIMMING POOL</b>	
	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	
	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SWIMMING POOL</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	BELL NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BELL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

<b>Question</b>	<b>Response</b>
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Violations	No violations recorded.
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	N/A
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	PILOT LIGHT NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Room R30 (Inside Custodian's Workshop)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Master Control Systems
Equipment	Fire Pump Controller Automatic Transfer Switch
Capacity/Size Quantity	60
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	PILOT LIGHT NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Roof - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	
Equipment	N/A
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Roof - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Roof - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	438
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	350
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,214
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	DEFECTIVE ENGINE COOLING SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Natural Gas</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Does not Exist
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Room 603, Staircase "T" - 1st Floor Landing
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Penthouse #1, Penthouse #3, Locker Room 368 - Boys, Corridor By Rooms 601, 603
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Duct Smoke Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	3 - Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Does not Exist
<b>Elevator Recall</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor By Rooms 233, 307, 308, 434, 537, 520
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Cutout Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Radionics
Equipment	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1995
Source of Installation	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Fire Alarm Digital Communicator</b>	
Potential Action	REWIRE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Fire Alarm Panel
Model	N/A
Capacity/Size Quantity	48
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	N/A
Model	N/A
Capacity/Size Quantity	8
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	N/A
Model	N/A
Capacity/Size Quantity	128
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Wheelock Signal
Equipment	N/A
Capacity/Size Quantity	4
Capacity/Size UOM	Circuits
Source of Capacity/Size	Diagram
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	GYMNASIUM - 3rd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Does not Exist
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>GROUNDING SYSTEM</b>	Inspected
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	5 - Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator - Device IDs: 3P907, 3P908
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	PVT551152
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	2nd Floor Gymnasium, Corridor By Rooms 539A, 352A
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
Instance	Telecommunication Room - B09A
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

<b>Question</b>	<b>Response</b>
<b>PUBLIC ADDRESS SYSTEM</b>	
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	1995
Source of Installation	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Rooms 211B, 268, 512, 601
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Locker Rooms, Gymnasiums, Swimming Pool, Classrooms, Corridors, and Offices
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	2001
Source of Installation	Inspector Estimate
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inaccessible
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Service Disconnect 1
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Service Disconnect 2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Service Disconnect 3
Capacity/Size Quantity	2,000

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MDP-1
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MDP-2
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Fire Pump
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	EDP
Capacity/Size Quantity	1,200

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	3
<b>Air Circuit Breaker Type</b>	
	Does not Exist
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate



**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K440

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Roof - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Emergency Generator Switchboard
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse #3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Inspected
Instance	Swimming Pool Mechanical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Ajax Transformer Co.
Equipment	N/A

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K440**

<b>Question</b>	<b>Response</b>
<b>TRANSFORMER</b>	
Capacity/Size Quantity	300
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>TV SYSTEM</b>	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
<b>Main Equipment Rack</b>	Does not Exist