

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Asset: ERASMUS HALL CAMPUS - K, 911 FLATBUSH AVENUE, New York, 11226

Inspection Id	Inspection Type	Time In	Last Edited
EE : K465	Electrical	2018-11-19 8:01 AM	2019-06-03 3:15 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: IPDVS/CCTV System, Telephone System
	Years: 2018
	Systems: Fluorescent Lighting (2nd Floor Mezzanine and 4th Floor Locker Rooms), Students Toilet Rooms (Partial Surface Fluorescent Lighting), LED Lighting - Except (1st, 4th Floor Gymnasiums), Partial Emergency Lighting (Non Battery Pack), Partial Exit Lights (Battery Pack), Fire Alarm System (Except Sub-Panel)
	Years: 2016
	Systems: LED Lighting (1st, 4th Floor Gymnasiums), 1st Floor Gymnasium (Local Sound System, Scoreboard)
	Years: 2014
	Systems: Science Demo Room 2N2 (Instructor Unit)
	Years: 2013
	Systems: Auditorium (Local Sound System), Public Address System
	Years: 2009
	Systems: Science Lab - Rooms (2N38, 3S30), Science Prep Room 2N40, Intrusion Alarm System
	Years: 2008
	Systems: Recessed Fluorescent Lighting (Nurse's Office)
	Years: 2004
	Systems: Interior Lighting, Local Sound System, Security Lights
	Years: 1998
	Systems: Service Switch, Switchboard, Panel Boards, Emergency Generator Set, Auditorium (Theater Lighting System)
	Years: 1995

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Panel Board, Lighting Fixture, Strobes	Mechanical Room BW38, Science Demo Room 4N46, Library, 3rd Floor Gymnasium - 3W44, Corridors by Rooms (2W44, 1W44, BS14)	Nolan Parr	Fireman	Sent to DSF	
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Magnetic Door Holder/Contacto r	2nd Floor Corridor by Staircase K	Nolan Parr	Fireman	Sent to DSF	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Manual Pull Station	Auditorium Balcony, 3rd Floor Staircase E	Nolan Parr	Fireman	Sent to DSF
No	Public Address System - Speakers Not Operational	N/A	PUBLIC ADDRESS SYSTEM	Auditorium, 3rd Floor Gymnasiums - Rooms (3W44, 3N11), Rooms (5S23, 5S27, 5S30, 5S36, 5S38, 4S19, 4S21, 4S27, 4S28, 4S30, 4S34, 4S36, 4S46, 3W52, 3W58, 3S20, 3S28, 3S36, 3S40, 3S46, 4W19, 4W21, 4W23, 4W27, 1W9, 1W12)	Nolan Parr	Fireman	Sent to DSF
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Rooms BW10K, B1NB	Nolan Parr	Fireman	Sent to DSF
Yes	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM Elevator	Elevators - Device ID: 3P8458, 3P8497, 3P8498, 3P10210	Nolan Parr	Fireman	Sent to DSF
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Room BW21	Nolan Parr	Fireman	Sent to DSF

Inspection

Question	Response
----------	----------

Electrical

AUDITORIUM

Instance on 1st Floor	Inspected
-----------------------	-----------

House Lighting

Does a Chandelier exist?	Inspected
Instance on 1st Floor	No
Instance on 1st Floor	Inspected

Lighting Fixture - Fluorescent

Instance on 1st Floor	Inspected
-----------------------	-----------

Pendant Mounted

Instance on 1st Floor	Does not Exist
-----------------------	----------------

Surface Mounted

Instance on 1st Floor	Inspected
-----------------------	-----------

Condition	3 - Fair
-----------	----------

Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
AUDITORIUM	Inspected
Theater Lighting System	
Theater Lighting	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Condition	Inspected
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Condition	Inspected
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	
Condition	Does not Exist
Surface Mounted	
Condition	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Inspected
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Pendant Mounted	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
COMPUTER LAB	Inspected
Instance on Room 2S30	Inspected
Power Panel	No
Instance on Rooms 2N3, 3N12, 3W5	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Rooms 2N3, 3N12, 3W5	Inspected
Instance on Room 2S30	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 2N3, 3N12, 3W5	Inspected
Instance on Room 2S30	Inspected
Pendant Mounted	Inspected
Instance on Rooms 2N3, 3N12, 3W5	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2S30	Does not Exist
Surface Mounted	Does not Exist
Instance on Rooms 2N3, 3N12, 3W5	Does not Exist
Instance on Room 2S30	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 2N3, 3N12, 3W5	Does not Exist
Instance on Room 2S30	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 2N3, 3N12, 3W5	Does not Exist
Instance on Room 2S30	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 2N3, 3N12, 3W5	Does not Exist
Instance on Room 2S30	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 2N3, 3N12, 3W5	Does not Exist
Instance on Room 2S30	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 2N3, 3N12, 3W5	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2S30	Does not Exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Instance on 3rd Floor - Room 3N11	Inspected
Instance on 3rd Floor - Room 3W44	Inspected
Instance on 4th Floor	Inspected
Lighting	Inspected
Instance on 4th Floor	Inspected
Instance on 3rd Floor - Room 3W44	Inspected
Instance on 3rd Floor - Room 3N11	Inspected
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor	Inspected
Instance on 3rd Floor - Room 3W44	Inspected
Instance on 3rd Floor - Room 3N11	Inspected
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Room 3W44	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Room 3N11	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Inspected
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Room 3N11	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 4th Floor	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Room 3W44	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Room 3N11	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
GYMNASIUM	
Projection System	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 3rd Floor - Room 3W44	Does not Exist
Instance on 3rd Floor - Room 3N11	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 4S20	Inspected
Lighting	Inspected
Instance on Room 4S20	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 4S20	Inspected
Pendant Mounted	Inspected
Instance on Room 4S20	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
	Does not Exist
Instance on Room 4S20	Does not Exist
Recessed Mounted	
	Does not Exist
Instance on Room 4S20	Does not Exist
Lighting Fixture - HID	
Instance on Room 4S20	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 4S20	Inspected
Pendant Mounted	
	Inspected
Instance on Room 4S20	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Does not Exist
Instance on Room 4S20	Does not Exist
Recessed Mounted	
	Does not Exist
Instance on Room 4S20	Does not Exist
Lighting Fixture - LED	
Instance on Room 4S20	Inspected
Pendant Mounted	
	Does not Exist
Instance on Room 4S20	Does not Exist
Surface Mounted	
	Inspected
Instance on Room 4S20	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
	Inspected
Instance on Room 4S20	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Raceway With Receptacles	
	Inspected
Instance on Room 4S20	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
	Does not Exist
Instance on Room 4S20	Does not Exist
LOCKER ROOM	
	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Alternative use	No
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
LOCKER ROOM	
Alternative use	No
Instance on 2nd Floor Mezzanine - Weight Room	Inspected
Alternative use	Yes
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Alternative use	No
Instance on Basement - Boys	Inspected
Alternative use	No
Instance on Basement - Girls	Inspected
Alternative use	No
Lighting	Inspected
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Instance on 2nd Floor Mezzanine - Weight Room	Inspected
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Instance on 2nd Floor Mezzanine - Weight Room	Inspected
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Instance on 2nd Floor Mezzanine - Weight Room	Does not Exist
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Surface Mounted	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor Mezzanine - Weight Room	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not Exist
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Boys	Inspected
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor Mezzanine - Weight Room	Does not Exist
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Instance on 2nd Floor Mezzanine - Weight Room	Does not Exist
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Instance on 2nd Floor Mezzanine - Weight Room	Does not Exist
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - LED	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
LOCKER ROOM	
Lighting	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Instance on 2nd Floor Mezzanine - Weight Room	Does not Exist
Instance on 2nd Floor Mezzanine - Boys, 2nd Floor Mezzanine - Girls (North), 2nd Floor Mezzanine - Girls (South)	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
SCIENCE DEMO ROOM	
Instance on Room 2N2	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE DEMO ROOM	
Power Panel	No
Alternative use	No
Instance on Room 3E22	Inspected
Power Panel	No
Alternative use	No
Instance on Room 3N32	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 4N40	Inspected
Power Panel	No
Alternative use	No
Instance on Room 4N46	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 3W16, 3E7	Inspected
Power Panel	No
Alternative use	Yes
Lighting	Inspected
Instance on Rooms 3W16, 3E7	Inspected
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Instance on Room 4N46	Inspected
Instance on Room 4N40	Inspected
Instance on Room 3N32	Inspected
Instance on Room 3E22	Inspected
Instance on Room 2N2	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 3W16, 3E7	Inspected
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Instance on Room 4N46	Inspected
Instance on Room 4N40	Inspected
Instance on Room 3N32	Inspected
Instance on Room 3E22	Inspected
Instance on Room 2N2	Inspected
Pendant Mounted	
Instance on Rooms 3W16, 3E7	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N46	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N40	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3N32	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3E22	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N2	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Recessed Mounted	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Instance on Room 4N46	Inspected
Instance on Room 4N40	Inspected
Instance on Room 3N32	Inspected
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Pendant Mounted	
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on Room 4N46	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N40	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Recessed Mounted	
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Projection System	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Does not Exist
Emergency Shut-Off Power	
	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	
Instance on Rooms 3W16, 3E7	Does not Exist
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Does not Exist
Instance on Room 4N40	Does not Exist
Instance on Room 3N32	Does not Exist
Instance on Room 3E22	Does not Exist
Instance on Room 2N2	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	
	Inspected
Instance on Rooms 3W16, 3E7	Inspected
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Instance on Room 4N46	Inspected
Instance on Room 4N40	Inspected
Instance on Room 3N32	Inspected
Instance on Room 3E22	Inspected
Instance on Room 2N2	Inspected
Instructor Unit	
Instance on Rooms 3W16, 3E7	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W1, 3W3, 3N34	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N46	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N40	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3E22	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N2	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 3W16, 3E7	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W1, 3W3, 3N34	Does not Exist
Instance on Room 4N46	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Meter Demonstration Unit	
Instance on Room 4N40	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3E22	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N2	Does not Exist
SCIENCE LAB	
Instance on Room 2N38	Inspected
Power Panel Alternative use	No No
Instance on Room 3N38	Inspected
Power Panel Alternative use	Yes No
Instance on Room 3S30	Inspected
Power Panel Alternative use	Yes No
Instance on Room 4N32	Inspected
Power Panel Alternative use	Yes No
Instance on Rooms 3W10,4W3	Inspected
Power Panel Alternative use	No No
Instance on Room 3E23, 3E19	Inspected
Power Panel Alternative use	Yes No
Lighting	
Instance on Room 3E23, 3E19	Inspected
Instance on Rooms 3W10,4W3	Inspected
Instance on Room 4N32	Inspected
Instance on Room 3S30	Inspected
Instance on Room 3N38	Inspected
Instance on Room 2N38	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 3E23, 3E19	Inspected
Instance on Rooms 3W10,4W3	Inspected
Instance on Room 4N32	Inspected
Instance on Room 3S30	Inspected
Instance on Room 3N38	Inspected
Instance on Room 2N38	Inspected
Pendant Mounted	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Does not Exist
Recessed Mounted	
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Does not Exist
Lighting Fixture - HID	
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Inspected
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Inspected
Pendant Mounted	
Instance on Room 4N32	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 2N38	Does not Exist
Lighting Fixture - LED	
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 3E23, 3E19	Inspected
Instance on Rooms 3W10,4W3	Inspected
Instance on Room 4N32	Inspected
Instance on Room 3S30	Inspected
Instance on Room 3N38	Inspected
Instance on Room 2N38	Inspected
Instructor Unit	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Does not Exist
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance on Room 2N38	Does not Exist
Meter Demonstration Unit	
Instance on Room 3E23, 3E19	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 3W10,4W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N38	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 3E23, 3E19	Does not Exist
Instance on Rooms 3W10,4W3	Does not Exist
Instance on Room 4N32	Does not Exist
Instance on Room 3S30	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 3N38	Does not Exist
Instance on Room 2N38	Does not Exist
SCIENCE PREP ROOM	
	Inspected
Instance on Room 2N40	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 3E21	Inspected
Power Panel	No
Alternative use	No
Instance on Room 4N32A	Inspected
Power Panel	No
Alternative use	No
Instance on Room 4W1	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 3N46, 4N28	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Rooms 3N46, 4N28	Inspected
Instance on Room 4W1	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE PREP ROOM	
Lighting	
Instance on Room 4N32A	Inspected
Instance on Room 3E21	Inspected
Instance on Room 2N40	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 3N46, 4N28	Inspected
Instance on Room 4W1	Inspected
Instance on Room 4N32A	Inspected
Instance on Room 3E21	Inspected
Instance on Room 2N40	Inspected
Pendant Mounted	
Instance on Rooms 3N46, 4N28	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4W1	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 3E21	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 2N40	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Recessed Mounted	
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Emergency Gas Shut-Off Valve	
	Does not Exist
Instance on Rooms 3N46, 4N28	Does not Exist
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
	Inspected
Instance on Rooms 3N46, 4N28	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4W1	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
	Inspected
Instance on Rooms 3N46, 4N28	Inspected
Instance on Room 4W1	Does not Exist
Instance on Room 4N32A	Does not Exist
Instance on Room 3E21	Does not Exist
Instance on Room 2N40	Does not Exist
Instructor Unit	
Instance on Rooms 3N46, 4N28	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not Exist
Lighting Fixture - HID	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SWIMMING POOL	
Lighting	
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Scoreboard	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	384,000
Replacement Uom	S.F.
Condition	4 - Between Fair and Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Boiler Room (By Fire Pump)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Firetrol
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Elevator Machine Room (South Building Roof)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Equipment	N/A
Capacity/Size Quantity	260
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	POORLY GROUNDED
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Room BE17 (By Swimming Pool)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #7
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-3
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN30
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #4
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BS30
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	POORLY GROUNDED
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Room BW21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #6
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW21

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #9
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Outdoor Generator Enclosure (East Building Roof)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Charles Industries
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Outdoor Generator Enclosure (East Building Roof)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	375
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	300
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,041
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
EMERGENCY LIGHTING	Inspected
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	1st Floor by Staircase G, Library
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Basement - Girls Locker Room, 2nd Floor Mezzanine - Girls (South)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Room 1E10
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	384,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
FIRE ALARM SYSTEM	
Manual Pull Station	
Condition	1 - Good
Deficiency	PULL STATION NOT OPERATIONAL
Deficiency Location/Instance	Auditorium Balcony, 3rd Floor Corridor by Staircase E
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fan Shutdown Control	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Area Smoke Detector	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
CO Detector	
Condition	Does not Exist
Heat Detector	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
Condition	Inspected
Deficiency	1 - Good
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor by Staircase K
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Cutout Panel	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	
Condition	Does not Exist
Main Panel	
Condition	Inspected
Bell At Panel	
Condition	Does not Exist
Fire Alarm Control Panel (Electronic)	
Instance	Inspected
Instance	Room BW21
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance Manufacturer	Gamewell
Equipment	Fire Alarm Control Panel
Model	E3 Series
Capacity/Size Quantity	32
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2016
Source of Installation	Custodial Staff
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	E426541
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Room BW38
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Deluge Preaction Control Panel
Model	RP - 1001
Capacity/Size Quantity	2
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2007
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevators - Device ID: 3P8458, 3P8497, 3P8498, 3P10210
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	38259086J, PVT449396, PVT449399
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Fan Room BN34 (S-21 Supply Fan), Fan Room Bn40 (S-22 Supply Fan)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
MOTOR STARTER/CONTACTOR	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	MOTOR STARTER INDICATOR LIGHT NOT OPERATIONAL
Deficiency Location/Instance	Fan Room BN34
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Custodial's Workshop - Room BS30
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	2nd Floor Corridor by Room 2W44, Custodial's Workshop - Room BS30
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Custodial's Workshop - Room BS30
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	384,000
Replacement Uom	S.F.
Instance	Room 1W27 (Inside Custodian's Office)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA125A
Installation Year	2009
Source of Installation	Custodial Staff
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Location/Instance	High School For Service and Learning Principal's Office Room 1S46
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, 3rd Floor Gymnasiums - Rooms (3W44, 3N11), Rooms (5S23, 5S27, 5S30, 5S36, 5S38, 4S19, 4S21, 4S27, 4S28, 4S30, 4S34, 4S36, 4S46, 3W52, 3W58, 3S20, 3S28, 3S36, 3S40, 3S46, 4W19, 4W21, 4W23, 4W27, 1W9, 1W12)
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	384,000
Replacement Uom	S.F.
Installation Year	2018
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SECURITY	
IPDVS/CCTV System	
Condition	1 - Good
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Corridors by Rooms 2N2B, 2W44, 3E10, 4W19
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Intrusion Alarm System	
Replacement Quantity	Inspected
Replacement Uom	384,000
Central Control Panel	
Instance	S.F.
Instance Condition	Inspected
Instance Quantity	Room 1W12
Instance Quantity Uom	4 - Between Fair and Poor
Model	1
Installation Year	EACH
Source of Installation	Vista - 250BP
Deficiency	2008
Deficiency Quantity	Custodial Staff
Quantity Uom	PANEL NOT OPERATIONAL
Potential Action	1
Urgency of Action	EACH
Purpose of Action	REPAIR
Deficiency Photo1	PRIORITY 4
Violations	LEVEL 3
Infrared Sensor	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Panic Switch	
Condition	No deficiencies recorded
Deficiency	Inspected
Remote Annunciator	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Ultrasonic Sensor	
Condition	Does not Exist
Lighting - Security	
Replacement Quantity	Inspected
Replacement Uom	45
Condition	EACH
Deficiency	3 - Fair
Violations	LIGHTING FIXTURE BALLAST DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SECURITY	
Lighting - Security	
Deficiency Location/Instance	Roof facing Bedford Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	4th Floor by (Staircase K, Room 4W29)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DP-E 1939 BLDG
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	SWB #3 1924 BLDG
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K465

Question	Response
SERVICE SWITCH	
Equipment	EDP 2
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	CONST - TRLS
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DP-B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power
Equipment	SSA (Spare)
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SERVICE SWITCH	
Equipment	SWB-1A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power
Equipment	SWB-1
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power
Equipment	SWB-2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power
Equipment	EDP-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mac Power

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SERVICE SWITCH	
Equipment	Fire Pump
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
Number of Spares	8
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Room 1S39
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DP-E
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN1B
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	EDP-II (Emergency Generator Switchboard)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DP-B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BN30
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	SWBD-2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	SWB-1A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K465

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Room BW10K
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	EDP-1 (Emergency Generator Switchboard)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room BW10U
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist