

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

**K495**

**Asset: SHEEPSHEAD BAY HS - K, 3000 AVENUE X, New York, 11235**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K495	Electrical	2019-04-30 8:45 AM	2019-05-29 9:49 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: IPDVS/CCTV System
	Years: 2018
	Systems: Telephone System
	Years: 2017
	Systems: Auditorium (Recessed Fluorescent Lighting), Gymnasium (LED Lighting), Computer Lab Room 253 (Raceways with Receptacles)
	Years: 2015
	Systems: Lightning Protection
	Years: 2014
	Systems: Intercom System
	Years: 2010
	Systems: 1st Floor Gymnasium (Scoreboard)
	Years: 2008
	Systems: Auditorium (Local Sound System)
	Years: 2007
	Systems: Switchboard
	Years: 2006
	Systems: Fire Alarm System, Emergency Light/Exit Light Panel, Intrusion Alarm System
	Years: 2004
	Systems: Security Lights
	Years: 2003, 2014
	Systems: Pendant Fluorescent Lighting, Retrofitted Surface and Recessed Fluorescent lighting
	Years: 2001
	Systems: Most Molded Case Circuit Breaker Panel Board
	Years: 1998, 2000, 2006
	Systems: Auditorium (Theater Lighting System)
	Years: 1998

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Potential Falling Electrical Component	Lighting Fixture is about to fall	Lighting Fixture	Cafeteria	James O'Connor	Fireman	Sent to DSF	
No	Fire Alarm System - Components Missing	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	Corridor by Room 091	James O'Connor	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

**K495**

Yes	Intercom - Not Operational	N/A	INTERCOM SYSTEM   Elevator	Elevator - Device IDs: 3P6408, 3P5263	James O'Connor Fireman	Sent to DSF
-----	----------------------------	-----	----------------------------	---------------------------------------	------------------------	-------------

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Dimming System</b>	
Violations	No violations recorded.
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
<b>Lighting</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not Exist
<b>Recessed Mounted</b>	
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor - Students	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Does not Exist
<b>Projection System</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Theater Lighting System</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	
Instance on Room 067	Inspected
Power Panel	Yes
Instance on Room 253	Inspected
Power Panel	Yes
Instance on Room 273/275	Inspected
Power Panel	Yes
<b>Lighting</b>	
Instance on Room 273/275	Inspected
Instance on Room 253	Inspected
Instance on Room 067	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 273/275	Inspected
Instance on Room 253	Inspected
Instance on Room 067	Inspected
<b>Pendant Mounted</b>	
Instance on Room 273/275	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency	No deficiencies recorded
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 067	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on Room 273/275	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Does not Exist
Instance on Room 067	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 273/275	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 067	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 273/275	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 067	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 273/275	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 067	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 273/275	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 067	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 273/275	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 067	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor	Inspected
Instance on Basement - 081G	Inspected
Instance on Basement - 082G	Inspected
<b>Lighting</b>	Inspected
Instance on Basement - 082G	Inspected
Instance on Basement - 081G	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - 082G	Inspected
Instance on Basement - 081G	Inspected
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on Basement - 082G	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Basement - 081G	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
Instance on Basement - 082G	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>GYMNASIUM</b>	
<b>Local Sound System</b>	
Instance on Basement - 081G	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	Does not Exist
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on Basement - 082G	Does not Exist
Instance on Basement - 081G	Does not Exist
Instance on 1st Floor	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 236	Inspected
<b>Lighting</b>	Inspected
Instance on Room 236	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 236	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 236	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 236	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 236	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 236	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 236	Does not Exist
<b>Raceway With Receptacles</b>	Does not Exist
Instance on Room 236	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 236	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Inspected
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Girls, Basement - Girls Varsity, Basement -	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Boys, Basement - Boys Varsity	
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Girls, Basement - Girls Varsity, Basement - Boys, Basement - Boys Varsity	Does not Exist
<b>MULTIPURPOSE ROOM</b>	
Instance on 1st Floor - 171G	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - 171G	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - 171G	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor - 171G	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor - 171G	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor - 171G	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>Projection System</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>Theater Lighting System</b>	
	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>MULTIPURPOSE ROOM</b>	Inspected
<b>Theater Lighting System</b>	
Instance on 1st Floor - 171G	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 225	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room 227	Inspected
Power Panel	No
Alternative use	No
Instance on Room 229	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room 271	Inspected
Power Panel	No
Alternative use	No
Instance on Room 325	Inspected
Power Panel	No
Alternative use	No
Instance on Room 371	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 272	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 327, 329	Inspected
Power Panel	No
Alternative use	No
Instance on Room 372	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 372	Inspected
Instance on Rooms 327, 329	Inspected
Instance on Room 272	Inspected
Instance on Room 371	Inspected
Instance on Room 325	Inspected
Instance on Room 271	Inspected
Instance on Room 229	Inspected
Instance on Room 227	Inspected
Instance on Room 225	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 372	Inspected
Instance on Rooms 327, 329	Inspected
Instance on Room 272	Inspected
Instance on Room 371	Inspected
Instance on Room 325	Inspected
Instance on Room 271	Inspected
Instance on Room 229	Inspected
Instance on Room 227	Inspected
Instance on Room 225	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Inspected
Instance on Room 372	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 329	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 371	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 229	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on Room 372	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 371	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Does not Exist
Instance on Room 271	Does not Exist
Instance on Room 229	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 271	Does not Exist
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 271	Does not Exist
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 271	Does not Exist
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 271	Does not Exist
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Projection System</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Projection System</b>	
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 271	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 372	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 329	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 371	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 372	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 329	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 371	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Emergency Shut-Off Power</b>	
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Room 372	Inspected
Instance on Rooms 327, 329	Inspected
Instance on Room 272	Inspected
Instance on Room 371	Inspected
Instance on Room 325	Inspected
Instance on Room 271	Inspected
Instance on Room 229	Inspected
Instance on Room 227	Inspected
Instance on Room 225	Inspected
<b>Instructor Unit</b>	
Instance on Room 372	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 329	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 371	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 229	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**Meter Demonstration Unit**

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Meter Demonstration Unit</b>	
Instance on Room 372	Does not Exist
Instance on Rooms 327, 329	Does not Exist
Instance on Room 272	Does not Exist
Instance on Room 371	Does not Exist
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271	Does not Exist
Instance on Room 229	Does not Exist
Instance on Room 227	Does not Exist
Instance on Room 225	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 228	Inspected
Power Panel Alternative use	Yes No
Instance on Room 320	Inspected
Power Panel Alternative use	No No
Instance on Room 328	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	Inspected
Instance on Room 328	Inspected
Instance on Room 320	Inspected
Instance on Room 228	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 328	Inspected
Instance on Room 320	Inspected
Instance on Room 228	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 328	Does not Exist
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 328	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 320	Does not Exist
Instance on Room 228	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 328	Does not Exist
Instance on Room 320	Does not Exist
Instance on Room 228	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 328	Does not Exist
Instance on Room 320	Does not Exist
Instance on Room 228	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 328	Does not Exist
Instance on Room 320	Does not Exist
Instance on Room 228	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 328	Inspected
Instance on Room 320	Inspected
Instance on Room 228	Inspected
<b>Instructor Unit</b>	
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
	Does not Exist
Instance on Room 328	Does not Exist
Instance on Room 320	Does not Exist
Instance on Room 228	Does not Exist
<b>SCIENCE PREP ROOM</b>	
	Inspected
Instance on Room 224/226	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 271P	Inspected
Power Panel	No
Alternative use	No
Instance on Room 324	Inspected
Power Panel	No
Alternative use	No
Instance on Room 330	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	
	Inspected
Instance on Room 330	Inspected
Instance on Room 324	Inspected
Instance on Room 271P	Inspected
Instance on Room 224/226	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 330	Inspected
Instance on Room 324	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 271P	Inspected
Instance on Room 224/226	Inspected
<b>Pendant Mounted</b>	
Instance on Room 330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271P	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 224/226	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 330	Does not Exist
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 330	Does not Exist
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 330	Does not Exist
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 330	Does not Exist
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 330	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 330	Inspected
Instance on Room 324	Does not Exist
Instance on Room 271P	Does not Exist
Instance on Room 224/226	Does not Exist
<b>Instructor Unit</b>	
Instance on Room 330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
Does not Exist	
<b>TOILET ROOM - STAFF</b>	
Inspected	
<b>Lighting</b>	
Inspected	
<b>Lighting Fixture - Fluorescent</b>	
Inspected	
<b>Pendant Mounted</b>	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Does not Exist	
<b>Lighting Fixture - HID</b>	
Does not Exist	
<b>Lighting Fixture - Incandescent</b>	
Does not Exist	
<b>Lighting Fixture - LED</b>	
Does not Exist	
<b>TOILET ROOM - STUDENT</b>	
Inspected	
<b>Lighting</b>	
Inspected	
<b>Lighting Fixture - Fluorescent</b>	
Inspected	
<b>Pendant Mounted</b>	
Does not Exist	
<b>Surface Mounted</b>	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Inspected	

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	300,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	300,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	CONTACTOR MISSING
Deficiency Location/Instance	Corridor by Room 091
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL CONTACTOR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	N/A
Model	EST 2
Capacity/Size Quantity	16
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2004

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	Inspected
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Strobe Panel
Model	N/A
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2004
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Door Holder Panel
Model	N/A
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2004
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	Inspected
<b>Tamper Flow Switch/Chain</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator - Device IDs: 3P6408, 3P5263
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Holding Area</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms 307, 225
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Fan Room 073E
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Kitchen, Fan Rooms 062, B20
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors by Rooms 198, 117, 076, Rooms 253, 236, 185, 171G, 161, 076, Fan Rooms 073E, 062, B20, Boiler Room, Students Cafeteria, Kitchen, Custodian's Office, Auditorium, 1st Floor Gymnasium
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms 165, 062, Rooms 290, 228
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	Inspected
<b>Molded Case Circuit Breaker Type</b>	
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	300,000
Replacement Uom	S.F.
Instance	Room 290
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TAX 250C
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 290
Deficiency Quantity	300,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	300,000
Replacement Uom	S.F.
Installation Year	2018
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	300,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	51
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Exterior lights by Exits 5/6, 9/10
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room 053
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Switchboard East Section A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1959
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 053
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SERVICE SWITCH</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room 053
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Switchboard East Section B
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1959
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 053
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room 053
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Switchboard West
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1959
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 053
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room 053
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1959
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 053
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room B22A
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Kitchen Equipment
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1959
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B22A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SWITCHBOARD</b>	Inspected
Number of Spares	7
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room 053
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	East Distribution A Section 1, 2
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K495

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room 053
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	East Distribution B Section 1, 2
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Room 073E
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	LP-PP
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Instance	Electrical Room B22A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Dist SWBD West (A)
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

**K495**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room B22A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Dist SWBD West (B)
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	Yes
<b>Main Equipment Rack</b>	Does not Exist