

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K705

Asset: MIDWOOD HS ADDITION - BROOKLYN, 2886 BEDFORD AVENUE, New York, 11210

Inspection Id	Inspection Type	Time In	Last Edited
EE : K705	Electrical	2017-11-14 12:40 PM	2017-11-28 9:35 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Public Address System
	Years: Under construction
	Systems: Panic Switch
	Years: 2016
	Systems: All Other Electrical Systems and Components
	Years: 2008

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Elevator Recall	1st Floor - in front of Elevator #1	Steven Fassano	Custodian	Sent to DSF	
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Magnetic Door Holder/Contacto r	Corridor by Rooms (119, 200, 300)	Steven Fassano	Custodian	Sent to DSF	
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Tamper Flow Switch/Chain	Room 292	Steven Fassano	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K705

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Inspected
Instance on Room 100-1A	Inspected
Lighting	Inspected
Instance on Room 100-1A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 100-1A	Inspected
Pendant Mounted	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 100-1A	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 100-1A	Does not Exist
Lighting Fixture - LED	
Instance on Room 100-1A	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 100-1A	Does not Exist
Projection System	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 218, 220, 316, 318	Inspected
Power Panel	No
Alternative use	No

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
SCIENCE DEMO ROOM	
Lighting	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Surface Mounted	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Recessed Mounted	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Surface Mounted	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
Projection System	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Instructor Unit	
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance on Rooms 215, 219, 313, 319	Inspected
Power Panel Alternative use	Yes No
Lighting	
Instance on Rooms 215, 219, 313, 319	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 215, 219, 313, 319	Inspected
Pendant Mounted	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Surface Mounted	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Recessed Mounted	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Lighting Fixture - Incandescent	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Rooms 215, 219, 313, 319	Inspected
Pendant Mounted	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Surface Mounted	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 215, 219, 313, 319	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 215, 219, 313, 319	Inspected
Instructor Unit	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 214	Inspected
Power Panel Alternative use	Yes No
Instance on Rooms 217, 317	Inspected
Power Panel Alternative use	Yes No
Lighting	
Instance on Rooms 217, 317	Inspected
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms 217, 317	Inspected
Instance on Room 214	Inspected
Pendant Mounted	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
Surface Mounted	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
Recessed Mounted	
Instance on Rooms 217, 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 217, 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 217, 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Inspected
Instructor Unit	
Instance on Room 214	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Basement - Mechanical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metron Inc
Equipment	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room C14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #2 1200A

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room C14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #1 Fire Alarm System
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Does not Exist
Diesel	Inspected
Instance	Outside Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Generac
Equipment	Emergency Generator
Capacity/Size Quantity	344
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	275
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	954
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
EXIT LIGHT	Inspected
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	1st Floor - in front of Elevator #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Magnetic Door Holder/Contactor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (119, 200, 300)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K705

Question	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	Inspected
Violations	No violations recorded.
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Room 109B
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Ademco
Equipment	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	8
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not Exist
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Room 292
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Under Construction
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K705

Question	Response
SECURITY	
IPDVS/CCTV System	Inspected
Installation Year	2008
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Room 200C
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BPT
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	16
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Service Disconnect
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K705

Question	Response
SWITCHBOARD	
Number of Spares	3
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDP SWBD
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room C14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	EDB - SWBD (Emergency Generator Switchboard)
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist