

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

**Asset:** PS 152 ANNEX -BROOKLYN, 1087 OCEAN AVENUE, New York, 11210

| Inspection Id | Inspection Type | Time In             | Last Edited        |
|---------------|-----------------|---------------------|--------------------|
| EE : K776     | Electrical      | 2018-03-20 12:16 PM | 2018-03-23 5:24 PM |

Asset Data

| Question  | Answer   |
|---|--|
| Type of Service   | Below Ground   |
| Does Interactive Whiteboard (IWB) Exist?                  | Yes  |
| Water Penetration in Electrical Room?                     | No   |
| Have any Systems/Major Building Components been upgraded? | Yes  |
|   | Systems: Interior Lighting   |
|   | Years: 2015  |
|   | Systems: Security Lights, Partial Motor Starter  |
|   | Years: 2010  |
|   | Systems: Intercom System (Elevator)  |
|   | Years: 2008  |
|   | Systems: Grounding System, LAN, Telephone System, Exit Lights (Battery Pack), Exit/Emergency Light |
|   | Years: 2007  |
|   | Systems: Partial Molded Case Circuit Breaker Panel Board   |
|   | Years: 2000, 2006, 2010  |

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

| Question  | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No       |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded               |                   |                       |                    |                      |                    |                 |        |            |

Inspection

| Question                               | Response                 |
|--|--------------------------|
| <b>Electrical</b>                      |                          |
| <b>AUDITORIUM</b>                      | Does not Exist           |
| <b>CAFETERIA</b>                       | Inspected                |
| Instance on Basement                   | Inspected                |
| <b>Lighting</b>                        | Inspected                |
| Instance on Basement                   | Inspected                |
| <b>Lighting Fixture - Fluorescent</b>  |                          |
| Instance on Basement                   | Inspected                |
| <b>Pendant Mounted</b>                 | Does not Exist           |
| Instance on Basement                   | Does not Exist           |
| <b>Surface Mounted</b>                 | Inspected                |
| Instance on Basement                   | Inspected                |
| Condition                              | 1 - Good                 |
| Deficiency                             | No deficiencies recorded |
| <b>Recessed Mounted</b>                | Does not Exist           |
| Instance on Basement                   | Does not Exist           |
| <b>Lighting Fixture - HID</b>          |                          |
| Instance on Basement                   | Does not Exist           |
| <b>Lighting Fixture - Incandescent</b> |                          |
| Instance on Basement                   | Does not Exist           |

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| Question                                       | Response                 |
|--|--------------------------|
| <b>CAFETERIA</b>                               |                          |
| <b>Lighting</b>                                |                          |
| <b>Lighting Fixture - LED</b>                  |                          |
| Instance on Basement                           | Does not Exist           |
| <b>Local Sound System</b>                      | Does not Exist           |
| Instance on Basement                           | Does not Exist           |
| <b>Projection System</b>                       | Does not Exist           |
| Instance on Basement                           | Does not Exist           |
| <b>Theater Lighting System</b>                 | Does not Exist           |
| Instance on Basement                           | Does not Exist           |
| <b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b> | Inspected                |
| <b>Lighting</b>                                | Inspected                |
| Does a Chandelier exist?                       | No                       |
| <b>Lighting Fixture - Fluorescent</b>          | Inspected                |
| <b>Pendant Mounted</b>                         | Does not Exist           |
| <b>Surface Mounted</b>                         | Inspected                |
| Condition                                      | 1 - Good                 |
| Deficiency                                     | No deficiencies recorded |
| <b>Recessed Mounted</b>                        | Does not Exist           |
| <b>Lighting Fixture - HID</b>                  | Does not Exist           |
| <b>Lighting Fixture - Incandescent</b>         | Does not Exist           |
| <b>Lighting Fixture - LED</b>                  | Does not Exist           |
| <b>COMPUTER LAB</b>                            | Does not Exist           |
| <b>GYMNASIUM</b>                               | Does not Exist           |
| <b>KITCHEN</b>                                 | Inspected                |
| Instance on Basement                           | Inspected                |
| <b>Lighting</b>                                | Inspected                |
| Instance on Basement                           | Inspected                |
| <b>Lighting Fixture - Fluorescent</b>          |                          |
| Instance on Basement                           | Inspected                |
| <b>Pendant Mounted</b>                         | Does not Exist           |
| Instance on Basement                           | Does not Exist           |
| <b>Surface Mounted</b>                         | Inspected                |
| Instance on Basement                           | Inspected                |
| Condition                                      | 1 - Good                 |
| Deficiency                                     | No deficiencies recorded |
| <b>Recessed Mounted</b>                        | Does not Exist           |
| Instance on Basement                           | Does not Exist           |
| <b>Lighting Fixture - HID</b>                  |                          |
| Instance on Basement                           | Does not Exist           |
| <b>Lighting Fixture - Incandescent</b>         |                          |
| Instance on Basement                           | Does not Exist           |
| <b>Lighting Fixture - LED</b>                  |                          |
| Instance on Basement                           | Does not Exist           |
| <b>LIBRARY</b>                                 | Inspected                |
| Instance on Room 208                           | Inspected                |
| <b>Lighting</b>                                | Inspected                |
| Instance on Room 208                           | Inspected                |

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| Question                               | Response                 |
|--|--------------------------|
| <b>LIBRARY</b>                         |                          |
| <b>Lighting</b>                        |                          |
| <b>Lighting Fixture - Fluorescent</b>  |                          |
| Instance on Room 208                   | Inspected                |
| <b>Pendant Mounted</b>                 | Does not Exist           |
| Instance on Room 208                   | Does not Exist           |
| <b>Surface Mounted</b>                 | Inspected                |
| Instance on Room 208                   | Inspected                |
| Condition                              | 1 - Good                 |
| Deficiency                             | No deficiencies recorded |
| <b>Recessed Mounted</b>                | Does not Exist           |
| Instance on Room 208                   | Does not Exist           |
| <b>Lighting Fixture - HID</b>          |                          |
| Instance on Room 208                   | Does not Exist           |
| <b>Lighting Fixture - Incandescent</b> |                          |
| Instance on Room 208                   | Does not Exist           |
| <b>Lighting Fixture - LED</b>          |                          |
| Instance on Room 208                   | Does not Exist           |
| <b>Raceway With Receptacles</b>        | Does not Exist           |
| Instance on Room 208                   | Does not Exist           |
| <b>Projection System</b>               | Does not Exist           |
| Instance on Room 208                   | Does not Exist           |
| <b>LOCKER ROOM</b>                     | Does not Exist           |
| <b>MULTIPURPOSE ROOM</b>               | Does not Exist           |
| <b>SCIENCE DEMO ROOM</b>               | Does not Exist           |
| <b>SCIENCE LAB</b>                     | Does not Exist           |
| <b>SCIENCE PREP ROOM</b>               | Does not Exist           |
| <b>SWIMMING POOL</b>                   | Does not Exist           |
| <b>TOILET ROOM - STAFF</b>             | Inspected                |
| <b>Lighting</b>                        | Inspected                |
| <b>Lighting Fixture - Fluorescent</b>  | Inspected                |
| <b>Pendant Mounted</b>                 | Does not Exist           |
| <b>Surface Mounted</b>                 | Inspected                |
| Condition                              | 1 - Good                 |
| Deficiency                             | No deficiencies recorded |
| <b>Recessed Mounted</b>                | Does not Exist           |
| <b>Lighting Fixture - HID</b>          | Does not Exist           |
| <b>Lighting Fixture - Incandescent</b> | Does not Exist           |
| <b>Lighting Fixture - LED</b>          | Does not Exist           |
| <b>TOILET ROOM - STUDENT</b>           | Inspected                |
| <b>Lighting</b>                        | Inspected                |
| <b>Lighting Fixture - Fluorescent</b>  | Inspected                |
| <b>Pendant Mounted</b>                 | Does not Exist           |
| <b>Surface Mounted</b>                 | Inspected                |
| Condition                              | 1 - Good                 |
| Deficiency                             | No deficiencies recorded |
| <b>Recessed Mounted</b>                | Does not Exist           |
| <b>Lighting Fixture - HID</b>          | Does not Exist           |

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| <b>Question</b>                           | <b>Response</b>                  |
|---|----------------------------------|
| <b>TOILET ROOM - STUDENT</b>              | Inspected                        |
| <b>Lighting</b>                           |                                  |
| <b>Lighting Fixture - Incandescent</b>    | Does not Exist                   |
| <b>Lighting Fixture - LED</b>             | Does not Exist                   |
| <b>AUXILIARY SIGNAL/BELL SYSTEM</b>       | Inspected                        |
| Replacement Quantity                      | 24,000                           |
| Replacement Uom                           | S.F.                             |
| Condition                                 | 3 - Fair                         |
| Deficiency                                | DOOR PUSH BUTTON NOT OPERATIONAL |
| Deficiency Location/Instance              | Main Entrance Door               |
| Deficiency Quantity                       | 1                                |
| Quantity Uom                              | EACH                             |
| Potential Action                          | MAINTENANCE                      |
| Urgency of Action                         | PRIORITY 3                       |
| Purpose of Action                         | LEVEL 2                          |
| Deficiency Photo1                         | No photo recorded                |
| Violations                                | No violations recorded.          |
| <b>EMERGENCY DC STANDBY BATTERY POWER</b> | Does not Exist                   |
| <b>EMERGENCY GENERATOR SET</b>            | Does not Exist                   |
| <b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>   | Does not Exist                   |
| <b>EMERGENCY LIGHTING</b>                 | Inspected                        |
| <b>Battery Pack</b>                       | Inspected                        |
| Condition                                 | 3 - Fair                         |
| Deficiency                                | FIXTURE LENS MISSING             |
| Deficiency Location/Instance              | Cafeteria                        |
| Deficiency Quantity                       | 1                                |
| Quantity Uom                              | EACH                             |
| Potential Action                          | INSTALL LENS                     |
| Urgency of Action                         | PRIORITY 5                       |
| Purpose of Action                         | LEVEL 2                          |
| Deficiency Photo1                         | No photo recorded                |
| Violations                                | No violations recorded.          |
| <b>Non Battery Pack</b>                   | Does not Exist                   |
| <b>EXIT LIGHT</b>                         | Inspected                        |
| <b>Battery Pack</b>                       | Inspected                        |
| Condition                                 | 2 - Between Good and Fair        |
| Deficiency                                | No deficiencies recorded         |
| <b>Non Battery Pack</b>                   | Inspected                        |
| Condition                                 | 3 - Fair                         |
| Deficiency                                | No deficiencies recorded         |
| <b>EXIT/EMERGENCY LIGHT</b>               | Inspected                        |
| Condition                                 | 2 - Between Good and Fair        |
| Deficiency                                | No deficiencies recorded         |
| <b>CITY FIRE ALARM SYSTEM</b>             | Does not Exist                   |
| <b>FIRE ALARM SYSTEM</b>                  | Inspected                        |
| Replacement Quantity                      | 24,000                           |
| Replacement Uom                           | S.F.                             |
| <b>Bell/Horn</b>                          | Inspected                        |
| Condition                                 | 3 - Fair                         |

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| Question                                     | Response                           |
|--|------------------------------------|
| <b>FIRE ALARM SYSTEM</b>                     |                                    |
| <b>Bell/Horn</b>                             | Inspected                          |
| Deficiency                                   | No deficiencies recorded           |
| <b>Strobe</b>                                | Does not Exist                     |
| <b>Manual Pull Station</b>                   | Inspected                          |
| Condition                                    | 3 - Fair                           |
| Deficiency                                   | No deficiencies recorded           |
| <b>Fan Shutdown Control</b>                  | Does not Exist                     |
| <b>Duct Smoke Detector</b>                   | Does not Exist                     |
| <b>Area Smoke Detector</b>                   | Does not Exist                     |
| <b>CO Detector</b>                           | Does not Exist                     |
| <b>Heat Detector</b>                         | Does not Exist                     |
| <b>Elevator Recall</b>                       | Does not Exist                     |
| <b>Magnetic Door Holder/Contactor</b>        | Does not Exist                     |
| <b>Fused Cutout Panel</b>                    | Inspected                          |
| Condition                                    | 3 - Fair                           |
| Deficiency                                   | No deficiencies recorded           |
| <b>Fire Alarm Digital Communicator</b>       | Does not Exist                     |
| <b>Main Panel</b>                            | Inspected                          |
| <b>Bell At Panel</b>                         | Inspected                          |
| Condition                                    | 3 - Fair                           |
| Deficiency                                   | No deficiencies recorded           |
| <b>Fire Alarm Control Panel (Electronic)</b> | Does not Exist                     |
| <b>Fire Alarm Control Panel (Standard)</b>   | Inspected                          |
| Instance                                     | Room 012                           |
| Instance Condition                           | 3 - Fair                           |
| Instance Quantity                            | 1                                  |
| Instance Quantity Uom                        | EACH                               |
| Instance Manufacturer                        | ACME                               |
| Equipment                                    | N/A                                |
| Capacity/Size Quantity                       | 4                                  |
| Capacity/Size UOM                            | Circuits                           |
| Source of Capacity/Size                      | Inspector Estimate                 |
| Installation Year                            | 1955                               |
| Source of Installation                       | Documented                         |
| Deficiency                                   | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity                          | 24,000                             |
| Quantity Uom                                 | S.F.                               |
| Potential Action                             | MAINTENANCE                        |
| Urgency of Action                            | PRIORITY 2                         |
| Purpose of Action                            | LEVEL 2                            |
| Deficiency Photo1                            | No photo recorded                  |
| Violations                                   | No violations recorded.            |
| Deficiency                                   | BEYOND USEFUL LIFE                 |
| Deficiency Location/Instance                 | Room 012                           |
| Deficiency Quantity                          | 24,000                             |
| Quantity Uom                                 | S.F.                               |
| Potential Action                             | REPLACE                            |
| Urgency of Action                            | PRIORITY 1                         |

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| <b>Question</b>                            | <b>Response</b>                                    |
|--|--|
| <b>FIRE ALARM SYSTEM</b>                   |  |
| <b>Main Panel</b>                          | Inspected  |
| <b>Fire Alarm Control Panel (Standard)</b> |  |
| Purpose of Action                          | LEVEL 2  |
| Deficiency Photo1                          | No photo recorded                                  |
| Violations                                 | No violations recorded.                            |
| <b>Sub-Panel</b>                           | Does not Exist                                     |
| <b>Remote Annunciator</b>                  | Does not Exist                                     |
| <b>Sprinkler Flow/Air Pressure Switch</b>  | Does not Exist                                     |
| <b>Tamper Flow Switch/Chain</b>            | Does not Exist                                     |
| <b>GROUNDING SYSTEM</b>                    | Inspected  |
| Condition                                  | 2 - Between Good and Fair                          |
| Deficiency                                 | No deficiencies recorded                           |
| <b>INTERCOM SYSTEM</b>                     | Inspected  |
| <b>Elevator</b>                            | Inspected  |
| Condition                                  | 2 - Between Good and Fair                          |
| Deficiency                                 | No deficiencies recorded                           |
| <b>Holding Area</b>                        | Does not Exist                                     |
| <b>LAN</b>                                 | Inspected  |
| <b>Local Distribution Frame (I/LDF)</b>    | Does not Exist                                     |
| <b>Main Equipment Rack (MDF)</b>           | Inspected  |
| Condition                                  | 2 - Between Good and Fair                          |
| Deficiency                                 | No deficiencies recorded                           |
| <b>LIGHTNING PROTECTION</b>                | Does not Exist                                     |
| <b>MOTOR CONTROL CENTER</b>                | Does not Exist                                     |
| <b>MOTOR STARTER/CONTACTOR</b>             | Inspected  |
| Condition                                  | 2 - Between Good and Fair                          |
| Deficiency                                 | No deficiencies recorded                           |
| <b>PANEL BOARD</b>                         | Inspected  |
| <b>Fused Disconnect Switch Type</b>        | Does not Exist                                     |
| <b>Fused Knife Switch Type</b>             | Does not Exist                                     |
| <b>Fused Toggle Switch Type</b>            | Does not Exist                                     |
| <b>Molded Case Circuit Breaker Type</b>    | Inspected  |
| Condition                                  | 3 - Fair   |
| Deficiency                                 | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance               | Cafeteria  |
| Deficiency Quantity                        | 1  |
| Quantity Uom                               | EACH   |
| Potential Action                           | MAINTENANCE  |
| Urgency of Action                          | PRIORITY 2   |
| Purpose of Action                          | LEVEL 2  |
| Deficiency Photo1                          | No photo recorded                                  |
| Violations                                 | No violations recorded.                            |
| Deficiency                                 | NO SPARE   |
| Deficiency Location/Instance               | 2nd Floor Corridor - By Room 202                   |
| Deficiency Quantity                        | 1  |
| Quantity Uom                               | EACH   |
| Potential Action                           | REPLACE PANEL BOARD                                |

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| Question                                | Response   |
|---|--|
| <b>PANEL BOARD</b>                      |  |
| <b>Molded Case Circuit Breaker Type</b> |  |
| Urgency of Action                       | PRIORITY 3                                       |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                |
| Violations                              | No violations recorded.                          |
| Deficiency                              | PANEL BOARD BEYOND USEFUL LIFE                   |
| Deficiency Location/Instance            | Kitchen, Cafeteria, Corridor - By Rooms 102, 302 |
| Deficiency Quantity                     | 4  |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE-UPGRADE                                  |
| Urgency of Action                       | PRIORITY 1                                       |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                |
| Violations                              | No violations recorded.                          |
| <b>PUBLIC ADDRESS SYSTEM</b>            |  |
|   | Inspected  |
| Replacement Quantity                    | 24,000   |
| Replacement Uom                         | S.F.   |
| Instance                                | Room 110   |
| Instance Condition                      | 3 - Fair   |
| Instance Quantity                       | 1  |
| Instance Quantity Uom                   | EACH   |
| Model                                   | Bogen  |
| Installation Year                       | 1980   |
| Source of Installation                  | Inspector Estimate                               |
| Deficiency                              | CLOCK NOT OPERATIONAL                            |
| Deficiency Location/Instance            | Classrooms and Corridors                         |
| Deficiency Quantity                     | 24,000   |
| Quantity Uom                            | S.F.   |
| Potential Action                        | REPLACE  |
| Urgency of Action                       | PRIORITY 3                                       |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                |
| Violations                              | No violations recorded.                          |
| Deficiency                              | BEYOND USEFUL LIFE                               |
| Deficiency Location/Instance            | Room 012   |
| Deficiency Quantity                     | 24,000   |
| Quantity Uom                            | S.F.   |
| Potential Action                        | REPLACE  |
| Urgency of Action                       | PRIORITY 1                                       |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                |
| Violations                              | No violations recorded.                          |
| <b>SECURITY</b>                         |  |
|   | Inspected  |
| <b>IPDVS/CCTV System</b>                |  |
|   | Does not Exist                                   |
| <b>Intrusion Alarm System</b>           |  |
|   | Inspected  |
| Replacement Quantity                    | 24,000   |
| Replacement Uom                         | S.F.   |

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| Question                      | Response                  |
|-------------------------------|---------------------------|
| <b>SECURITY</b>               |                           |
| <b>Intrusion Alarm System</b> |                           |
| <b>Central Control Panel</b>  | Inspected                 |
| Instance                      | Room 110                  |
| Instance Condition            | 5 - Poor                  |
| Instance Quantity             | 1                         |
| Instance Quantity Uom         | EACH                      |
| Model                         | Magnum Alert 1008LK       |
| Installation Year             | 1988                      |
| Source of Installation        | Inspector Estimate        |
| Deficiency                    | PANEL NOT OPERATIONAL     |
| Deficiency Quantity           | 24,000                    |
| Quantity Uom                  | S.F.                      |
| Potential Action              | REPLACE SYSTEM            |
| Urgency of Action             | PRIORITY 4                |
| Purpose of Action             | LEVEL 3                   |
| Deficiency Photo              | No photo recorded         |
| Violations                    | No violations recorded.   |
| <b>Infrared Sensor</b>        | Inspected                 |
| Condition                     | 3 - Fair                  |
| Deficiency                    | No deficiencies recorded  |
| <b>Panic Switch</b>           | Does not Exist            |
| <b>Remote Annunciator</b>     | Inspected                 |
| Condition                     | 3 - Fair                  |
| Deficiency                    | No deficiencies recorded  |
| <b>Siren/Strobe</b>           | Inspected                 |
| Condition                     | 3 - Fair                  |
| Deficiency                    | No deficiencies recorded  |
| <b>Ultrasonic Sensor</b>      | Does not Exist            |
| <b>Lighting - Security</b>    | Inspected                 |
| Replacement Quantity          | 8                         |
| Replacement Uom               | EACH                      |
| Condition                     | 2 - Between Good and Fair |
| Deficiency                    | No deficiencies recorded  |
| <b>SERVICE SWITCH</b>         | Inspected                 |
| Instance                      | Room 012                  |
| Instance Condition            | 3 - Fair                  |
| Instance Quantity             | 1                         |
| Instance Quantity Uom         | EACH                      |
| Instance Manufacturer         | Empire Switchboard        |
| Equipment                     | N/A                       |
| Capacity/Size Quantity        | 800                       |
| Capacity/Size UOM             | Amps                      |
| Source of Capacity/Size       | Nameplate                 |
| Installation Year             | 1955                      |
| Source of Installation        | Documented                |
| Deficiency                    | BEYOND USEFUL LIFE        |
| Deficiency Location/Instance  | Room 012                  |
| Deficiency Quantity           | 24,000                    |



**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K776

| <b>Question</b>                         | <b>Response</b>                                    |
|---|--|
| <b>SERVICE SWITCH</b>                   |  |
| Quantity Uom                            | S.F.   |
| Potential Action                        | REPLACE  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                  |
| Violations                              | No violations recorded.                            |
| <b>SWITCHBOARD</b>                      |  |
| Number of Spares                        | Inspected<br>2                                     |
| <b>Air Circuit Breaker Type</b>         | Does not Exist                                     |
| <b>Fused Disconnect Switch Type</b>     | Inspected  |
| Instance                                | Room 012   |
| Instance Condition                      | 3 - Fair   |
| Instance Quantity                       | 1  |
| Instance Quantity Uom                   | EACH   |
| Instance Manufacturer                   | Empire Switchboard                                 |
| Equipment                               | N/A  |
| Capacity/Size Quantity                  | 800  |
| Capacity/Size UOM                       | Amps Total   |
| Capacity/Size2 Quantity                 | 2  |
| Capacity/Size2 UOM                      | Section(S)   |
| Source of Capacity/Size                 | Service Switch Size                                |
| Installation Year                       | 1955   |
| Source of Installation                  | Documented   |
| Deficiency                              | SWITCHBOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Quantity                     | 1  |
| Quantity Uom                            | EACH   |
| Potential Action                        | MAINTENANCE  |
| Urgency of Action                       | PRIORITY 2   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                  |
| Violations                              | No violations recorded.                            |
| Deficiency                              | BEYOND USEFUL LIFE                                 |
| Deficiency Location/Instance            | Room 012   |
| Deficiency Quantity                     | 24,000   |
| Quantity Uom                            | S.F.   |
| Potential Action                        | REPLACE  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded                                  |
| Violations                              | No violations recorded.                            |
| <b>Fused Knife Switch Type</b>          | Does not Exist                                     |
| <b>Molded Case Circuit Breaker Type</b> | Does not Exist                                     |
| <b>TELEPHONE SYSTEM</b>                 |  |
| <b>PBX/Intercom</b>                     | Inspected  |
| Condition                               | 2 - Between Good and Fair                          |
| Deficiency                              | No deficiencies recorded                           |
| <b>Standard</b>                         | Inspected  |

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K776**

| <b>Question</b>         | <b>Response</b>           |
|-------------------------|---------------------------|
| <b>TELEPHONE SYSTEM</b> | Inspected                 |
| <b>Standard</b>         |                           |
| Condition               | 2 - Between Good and Fair |
| Deficiency              | No deficiencies recorded  |
| <b>TRANSFORMER</b>      | Does not Exist            |
| <b>TV SYSTEM</b>        | Does not Exist            |