

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K857

Asset: P.S. 36 ANNEX - BROOKLYN, 2045 LINDEN BLVD, New York, 11207

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|---------------------|--------------------|
| EE : K857 | Electrical | 2017-10-23 12:44 PM | 2017-10-31 3:21 PM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Public Address System (Amplifier, Partial Speakers) |
| | Years: 2015 |
| | Systems: Interior Fluorescent Lighting |
| | Years: 2013 |
| | Systems: Motor Starters |
| | Years: 2009 |
| | Systems: Telephone System, LAN |
| | Years: 2008 |
| | Systems: Intrusion Alarm System, Security Lights |
| | Years: 2004 |
| | Systems: Emergency Light/Exit Light Panel |
| | Years: 1994 |
| | Systems: Partial Molded Case Circuit Breaker Panel Board |
| | Years: 1985, 1995 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded | | | | | | | | |

Inspection

| Question | Response |
|---------------------------------------|---------------------------|
| Electrical | |
| AUDITORIUM | Does not Exist |
| CAFETERIA | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|--|---------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | |
| Instance on 1st Floor | Does not Exist |
| Projection System | |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | |
| Instance on 1st Floor | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Does not Exist | |
| Surface Mounted | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Does not Exist | |
| Lighting Fixture - Incandescent | |
| Does not Exist | |
| Lighting Fixture - LED | |
| Does not Exist | |
| COMPUTER LAB | |
| Inspected | |
| Instance on Room 203 | Inspected |
| Power Panel | No |
| Lighting | |
| Instance on Room 203 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 203 | Inspected |
| Pendant Mounted | |
| Does not Exist | |
| Instance on Room 203 | Does not Exist |
| Surface Mounted | |
| Does not Exist | |
| Instance on Room 203 | Does not Exist |
| Recessed Mounted | |
| Inspected | |
| Instance on Room 203 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 203 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 203 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 203 | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|--|---------------------------|
| COMPUTER LAB | Inspected |
| Raceway With Receptacles | Does not Exist |
| Instance on Room 203 | Does not Exist |
| GYMNASIUM | Does not Exist |
| KITCHEN | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| LIBRARY | Inspected |
| Instance on Room 311 | Inspected |
| Lighting | Inspected |
| Instance on Room 311 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 311 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room 311 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 311 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 311 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 311 | Does not Exist |
| Raceway With Receptacles | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 311 | Does not Exist |
| LOCKER ROOM | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K857

| Question | Response |
|--|----------------------------------|
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Projection System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| SCIENCE DEMO ROOM | Inspected |
| Instance on Room 310 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Lighting | Inspected |
| Instance on Room 310 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 310 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Room 310 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Room 310 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room 310 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|--|---------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on Room 310 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 310 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 310 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 310 | Does not Exist |
| Emergency Gas Shut-Off Valve | Does not Exist |
| Instance on Room 310 | Does not Exist |
| Emergency Shut-Off Power | Does not Exist |
| Instance on Room 310 | Does not Exist |
| Power Supply | Does not Exist |
| Instance on Room 310 | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 42,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K857

| Question | Response |
|---|---|
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Cafeteria |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | By Rooms (207, 216), Room 124, Cafeteria, Multipurpose Room |
| Deficiency Quantity | 9 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Multipurpose Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| CITY FIRE ALARM SYSTEM | Does not Exist |
| FIRE ALARM SYSTEM | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|--|--------------------------|
| FIRE ALARM SYSTEM | |
| Replacement Quantity | 42,000 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Does not Exist |
| Manual Pull Station | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not Exist |
| Duct Smoke Detector | Does not Exist |
| Area Smoke Detector | Does not Exist |
| CO Detector | Does not Exist |
| Heat Detector | Does not Exist |
| Elevator Recall | Does not Exist |
| Magnetic Door Holder/Contactor | Does not Exist |
| Fused Cutout Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Does not Exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ACME |
| Equipment | FIRE ALARM CONTROL BOARD |
| Capacity/Size Quantity | 4 |
| Capacity/Size UOM | Circuits |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Sub-Panel | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|---|--|
| FIRE ALARM SYSTEM | Inspected |
| Remote Annunciator | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Does not Exist |
| Tamper Flow Switch/Chain | Inaccessible |
| GROUNDING SYSTEM | Inaccessible |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not Exist |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Does not Exist |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Room 217 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | Rooms (217, 219), Kitchen |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | By Room 119, Room 217 |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|---|--------------------------------|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Rooms (217, 319), Kitchen |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 42,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Rauland Telecenter |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Does not Exist |
| Intrusion Alarm System | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|-------------------------------|--|
| SECURITY | |
| Intrusion Alarm System | |
| Replacement Quantity | 42,000 |
| Replacement Uom | S.F. |
| Central Control Panel | |
| | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128B |
| Installation Year | 2004 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | |
| | Does not Exist |
| Lighting - Security | |
| | Inspected |
| Replacement Quantity | 6 |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Location/Instance | Wall Facing back Walkway |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SERVICE SWITCH | |
| | Inspected |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |
| Equipment | Air AC |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K857

| Question | Response |
|------------------------------|--|
| SERVICE SWITCH | |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |
| Equipment | N/A |
| Capacity/Size Quantity | 200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |
| Equipment | Power Panel #6 Disconnect Switch |
| Capacity/Size Quantity | 200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K857

| Question | Response |
|------------------------------|--|
| SERVICE SWITCH | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |
| Equipment | AC |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |
| Equipment | L.P. 2nd and 3rd Floor |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room - Room inside Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Delta Metal Product |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K857

| Question | Response |
|------------------------------|---------------------------|
| SERVICE SWITCH | |
| Equipment | L.P. |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1973 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 42,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SWITCHBOARD | Does not Exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not Exist |
| TV SYSTEM | Inspected |
| Cable System Exist? | Yes |
| Operational? | Yes |
| Main Equipment Rack | Does not Exist |