

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

School: P.S. 96 - MANHATTAN, 216 EAST 120 STREET, MANHATTAN, NY, 10035

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 612 | MECHANICAL | 2018-12-07 11:54AM | 2019-06-11 10:45AM |

Asset Data

| Question | Answer |
|--|--|
| Have any Systems/Major Building Components been upgraded? | Systems: Climate Control System: Air Compressor, Refrigerated Air Dryer, Pneumatic PRV Station Years: 2008 Systems: Science Lab Years: 2009 Systems: Domestic Hot Water Remote Storage Tank; Kitchen - Grease Trap Years: 2011 Systems: MDF Room - Dedicated A/C Equipment (1 of 2, DX Split System) Years: 2016 Systems: Climate Control System: Temperature Control Thermostats, Terminal Unit Control Valves (~50%) Years: 2014 Systems: Boilers re-tubed; Kitchen - Hood Fire Suppression System Years: 2015 Systems: Steam Condensate Return Pumping Systems, Terminal Unit Thermostatic Traps, F&T/Steam Drip Traps, Wet Sprinkler Alarm Valve Assembly Years: 2018 Systems: Sump Pumps (2 of 3); MDF Room - Dedicated A/C Equipment (1 of 2, water-cooled PTAC); Boiler Safety Valves (2 of 4) for Boiler #2 Years: 2013 |
| Are there fuel tanks? | Yes |
| Total # of above ground tanks | 2 |
| Total capacity of all above ground tanks in gal. | 15,000 |
| Total # of below ground tanks | 0 |
| Total capacity of all below ground tanks in gal. | 0 |
| Total # of water main service entries to the asset | 2 |
| MERs/Fan Rooms Locations | Basement - Basement MER, Boiler Room Mechanical Area; 1st Floor - Cafeteria MER |
| Are there any spaces with Missing or Defective CO Detectors? | Boiler Room, Kitchen |
| Are there any Emergency Stop Switches with Missing Hammers? | Component: Boiler Room Mechanical Area near Ash Hoist Location: Boiler Emergency Stop Switch |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image | |
|------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|--|
| | | No condition recorded | | | | | | |

Inspection

| Question | Response |
|---|--------------------------|
| Mechanical | |
| AIR CONDITIONING | Does not exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Does not exist |
| CLIMATE CONTROL SYSTEM | Inspected |
| BMS | Does not exist |
| Electric System | Does not exist |
| Hybrid System | Does not exist |
| Pneumatic System | Inspected |
| Instance | Throughout |
| Instance Condition | 2- Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|---|---|
| CLIMATE CONTROL SYSTEM | |
| Pneumatic System | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 81-100% |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL THERMOSTAT |
| Deficiency Location/Instance | Rooms 133, 223, 307, 309, 311 and other locations |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| COMPACTOR | Does not exist |
| CONVEYING | Does not exist |
| DOMESTIC WATER SYSTEM | Inspected |
| Domestic Cold Water System | |
| Gravity System | |
| | Does not exist |
| Pressure Booster System | |
| | Does not exist |
| Water Service | |
| Instance | Basement - Sprinkler Valve Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Deficiency | WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE |
| Deficiency Location/Instance | Basement - Sprinkler Valve Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | WATER MAIN:DEFECTIVE ISOLATION VALVE |
| Deficiency Location/Instance | Basement - Sprinkler Valve Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Boiler Room Mechanical Area - By 119th Street |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Deficiency | WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE |
| Deficiency Location/Instance | Boiler Room Mechanical Area - By 119th Street |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Domestic Hot Water System | |
| | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|---|--|
| DOMESTIC WATER SYSTEM | |
| Domestic Hot Water System | |
| Domestic Hot Water Remote Storage Tank | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Domestic Water Heat Exchanger | Inspected |
| Condition | 3- Fair |
| Deficiency | NOT IN USE |
| Deficiency Location/Instance | Boiler Room Mechanical Area |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | NO ACTION |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 1 |
| Violations | No violations recorded |
| Electric Domestic Water Heater | Does not exist |
| Gas Fired Domestic Water Heater | Inspected |
| Instance | Boiler Room Mechanical Area |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Laars |
| EquipmentId | N/A |
| Capacity/Size Quantity | 625 |
| Capacity/Size UOM | MBH Input |
| Capacity/Size 2 Quantity | 0 |
| Capacity/Size 2 UOM | Gallons |
| Source of Capacity/Size | Documented |
| Installation Year | 1981 |
| Source of Installation Year | Inspector Estimate |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room Mechanical Area |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Oil Fired Domestic Water Heater | Does not exist |
| Domestic Water Distribution Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | |
| Interior Storm Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not exist |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS |
| Deficiency Location/Instance | Boiler Room Mechanical Area near Incinerator |
| Deficiency Quantity | 20 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|--|---|
| DRAIN/WASTE/VENT AND STORM SYSTEM | |
| Sewage/Waste/Vent Piping | |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Sump Pump | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | |
| Does not exist | |
| Enclosed IDF Room | |
| Instance on Rooms 101, 324 | Inspected |
| Dedicated A/C Equipment | |
| Instance on Rooms 101, 324 | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | DOES NOT EXIST |
| Deficiency Location/Instance | Rooms 101, 324 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| FIXTURES | |
| Inspected | |
| Staff And Other | |
| Inspected | |
| Janitor Sink | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Toilet | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Urinal | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Student | |
| Inspected | |
| Drinking Fountain | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.) |
| Deficiency Location/Instance | Girl's Toilet Room 312 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Locker Room Shower | |
| Does not exist | |
| Sink And Fountain Combo Unit | |
| Inspected | |
| Condition | 4- Between Fair and Poor |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|--|---|
| FIXTURES | |
| Student | |
| Sink And Fountain Combo Unit | |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.) |
| Deficiency Location/Instance | Rooms 226, 308, 310, 323, 326 and other locations |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Toilet | Inspected |
| Condition | 3- Fair |
| Deficiency | CLOGGED/LEAKING |
| Deficiency Location/Instance | Girl's Toilet Room 212 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Urinal | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GAS FIRED FURNACE | |
| | Does not exist |
| GAS SERVICE | |
| | Inspected |
| CO/Gas Leak Detection | |
| | Does not exist |
| Gas Distribution Piping | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Exhaust Fan | |
| | Does not exist |
| Gas Meter Room Vent | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Gas Pressure Booster | |
| | Does not exist |
| HEATING | |
| | Inspected |
| Heating Coil In Ductwork | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hydronic Heating | |
| | Does not exist |
| Radiator/Convactor/Fin Tube | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam Heating | |
| | Inspected |
| F&T/Steam Drip Trap | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| MER Steam and Condensate Piping | |
| Condition | 3- Fair |
| Deficiency | DAMAGED/MISSING INSULATION |
| Deficiency Location/Instance | Basement MER @ Gymnasium SF |
| Deficiency Quantity | 20 |
| Quantity Uom | L.F. |

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Mechanical Inspection

M096

| Question | Response |
|--|--|
| HEATING | |
| Steam Heating | |
| MER Steam and Condensate Piping | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Steam Condensate Return Piping | |
| Condition | Inspected |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Pumping System | |
| Condition | Inspected |
| Deficiency | 1- Good |
| Steam Piping | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| Terminal Unit Thermostatic Trap | |
| Condition | Inspected |
| Deficiency | 1- Good |
| Steam supplied by External Sources | |
| Unit Heater/Cabinet Heater | Does not exist |
| HEATING PLANT | |
| Replacement Quantity | 9,440 |
| Replacement Uom | MBH NET |
| Instance on Basement | Inspected |
| Burner Type | Oil |
| Heating Plant Oil Number | 4 |
| Boiler Auxiliaries | |
| Instance on Basement | Inspected |
| Boiler Auxiliary Piping | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Emergency Stop Switch | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | MISSING HAMMER |
| Deficiency Location/Instance | Boiler Room Mechanical Area near Ash Hoist |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Boiler Feedwater System | |
| Instance on Basement | Does not exist |
| Boiler Feedwater Treatment(Automatic) | |
| Instance on Basement | Does not exist |
| Boiler Flue Exhaust | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Make-up Water Backflow Preventer | |
| Instance on Basement | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|--|----------------------------|
| HEATING PLANT | |
| Boiler Auxiliaries | |
| Boiler Room Steam And Condensate Piping | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Safety Valve | |
| Instance on Basement | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Boiler System | |
| Instance on Basement | Inspected |
| Coal-fired Boiler | |
| Instance on Basement | Does not exist |
| Hot Water Boiler | |
| Instance on Basement | Does not exist |
| Modular Boiler | |
| Instance on Basement | Does not exist |
| Steam Boiler | |
| Instance on Basement | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 4,720 |
| Instance Quantity Uom | MBH NET |
| Manufacturer | Federal Boiler Company |
| EquipmentId | 50994-1 |
| Capacity/Size Quantity | 4720 |
| Capacity/Size UOM | MBH Net |
| Source of Capacity/Size | Documented |
| Installation Year | 1964 |
| Source of Installation Year | Documented |
| Deficiency | DAMAGED/MISSING INSULATION |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 4,720 |
| Instance Quantity Uom | MBH NET |
| Manufacturer | Federal Boiler Company |
| EquipmentId | 50994-2 |
| Capacity/Size Quantity | 4720 |
| Capacity/Size UOM | MBH Net |
| Source of Capacity/Size | Documented |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|--|--------------------------------|
| HEATING PLANT | |
| Boiler System | |
| Steam Boiler | |
| Installation Year | 1964 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fuel System | |
| Instance on Basement | Inspected |
| Boiler Fresh Air Louver/Damper | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | DEFECTIVE ACTUATOR |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Burner/Burner Control Panel | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | OIL BURNER:DEFECTIVE |
| Deficiency Location/Instance | Boiler Room @ Boiler #1 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fuel Oil Storage/Supply System | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | FUEL OIL LEVEL GAUGE:DEFECTIVE |
| Deficiency Location/Instance | Boiler Room Mechanical Area |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Gas Trains And Vent At The Boiler | |
| Instance on Basement | Does not exist |
| KITCHEN | |
| Instance on 1st Floor | Inspected |
| CO Detector | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|--------------------------------------|--------------------------|
| KITCHEN | |
| CO Detector | |
| Deficiency | DEFECTIVE/MISSING |
| Deficiency Location/Instance | Kitchen |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Gas System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Grease Trap | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Hood | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood Exhaust Ductwork | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood Exhaust Fan | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood Fire Suppression System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Hot Water Temperature Booster | |
| Instance on 1st Floor | Does not exist |
| Kitchen Sink | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| MDF Room | |
| Instance on Room within Room 222 | Inspected |
| Dedicated A/C Equipment | |
| Instance on Room within Room 222 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| SCIENCE DEMO ROOM | |
| | Does not exist |
| SCIENCE LAB | |
| Instance on Room 302 | Inspected |
| Alternative Use | Yes |
| Acid Waste Neutralizing Tank | |
| Instance on Room 302 | Inspected |
| Instance Condition | 2- Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|---|--------------------------|
| SCIENCE LAB | |
| Acid Waste Neutralizing Tank | |
| Deficiency | No deficiencies recorded |
| CO Detector | |
| Instance on Room 302 | Not required |
| Emergency Shower | |
| Instance on Room 302 | Does not exist |
| Eye Wash | |
| Instance on Room 302 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fixed Laboratory Hood | |
| Instance on Room 302 | Does not exist |
| Hood Exhaust Ductwork | |
| Instance on Room 302 | Does not exist |
| Hood Exhaust Fan | |
| Instance on Room 302 | Does not exist |
| Laboratory Sink | |
| Instance on Room 302 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Make-up Air Unit | |
| Instance on Room 302 | Does not exist |
| SCIENCE PREP ROOM | Does not exist |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | Inspected |
| Dry Sprinkler Alarm Valve Assembly | Does not exist |
| Fire Booster Pump Assembly | Does not exist |
| Roof Tank | Does not exist |
| Siamese Connection | Does not exist |
| Sprinkler Head | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sprinkler Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Standpipe System | Does not exist |
| Water Gong | Does not exist |
| Wet Sprinkler Alarm Valve Assembly | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| SWIMMING POOL | Does not exist |
| VENTILATION | Inspected |
| Exhaust Fan | Inspected |
| Condition | 3- Fair |
| Approximate Total # of Fans | 1-25 |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Roof |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Heating And Ventilating Unit | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M096

| Question | Response |
|-------------------------------------|-----------------------------|
| VENTILATION | |
| Heating And Ventilating Unit | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Metal Ductwork | |
| Condition | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE REGISTER/DIFFUSER |
| Deficiency Location/Instance | Gymnasium |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Supply Fan | |
| Condition | Inspected |
| Condition | 3- Fair |
| Approximate Total # of Fans | 1-5 |
| Deficiency | No deficiencies recorded |
| Unit Ventilator | |
| Condition | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |