

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M112

School: P.S. 112 (TANDEM M206) - MANHATTAN, 535 EAST 119 STREET, MANHATTAN, NY, 10035

InspectionId	Inspection Type	Time In	Last Edited
406	MECHANICAL	2018-11-29 08:57AM	2018-11-29 02:16PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	N/A
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Not required
CENTRAL ACID WASTE NEUTRALIZING TANK	Not required
CLIMATE CONTROL SYSTEM	Not required
COMPACTOR	Not required
CONVEYING	Not required
DOMESTIC WATER SYSTEM	Not required
DRAIN/WASTE/VENT AND STORM SYSTEM	Not required
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Not required
Enclosed IDF Room	Not required
FIXTURES	Not required
GAS FIRED FURNACE	Not required
GAS SERVICE	Not required
HEATING	Not required
HEATING PLANT	Not required
KITCHEN	Not required
MDF Room	Not required
SCIENCE DEMO ROOM	Not required
SCIENCE LAB	Not required
SCIENCE PREP ROOM	Not required
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Not required
SWIMMING POOL	Not required
VENTILATION	Not required