

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

School: ELEANOR ROOSEVELT HS - MANHATTAN, 411 EAST 76 STREET, MANHATTAN, NY, 10021

InspectionId	Inspection Type	Time In	Last Edited
519	ELECTRICAL	2018-12-03 11:43AM	2019-04-23 10:15AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency Generator, Public Address System - Additional Speakers Years: Under Construction Systems: All Other Systems And Components Years: 2003 Systems: Telephone System, LAN Years: 2006 Systems: Auditorium - Projection System Years: 2010 Systems: IPDVS/CCTV Years: 2013
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	221, 321, 421, 521

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Local Sound System - Not Connected to Public Address System	N/A	Local Sound System	Auditorium	Israel Santiago	Fireman	No Photo Taken
No	Electrical Room Used as Storage	N/A	Electrical Equipment	Rooms 101, 205, 510	Israel Santiago	Fireman	No Photo Taken
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Room 132	Israel Santiago	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Room 518	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 518	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 518	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 518	Does not exist
Recessed Mounted	
Instance on Room 518	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 518	Does not exist
Lighting Fixture - HID	
Instance on Room 518	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 518	Does not exist
Lighting Fixture - LED	
Instance on Room 518	Does not exist
Raceway With Receptacles	
Instance on Room 518	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room 131
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Tornatech
EquipmentId	Fire Pump Power Transfer Switch
Capacity/Size Quantity	15
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Fire Alarm Transfer Switch
Capacity/Size Quantity	70
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS #2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size Quantity	225
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 510
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS #1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Room 510
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	Under construction
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
FIRE ALARM SYSTEM	
Area Smoke Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	
Condition	Inspected
Deficiency	2- Between Good and Fair
CO Detector	
Condition	No deficiencies recorded
Duct Smoke Detector	
Condition	Does not exist
Deficiency	Inspected
Elevator Recall	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	Inspected
Deficiency	2- Between Good and Fair
Fire Alarm Digital Communicator	
Instance	Inspected
Instance Condition	Room 101
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Ademco
Capacity/Size Quantity	N/A
Capacity/Size UOM	5
Source of Capacity/Size	Zones
Installation Year	Nameplate
Source of Installation Year	2003
Deficiency	Documented
Fused Cutout Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Heat Detector	
Condition	No deficiencies recorded
Deficiency	Inspected
Magnetic Door Holder/Contactor	
Condition	Does not exist
Main Panel	
Condition	Inspected
Bell At Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Fire Alarm Control Panel (Electronic)	
Instance	No deficiencies recorded
Instance Condition	Inspected
Instance Quantity	Room 101
Instance Quantity Uom	2- Between Good and Fair
Manufacturer	1
Model	EACH
EquipmentId	Edwards System Technology
Capacity/Size Quantity	EST 2
Capacity/Size UOM	Fire Alarm Control Panel
Capacity/Size 2 Quantity	18
Capacity/Size 2 UOM	Zones
Source of Capacity/Size	1
Installation Year	Section(s)
	Diagram
	2003

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
KITCHEN	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
LAN	
Local Distribution Frame (I/LDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 511	Inspected
Lighting	
Instance on Room 511	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 511	Inspected
Pendant Mounted	
Instance on Room 511	Does not exist
Recessed Mounted	
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 511	Does not exist
Lighting Fixture - HID	
Instance on Room 511	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 511	Does not exist
Lighting Fixture - LED	
Instance on Room 511	Does not exist
Projection System	
Instance on Room 511	Does not exist
Raceway With Receptacles	
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Does not exist	
LOCKER ROOM	
Instance on 2nd Floor - Boys	Inspected
Alternative Use	No
Instance on 2nd Floor - Girls	Inspected
Alternative Use	No
Lighting	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 2nd Floor - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
Instance on Room 218/219	Inspected
Lighting	
Instance on Room 218/219	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 218/219	Inspected
Pendant Mounted	
Instance on Room 218/219	Does not exist
Recessed Mounted	
Instance on Room 218/219	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 218/219	Does not exist
Lighting Fixture - HID	
Instance on Room 218/219	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 218/219	Does not exist
Lighting Fixture - LED	
Instance on Room 218/219	Does not exist
Local Sound System	
Instance on Room 218/219	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
MULTIPURPOSE ROOM	
Projection System	
Instance on Room 218/219	Does not exist
Theater Lighting System	
Instance on Room 218/219	Does not exist
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
Instance	Room 108
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Rooms 402, 403, 409	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms 402, 403, 409	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 402, 403, 409	Inspected
Pendant Mounted	
Instance on Rooms 402, 403, 409	Does not exist
Recessed Mounted	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 402, 403, 409	Does not exist
Lighting Fixture - HID	
Instance on Rooms 402, 403, 409	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 402, 403, 409	Does not exist
Lighting Fixture - LED	
Instance on Rooms 402, 403, 409	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Instance on Rooms 402, 403, 409	Inspected
Instructor Unit	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 402, 403, 409	Does not exist
SCIENCE LAB	
Instance on Rooms 414, 417	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms 414, 417	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 414, 417	Inspected
Pendant Mounted	
Instance on Rooms 414, 417	Does not exist
Recessed Mounted	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 414, 417	Does not exist
Lighting Fixture - HID	
Instance on Rooms 414, 417	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 414, 417	Does not exist
Lighting Fixture - LED	
Instance on Rooms 414, 417	Does not exist
Power Supply	
Instance on Rooms 414, 417	Inspected
Instructor Unit	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance on Rooms 414, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 414, 417	Does not exist
SCIENCE PREP ROOM	
Instance on Room 415	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 415	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 415	Inspected
Pendant Mounted	
Instance on Room 415	Does not exist
Recessed Mounted	
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 415	Does not exist
Lighting Fixture - HID	
Instance on Room 415	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 415	Does not exist
Lighting Fixture - LED	
Instance on Room 415	Does not exist
Power Supply	
Instance on Room 415	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Room 125
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	
Deficiency	No deficiencies recorded
Panic Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	
Condition	3- Fair
Replacement Quantity	13
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MAIN SWITCH #2
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MAIN SWITCH #3
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	6
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MAIN SWITCH #1
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	DPH-BSMT
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	DPL-BSMT
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Inspected
Instance	Room 131
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Olsun Electric
EquipmentId	N/A
Capacity/Size Quantity	300
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 132
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Olsun Electric
EquipmentId	N/A
Capacity/Size Quantity	750
Capacity/Size UOM	kVA

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M855

Question	Response
TRANSFORMER	
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 510
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded