

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Asset: J.H.S. 190 - QUEENS, 68-17 AUSTIN STREET, New York, 11375

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q190	Electrical	2018-12-12 8:51 AM	2018-12-27 11:00 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Exit Lights (Battery Pack)
	Years: 2016
	Systems: Auditorium (Except Lighting)
	Years: 2014
	Systems: Interior Lighting (Except Library)
	Years: 2013
	Systems: Telephone System, LAN
	Years: 2012
	Systems: Library
	Years: 2010
	Systems: Intercom System (Elevator)
	Years: 2009
	Systems: Service Switch, Switchboard, Fire Alarm System, Fused Disconnect Switch Type Panel Board, Emergency Light/Exit Light Panel, Security Lights, IPDVS/CCTV System, Public Address System (Amplifier)
	Years: 2007
	Systems: Local Sound System, Intrusion Alarm System
	Years: 1998
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1980, 2007, 2013

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Roy Cardoza	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
CAFETERIA	
Lighting	Inspected
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Pendant Mounted	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Surface Mounted	Inspected
Instance on Basement - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Lighting Fixture - HID	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Local Sound System	Inspected
Instance on Basement - Students	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Staff	Does not Exist
Projection System	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
CAFETERIA	Inspected
Theater Lighting System	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Rooms 240, 241	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Rooms 240, 241	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 240, 241	Inspected
Pendant Mounted	Inspected
Instance on Rooms 240, 241	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 240, 241	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 240, 241	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 240, 241	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 240, 241	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 240, 241	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 240, 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	1998
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Scoreboard	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Inspected
Instance on Room 242	Inspected
Lighting	Inspected
Instance on Room 242	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 242	Inspected
Pendant Mounted	Inspected
Instance on Room 242	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 242	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 242	Does not Exist
Lighting Fixture - HID	
Instance on Room 242	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 242	Does not Exist
Lighting Fixture - LED	
Instance on Room 242	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 242	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 242	Does not Exist
LOCKER ROOM	Inspected
Instance on Basement - Boys, 1st Floor - Girls	Inspected
Alternative use	No
Lighting	Inspected
Instance on Basement - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on Basement - Boys, 1st Floor - Girls	Does not Exist
Surface Mounted	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Instance on Basement - Boys, 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on Basement - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Boys, 1st Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	
	Does not Exist
SCIENCE DEMO ROOM	
	Inspected
Instance on Room 250	Inspected
Power Panel Alternative use	No No
Instance on Room 254	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room 254	Inspected
Instance on Room 250	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 254	Inspected
Instance on Room 250	Inspected
Pendant Mounted	
Instance on Room 254	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 250	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Lighting Fixture - HID	
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
SCIENCE DEMO ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Projection System	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
Power Supply	Does not Exist
Instance on Room 254	Does not Exist
Instance on Room 250	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 354	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 354	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 354	Inspected
Pendant Mounted	Inspected
Instance on Room 354	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 354	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 354	Does not Exist
Lighting Fixture - HID	
Instance on Room 354	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 354	Inspected
Pendant Mounted	Does not Exist
Instance on Room 354	Does not Exist
Surface Mounted	Inspected
Instance on Room 354	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 354	Does not Exist
Lighting Fixture - LED	
Instance on Room 354	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 354	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 354	Inspected
Instructor Unit	
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 354	Does not Exist
Meter Demonstration Unit	
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 354	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 352	Inspected
Power Panel Alternative use	No No
Instance on Room 252	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room 252	Inspected
Instance on Room 352	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 252	Inspected
Instance on Room 352	Inspected
Pendant Mounted	Does not Exist
Instance on Room 252	Does not Exist
Instance on Room 352	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 252	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 352	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 252	Does not Exist
Instance on Room 352	Does not Exist
Lighting Fixture - HID	
Instance on Room 252	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Room 352	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 252	Does not Exist
Instance on Room 352	Does not Exist
Lighting Fixture - LED	
Instance on Room 252	Does not Exist
Instance on Room 352	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 252	Does not Exist
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Room 252	Does not Exist
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 252	Does not Exist
Instance on Room 352	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	123,000

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	123,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not Exist
MOTOR CONTROL CENTER	
	Does not Exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	123,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	By Rooms (106, 143, 206, 230, 250, 308, 330, 335, 343), Rooms (140, 152, 254), Gymnasium
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office
Deficiency Quantity	123,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	123,000
Replacement Uom	S.F.
Installation Year	2007
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	123,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1998
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q190

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	16
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	5
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q190

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist