

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q198

Asset: I.S. 198 - QUEENS, 3-65 BEACH 56 STREET, New York, 11692

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q198	Electrical	2018-02-28 8:26 AM	2018-03-07 1:13 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Panel Boards, Fire Alarm System, Auxiliary Signal/Bell System, Grounding System, Lightning Protection
	Years: Under construction
	Systems: Gymnasium (LED Lighting), Partial Emergency Lighting (Non Battery Pack)
	Years: 2015
	Systems: Science Lab - Room 341, Motor Control Center, Service Switch, Switchboard
	Years: 2013
	Systems: Transformers
	Years: 2010, 2013
	Systems: Auditorium (Local Sound System, Projection System), Exit Lights (Battery Pack), Public Address System (Clocks), Telephone System
	Years: 2010
	Systems: Recessed Fluorescent Lighting(Expect Auditorium)
	Years: 2008
	Systems: Computer Lab - Room 323
	Years: 2004
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2000, 2013
	Systems: Intrusion Alarm System, IPDVS/CCTV System
	Years: 2000
	Systems: Interior Fluorescent Lighting (Surface, Pendant), Auditorium (Retrofitted Recessed Fluorescent Lighting, Theater Lighting)
	Years: 1998
	Systems: Emergency Light/Exit Light Panel
	Years: 1997
	Systems: Most Security Lights
	Years: 1995, 2001
	Systems: Public Address System
	Years: 1994

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixutre, Security Lights	Rooms (418, 421), Cafeteria, Bulkhead 2, Canopies by Exits (4, 10)	Richard Cohen	Fireman	Sent to DSF	

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q198

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q198

Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Violations	No violations recorded.
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
	Inspected
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not Exist
Surface Mounted	
	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Local Sound System	
	Inspected
Instance on 1st Floor - Students	Inspected
Installation Year	1990
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	CAFETERIA - 1st Floor - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
CAFETERIA	
Local Sound System	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
Lighting	Inspected
Instance on Room 323	Inspected
Power Panel	Yes
Lighting Fixture - Fluorescent	Inspected
Instance on Room 323	Inspected
Pendant Mounted	Inspected
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 323	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 323	Does not Exist
Lighting Fixture - HID	Does not Exist
Instance on Room 323	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Instance on Room 323	Does not Exist
Lighting Fixture - LED	Does not Exist
Instance on Room 323	Does not Exist
Raceway With Receptacles	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
COMPUTER LAB	Inspected
Raceway With Receptacles	
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	1990
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	CAFETERIA - 1st Floor - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q198

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 237	Inspected
Lighting	
Instance on Room 237	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 237	Inspected
Pendant Mounted	
Instance on Room 237	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 237	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 237	Does not Exist
Lighting Fixture - HID	
Instance on Room 237	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 237	Does not Exist
Lighting Fixture - LED	
Instance on Room 237	Does not Exist
Raceway With Receptacles	
Instance on Room 237	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 237	Does not Exist
LOCKER ROOM	
Instance on 1st Floor, 2nd Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
LOCKER ROOM	
Alternative use	Yes
Lighting	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor, 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor, 2nd Floor	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 341	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 341	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 341	Inspected
Pendant Mounted	Inspected
Instance on Room 341	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 341	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 341	Does not Exist
Lighting Fixture - HID	
Instance on Room 341	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 341	Inspected
Pendant Mounted	Does not Exist
Instance on Room 341	Does not Exist
Surface Mounted	Inspected
Instance on Room 341	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q198

Question	Response
SCIENCE LAB	
Lighting	Inspected
Lighting Fixture - Incandescent	
Recessed Mounted	
Instance on Room 341	Does not Exist
Lighting Fixture - LED	
Instance on Room 341	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 341	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 341	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 341	Does not Exist
Projection System	Does not Exist
Instance on Room 341	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 309	Inaccessible
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Under Construction
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Locker Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	By General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
CITY FIRE ALARM SYSTEM	Inspected
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
FIRE ALARM SYSTEM	Under Construction
GROUNDING SYSTEM	Under Construction
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Under Construction
MOTOR CONTROL CENTER	Inspected
Instance	Chiller Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Fan Room 306 (Boys Bath + Slop Sinks)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	Under Construction
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	116,500
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity Uom	EACH
Model	Rauland FAX 250
Installation Year	1994
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	116,500
Replacement Uom	S.F.
Installation Year	2000
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	116,500
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2000
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not Exist
Lighting - Security	
	Inspected
Replacement Quantity	27

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
SECURITY	
Lighting - Security	
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Canopies facing (Beach Channel Drive, Beach 56th Street)
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room inside Chiller Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	
	Inspected
Instance	Electrical Room inside Chiller Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DPL
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Inspected
Instance	Electrical Room 145
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Hammond
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room inside Chiller Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	N/A
Capacity/Size Quantity	500
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 234
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	15
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room inside Chiller Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Hammond
Equipment	N/A

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q198

Question	Response
TRANSFORMER	
Capacity/Size Quantity	15
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist