

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

**Asset:** P.S. 229 - QUEENS, 67-25 51 ROAD, New York, 11377

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q229	Electrical	2018-11-02 8:33 AM	2018-11-21 9:27 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Interior Lighting - Except (Fluorescent Lighting in Library, New Wing), Partial Emergency Lighting (Non Battery Pack), IPDVS/CCTV System
	Years: 2016
	Systems: Library (Pendant Fluorescent Lighting)
	Years: 2009
	Systems: Auditorium (Theater Lighting System)
	Years: 2008
	Systems: Intrusion Alarm System
	Years: 2006
	Systems: Security Lights
	Years: 1999, 2013
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 1999, 2007
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1999, 2003, 2008
	Systems: Partial Service Switch, Partial Switchboard, Emergency Light/Exit Light Panel, Fire Alarm System (Except Standard Sub-Panel), Public Address System, Local Sound System, New Wing Fluorescent Lighting
	Years: 1999

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Junction Box	Corridor Near Room 256	Keith Hennin	Custodian	Sent to DSF	
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM   Main Panel   Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Keith Hennin	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Missing	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	By Room G45	Keith Hennin	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	New Wing Corridors (Ground, 1st, 2nd Floors)	Keith Hennin	Custodian	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Manual Pull Station	Cafeteria	Keith Hennin	Custodian	Sent to DSF
-----	--	-----	---	-----------	--------------	-----------	-------------

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on Ground Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on Ground Floor	Inspected
Installation Year	1999
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on Ground Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
Instance on Ground Floor	Inspected
<b>Dimming System</b>	
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on Ground Floor - Staff	Inspected
Instance on Ground Floor - Students	Inspected
<b>Lighting</b>	
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Inspected
<b>Pendant Mounted</b>	
Instance on Ground Floor - Staff	Does not Exist
<b>Surface Mounted</b>	
Instance on Ground Floor - Staff	Does not Exist
<b>Recessed Mounted</b>	
Instance on Ground Floor - Staff	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Does not Exist
<b>Pendant Mounted</b>	
Instance on Ground Floor - Students	Does not Exist
<b>Surface Mounted</b>	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on Ground Floor - Students	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Installation Year	1999
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - Staff	Does not Exist
<b>Projection System</b>	
	Does not Exist
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>Theater Lighting System</b>	
	Does not Exist
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	
	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
	Does not Exist
<b>Lighting Fixture - LED</b>	
	Inspected
<b>Pendant Mounted</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
	Does not Exist
<b>Recessed Mounted</b>	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room 125	Inspected
Power Panel	No
Instance on Room 225	Inspected
Power Panel	Yes
Instance on Room 258	Inspected
Power Panel	Yes
<b>Lighting</b>	
	Inspected
Instance on Room 258	Inspected
Instance on Room 225	Inspected
Instance on Room 125	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 258	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 225	Inspected
Instance on Room 125	Inspected
<b>Pendant Mounted</b>	
Instance on Room 258	Does not Exist
Instance on Room 225	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 125	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 258	Does not Exist
Instance on Room 225	Does not Exist
Instance on Room 125	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Does not Exist
Instance on Room 125	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 258	Does not Exist
Instance on Room 225	Does not Exist
Instance on Room 125	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 258	Does not Exist
Instance on Room 225	Does not Exist
Instance on Room 125	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 258	Does not Exist
Instance on Room 225	Does not Exist
Instance on Room 125	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 125	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on Ground Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	Inspected
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on Ground Floor	Inspected
Installation Year	1999
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>KITCHEN</b>	
Instance on Ground Floor	Inspected
<b>Lighting</b>	Inspected
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 223	Inspected
<b>Lighting</b>	Inspected
Instance on Room 223	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 223	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 223	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 223	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 223	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 223	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 223	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 223	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on Ground Floor	Inspected
<b>Lighting</b>	Inspected
Instance on Ground Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Ground Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Ground Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

<b>Question</b>	<b>Response</b>
<b>MULTIPURPOSE ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Ground Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Ground Floor	Does not Exist
<b>Local Sound System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Ground Floor	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

<b>Question</b>	<b>Response</b>
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	110,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	By General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	110,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	3 - Fair
Deficiency	PULL STATION NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Manual Pull Station</b>	Inspected
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fan Shutdown Control</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CONTACTOR MISSING
Deficiency Location/Instance	By Room G45
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONTACTOR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	New Wing Corridors (Ground, 1st, 2nd Floors)
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Cutout Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Fire Control Instruments
Equipment	Fire Alarm Control Panel
Model	7200 Series
Capacity/Size Quantity	36
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	E420729
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	
	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Faraday
Equipment	Duct Detector Control Panel
Model	FireWatch XVI
Capacity/Size Quantity	8
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Standard)</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Sprinkler Alarm Control Board
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1967
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	110,000
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

<b>Question</b>	<b>Response</b>
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	
	Does not Exist
<b>MOTOR CONTROL CENTER</b>	
	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Fan Room 126, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (G1, G13, G25, 101, 109, 121, 122, 129, 201A, 222, 225, 301, 322), Students Cafeteria, Gymnasium
Deficiency Quantity	15
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
	Inspected
Replacement Quantity	110,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA 250
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	
	Inspected
<b>IPDVS/CCTV System</b>	
	Inspected
Replacement Quantity	110,000
Replacement Uom	S.F.
Installation Year	2016
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	110,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2006
Source of Installation	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Infrared Sensor</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Panic Switch</b>	
Condition	5 - Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Principals Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	
Condition	Does not Exist
<b>Lighting - Security</b>	
Replacement Quantity	Inspected
Replacement Uom	35
Condition	EACH
Deficiency	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Walls by Exits (3, 4, 5, 8)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	
Instance	Inspected
Instance Condition	Electrical Room G14
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Lexington
Capacity/Size Quantity	Main Switch 1600 Amp Fuse
Capacity/Size UOM	1,600
Source of Capacity/Size	Amps
Installation Year	Fuse Size
Source of Installation	1967
Deficiency	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G14
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>SERVICE SWITCH</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room G45D
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Service Disconnect
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	1
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room G14
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G14
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room G45D
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q229

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not Exist