

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Asset: P.S./ I.S. 314 - QUEENS, 88-08 164 STREET, New York, 11432

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q314	Electrical	2021-04-08 7:51 AM	2021-04-29 9:30 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components
	Years: 2015

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	Water penetrating a security lighting fixture through canopy.	Security Lighting Fixture	Main Entrance Canopy	Joseph Maneri	Custodian	Sent to DSF	
No	Emergency Generator - Defective Engine Cooling System	The emergency generator is not operational due to defective cooling system.	EMERGENCY GENERATOR SET Diesel	Roof - Outdoor Generator Enclosure	Joseph Maneri	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
Pendant Mounted	
Surface Mounted	
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	
Instance on Room 229	Inspected
Power Panel	No
Lighting	
Inspected	

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q314

Question	Response
COMPUTER LAB	
Lighting	
Instance on Room 229	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 229	Inspected
Pendant Mounted	
Instance on Room 229	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 229	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 229	Does not Exist
Lighting Fixture - HID	
Instance on Room 229	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 229	Does not Exist
Lighting Fixture - LED	
Instance on Room 229	Does not Exist
Raceway With Receptacles	
Instance on Room 229	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
GYMNASIUM	
Lighting	Inspected
Lighting Fixture - LED	
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement	Does not Exist
Scoreboard	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 225	Inspected
Lighting	Inspected
Instance on Room 225	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 225	Inspected
Pendant Mounted	Does not Exist
Instance on Room 225	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 225	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Inspected
Instance on Room 225	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 225	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 225	Does not Exist
Lighting Fixture - LED	
Instance on Room 225	Does not Exist
Raceway With Receptacles	
Instance on Room 225	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 225	Does not Exist
LOCKER ROOM	
Instance on Basement - Boys, Basement - Girls	Inspected
Alternative use	Yes
Lighting	
Instance on Basement - Boys, Basement - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Boys, Basement - Girls	Inspected
Pendant Mounted	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Surface Mounted	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Recessed Mounted	
Instance on Basement - Boys, Basement - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Boys, Basement - Girls	Does not Exist
MULTIPURPOSE ROOM	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	
Instance on 2nd Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Does not Exist	
SCIENCE LAB	
Instance on Room 418	Inspected
Power Panel Alternative use	Yes
Instance on Room 216	Inspected
Power Panel Alternative use	No
Lighting	
Instance on Room 216	Inspected
Instance on Room 418	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
SCIENCE LAB	
Lighting	
Instance on Room 216	Inspected
Instance on Room 418	Inspected
Pendant Mounted	Inspected
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - HID	
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Lighting Fixture - LED	
Instance on Room 216	Inspected
Instance on Room 418	Inspected
Pendant Mounted	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Surface Mounted	Inspected
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
SCIENCE LAB	
Power Supply	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
Projection System	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 420	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 420	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 420	Inspected
Pendant Mounted	Inspected
Instance on Room 420	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 420	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 420	Does not Exist
Lighting Fixture - HID	
Instance on Room 420	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 420	Does not Exist
Lighting Fixture - LED	
Instance on Room 420	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 420	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q314

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	116,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Fire Pump Room C017
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Firetrol
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Emergency Service Room C033
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	Fire Alarm Automatic Transfer Switch - ATS-2 SDP
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Emergency Service Room C033
Instance Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q314

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Emergency Service Room C033
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS-1 ESB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Does not Exist
Diesel	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Generac
Equipment	Emergency Generator
Capacity/Size Quantity	625
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	500
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,804
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE ENGINE COOLING SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
EMERGENCY GENERATOR SET	Inspected
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Basement Corridor by Room C004A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Basement Corridor by Room C018
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	116,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q314

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 3
Capacity/Size Quantity	38
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROL CENTER	
MOTOR STARTER/CONTACTOR	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
Replacement Quantity	116,000

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Uom	S.F.
Instance	Room 215
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	116,000
Replacement Uom	S.F.
Installation Year	2015
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	116,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BPT
Installation Year	2015
Source of Installation	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Infrared Sensor	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Deficiency Location/Instance	Corridors by Rooms (425, 419, 405, 327, 319, 305, 227, 223, 203, 113, 103, C020, C013, C004A), 1st Floor Corridor by Cafeteria, Cafeteria, Kitchen, Exterior Wall facing 164th Street)
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	37
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Fire Pump
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MSB-B
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MSB-A

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	ESB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	SPARE
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	7
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Emergency Service Room C033
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	ESB (Emergency Generator Switchboard)
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Electrical Service Room C032
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MSB-A
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse - Room 502 (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MSB-B
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Instance	Emergency Service Room C033
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	SDP (Emergency Generator Switchboard)
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q314

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist