

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

**Asset:** P.S./ I.S. 314 - QUEENS, 88-08 164 STREET, New York, 11432

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q314	Mechanical	2021-04-08 8:44 AM	2021-04-29 5:13 PM

Asset Data

Question	Answer
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Fire Booster Pump Assembly Room C04
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen, Science Lab 418, Science Prep Room 420
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Defective Fire/Smoke Damper	Defective Fire/Smoke Dampers	VENTILATION   Metal Ductwork	3rd and 4th Floors	Joseph Maneri	Fireman	Sent to DSF	

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Inspected
<b>Absorption Chiller</b>	Does not Exist
<b>Air Cooled Chiller</b>	Does not Exist
<b>Air Cooled Condenser</b>	Does not Exist
<b>Chilled Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Does not Exist
<b>Central Station Air Handler</b>	Inspected
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Seasons.4
Equipment	RTU-CR-2
Capacity/Size Quantity	23,000
Capacity/Size UOM	CFM
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Central Station Air Handler</b>	
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Seasons.4
Equipment	RTU-K/C
Capacity/Size Quantity	12,000
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Seasons.4
Equipment	RTU-CR1
Capacity/Size Quantity	22,000
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Multipurpose Room Roof
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Instance Manufacturer	Seasons.4
Equipment	RTU-GA, RTU-G
Capacity/Size Quantity	12,000
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Multipurpose Room Roof / RTU-GA
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fan Coil Unit</b>	Inspected
Condition	1 - Good
Deficiency	DEFECTIVE

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Fan Coil Unit</b>	
Deficiency Location/Instance	Basement Hallway, Room C04
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Packaged Air Cooled Chiller</b>	
	Inspected
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-1A
Capacity/Size Quantity	150
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	OVER 100 TONS: DEFECTIVE COMPRESSOR
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-2
Capacity/Size Quantity	150
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	OVER 100 TONS: DEFECTIVE COMPRESSOR
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Packaged Air Cooled Chiller</b>	
Violations	No violations recorded.
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Airstack
Equipment	CH-1B
Capacity/Size Quantity	150
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	OVER 100 TONS: DEFECTIVE COMPRESSOR
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Water Cooled Chiller</b>	Does not Exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not Exist
<b>Cooling Coil in Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Cooling Tower</b>	Does not Exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not Exist
<b>Packaged / Rooftop Unit</b>	Does not Exist
<b>Packaged Terminal A/C</b>	Does not Exist
<b>Refrigerant Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not Exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not Exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>CLIMATE CONTROL SYSTEM</b>	
<b>BMS</b>	
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Throughout
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Pneumatic System</b>	Does not Exist
<b>Hybrid System</b>	Does not Exist
<b>Electric System</b>	Does not Exist
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiter</b>	Does not Exist
<b>Elevator</b>	Inspected
Are all the existing elevators operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not Exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Inspected
Are all the existing non-auditorium vertical handicap lifts operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non-auditorium Handicap Lift - Stair</b>	Does not Exist
<b>Ash Hoist</b>	Does not Exist
<b>Sidewalk Elevator</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not Exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Inspected
Instance	Room C016
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Canariis
Equipment	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size2 Quantity	15
Capacity/Size2 UOM	Total Pumps HP

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Cold Water System</b>	
<b>Pressure Booster System</b>	
<b>Electric Pressure Booster System</b>	
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Hydraulic/Pneumatic Booster System</b>	Does not Exist
<b>Water Service</b>	Inspected
Instance	Room C029
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Instance	Room C016
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Domestic Water Heat Exchanger</b>	Does not Exist
<b>Electric Domestic Water Heater</b>	Does not Exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lochinvar
Equipment	N/A
Capacity/Size Quantity	650
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	0
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not Exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Does not Exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not Exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Does not Exist
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not Exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not Exist
<b>Gas Meter Room Vent</b>	Does not Exist
<b>Gas Pressure Booster</b>	Does not Exist
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>GAS SERVICE</b>	
<b>CO/Gas Leak Detection</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>HEATING</b>	
<b>Heating Coil In Ductwork</b>	Does not Exist
<b>Hydronic Heating</b>	Inspected
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	AUXILIARIES: DEFECTIVE EXPANSION TANK
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	AUXILIARIES: DEFECTIVE MAKE-UP GLYCOL/WATER FEEDER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Backflow Preventer</b>	Does not Exist
<b>Hot Water Heat Exchanger</b>	Does not Exist
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Does not Exist
<b>Steam supplied by External Sources</b>	Does not Exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	
Replacement Quantity	9,600
Replacement Uom	MBH Net
Instance on Penthouse	Inspected
Burner Type	Gas
Heating Plant Oil Number	N/A
<b>Boiler Auxiliaries</b>	Inspected
Instance on Penthouse	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Auxiliary Piping</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Flue Exhaust</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Penthouse	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Safety Valve</b>	
Instance on Penthouse	Does not Exist
<b>Boiler System</b>	
Instance on Penthouse	Inspected
<b>Coal-fired Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Hot Water Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Modular Boiler</b>	
Instance on Penthouse	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-01
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE BURNER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Modular Boiler</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-02
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE BURNER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-03
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-04
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	DEFECTIVE BURNER

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Modular Boiler</b>	
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-05
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,600
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	81853-06
Capacity/Size Quantity	1,840
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Steam Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Fuel System</b>	
Instance on Penthouse	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Penthouse	Does not Exist
<b>Fuel Oil Storage/Supply System</b>	
Instance on Penthouse	Does not Exist
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Penthouse	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

<b>Question</b>	<b>Response</b>
<b>Enclosed IDF Room</b>	Inspected
Instance on Room 107	Inspected
Instance on Rooms C025, C034, 309, 409	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Rooms C025, C034, 309, 409	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 107	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 107
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>CO Detector</b>	Inspected
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Gas System</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>KITCHEN</b>	
<b>Hood Exhaust Fan</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Kitchen Sink</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	Inspected
Instance on Room 215	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Room 215	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 418	Inspected
Alternative use	No
Instance on Room 216	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Inspected
Instance on Room 216	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Not Required
Instance on Room 216	Not Required
Instance on Room 418	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Room 418
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Emergency Shower</b>	Does not Exist
Instance on Room 216	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>SCIENCE LAB</b>	
<b>Emergency Shower</b>	Does not Exist
Instance on Room 418	Does not Exist
<b>Eye Wash</b>	Inspected
Instance on Room 216	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
<b>Hood Exhaust Fan</b>	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
<b>Fixed Laboratory Hood</b>	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
<b>Laboratory Sink</b>	Inspected
Instance on Room 216	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 418	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Does not Exist
Instance on Room 216	Does not Exist
Instance on Room 418	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 420	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Instance on Room 420	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Room 420
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Emergency Shower</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Emergency Shower</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Eye Wash</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fixed Laboratory Hood</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	Inspected
Instance on Room 420	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Does not Exist
Instance on Room 420	Does not Exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Dry Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Booster Pump Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Roof Tank</b>	Does not Exist
<b>Siamese Connection</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Inspected
<b>Hose Valve Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Piping</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

Q314

Question	Response
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Standpipe System</b>	Inspected
<b>Piping</b>	
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Water Gong</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Approximate Total # of Fans	1-25
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not Exist
<b>Metal Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	DEFECTIVE FIRE/SMOKE DAMPER
Deficiency Location/Instance	3rd and 4th Floors
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Supply Fan</b>	Does not Exist
<b>Unit Ventilator</b>	Does not Exist