

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**Q410**

**Asset: BEACH CHANNEL HS - Q, 100-00 BEACH CHANNEL DRIVE, New York, 11694**

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q410	Electrical	2018-01-03 8:08 AM	2018-01-24 12:02 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System (Auditorium Stage Sub-Panels, Sprinkler Flow/Air Pressure Switch, Tamper Flow Switch/Chain), Intercom System (Elevator), Panel Boards, Emergency Generator Set, IPDVS/CCTV System, Grounding System, Motor Starters
	Years: Under construction
	Systems: LED Lighting, Partial Emergency Lights (Non Battery Pack)
	Years: 2016
	Systems: Public Address System, Local Sound System (Except Auditorium), Partial Emergency Lighting (Battery Pack), Exit Lights (Battery Pack), Fire Alarm System
	Years: 2015
	Systems: Most Security Lights
	Years: 2011
	Systems: Auditorium (Except Fluorescent and Incandescent Lighting)
	Years: 2009
	Systems: Telephone System
	Years: 2008
	Systems: Interior Fluorescent Lighting, HID Lighting, Intrusion Alarm System
	Years: 1997

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM   Main Panel   Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Joe Gargiulo	Fireman	Sent to DSF	
No	Water Leaks onto Electrical Equipment	N/A	Lighting Switch, Lighting Fixture	Room B356, Room A2-2	Joe Gargiulo	Fireman	Sent to DSF	
Yes	Intercom - Does Not Exist	N/A	Intercom System - Holding/Fire Rescue Area	Rooms B262, B364, E201, E301	Joe Gargiulo	Fireman	Sent to DSF	

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>AUDITORIUM</b>	
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor	Inspected
Instance on 2nd Floor - Staff	Inspected
Instance on 2nd Floor - Students	Inspected
<b>Lighting</b>	
Instance on 2nd Floor - Students	Inspected
Instance on 2nd Floor - Staff	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor - Students	Inspected
Instance on 2nd Floor - Staff	Inspected
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Theater Lighting System</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
Instance on 1st Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
<b>COMPUTER LAB</b>	Inspected
Instance on Room D120	Inspected
Power Panel	No
Instance on Room B158	Inspected
Power Panel	No
Instance on Room D283 A/B	Inspected
Power Panel	Yes
Instance on Room D289	Inspected
Power Panel	No
Instance on Room E303	Inspected
Power Panel	No
Instance on Room C341	Inspected
Power Panel	No
<b>Lighting</b>	Inspected
Instance on Room C341	Inspected
Instance on Room E303	Inspected
Instance on Room D289	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
Instance on Room D283 A/B	Inspected
Instance on Room B158	Inspected
Instance on Room D120	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room C341	Inspected
Instance on Room E303	Inspected
Instance on Room D289	Inspected
Instance on Room D283 A/B	Inspected
Instance on Room B158	Inspected
Instance on Room D120	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room C341	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E303	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D289	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D283 A/B	Does not Exist
Instance on Room B158	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D120	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room C341	Does not Exist
Instance on Room E303	Does not Exist
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room B158	Does not Exist
Instance on Room D120	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room C341	Does not Exist
Instance on Room E303	Does not Exist
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Does not Exist
Instance on Room B158	Does not Exist
Instance on Room D120	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room C341	Does not Exist
Instance on Room E303	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Does not Exist
Instance on Room B158	Does not Exist
Instance on Room D120	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room C341	Does not Exist
Instance on Room E303	Does not Exist
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Does not Exist
Instance on Room B158	Does not Exist
Instance on Room D120	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room C341	Does not Exist
Instance on Room E303	Does not Exist
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Does not Exist
Instance on Room B158	Does not Exist
Instance on Room D120	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room C341	Does not Exist
Instance on Room E303	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D289	Does not Exist
Instance on Room D283 A/B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room B158	Does not Exist
Instance on Room D120	Does not Exist
<b>GYMNASIUM</b>	
Instance on 1st Floor - A/B/C	Inspected
Instance on 1st Floor - F/G	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - F/G	Inspected
Instance on 1st Floor - A/B/C	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - F/G	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - F/G	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - F/G	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>Lighting Fixture - LED</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - F/G	Inspected
Instance on 1st Floor - A/B/C	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - F/G	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - A/B/C	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
	Does not Exist
Instance on 1st Floor - F/G	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>Recessed Mounted</b>	
	Inspected
Instance on 1st Floor - F/G	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - A/B/C	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
	Inspected
Instance on 1st Floor - F/G	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	SPEAKER POORLY PROTECTED FROM PHYSICAL DAMAGE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - A/B/C	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	SPEAKER POORLY PROTECTED FROM PHYSICAL DAMAGE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	
	Does not Exist
Instance on 1st Floor - F/G	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Projection System</b>	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on 1st Floor - F/G	Inspected
<b>Condition</b>	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - A/B/C	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor - F/G	Does not Exist
Instance on 1st Floor - A/B/C	Does not Exist
<b>KITCHEN</b>	
	Inspected
Instance on 1st Floor	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 2nd Floor	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Condition</b>	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor	Inspected
<b>Condition</b>	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Does not Exist
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	
	Inspected
Instance on Room D180	Inspected
<b>Lighting</b>	Inspected
Instance on Room D180	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room D180	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on Room D180	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room D180	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on Room D180	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room D180	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room D180	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room D180	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room D180	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room D180	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	No
Instance on 1st Floor - Pool	Inaccessible
Instance on 2nd Floor - Girls	Inaccessible
<b>Lighting</b>	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Boys	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>LOCKER ROOM</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on 2nd Floor - D/E	Inaccessible
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room D218	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room D222	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room D224	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room D228	Inspected
Power Panel	No
Alternative use	No
Instance on Room D230	Inspected
Power Panel	No
Alternative use	No
Instance on Room E297	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Room E299	Inspected
Power Panel	No
Alternative use	No
Instance on Room E310	Inspected
Power Panel	No
Alternative use	No
Instance on Room D322	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Room D324	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms D325, D327, D328	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room D330	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room D330	Inspected
Instance on Rooms D325, D327, D328	Inspected
Instance on Room D324	Inspected
Instance on Room D322	Inspected
Instance on Room E310	Inspected
Instance on Room E299	Inspected
Instance on Room E297	Inspected
Instance on Room D230	Inspected
Instance on Room D228	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	Inspected
<b>Lighting</b>	
Instance on Room D224	Inspected
Instance on Room D222	Inspected
Instance on Room D218	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room D330	Inspected
Instance on Rooms D325, D327, D328	Inspected
Instance on Room D324	Inspected
Instance on Room D322	Inspected
Instance on Room E310	Inspected
Instance on Room E299	Inspected
Instance on Room E297	Inspected
Instance on Room D230	Inspected
Instance on Room D228	Inspected
Instance on Room D224	Inspected
Instance on Room D222	Inspected
Instance on Room D218	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room D330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms D325, D327, D328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E299	Does not Exist
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room E310	Does not Exist
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E297	Does not Exist
Instance on Room D230	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D224	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D218	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E310	Does not Exist
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E310	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room D330	Inspected
Instance on Rooms D325, D327, D328	Inspected
Instance on Room D324	Inspected
Instance on Room D322	Inspected
Instance on Room E310	Does not Exist
Instance on Room E299	Inspected
Instance on Room E297	Inspected
Instance on Room D230	Inspected
Instance on Room D228	Inspected
Instance on Room D224	Inspected
Instance on Room D222	Inspected
Instance on Room D218	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on Room D330	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms D325, D327, D328	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D324	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D230	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D228	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D224	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D222	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room D218	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E310	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Projection System</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Does not Exist
Instance on Room D322	Does not Exist
Instance on Room E310	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Projection System</b>	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room D330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms D325, D327, D328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D230	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D224	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D218	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room D330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms D325, D327, D328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Emergency Shut-Off Power</b>	
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D230	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D224	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D218	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected
Instance on Room D330	Inspected
Instance on Rooms D325, D327, D328	Inspected
Instance on Room D324	Inspected
Instance on Room D322	Inspected
Instance on Room E310	Inspected
Instance on Room E299	Inspected
Instance on Room E297	Inspected
Instance on Room D230	Inspected
Instance on Room D228	Inspected
Instance on Room D224	Inspected
Instance on Room D222	Inspected
Instance on Room D218	Inspected
<b>Instructor Unit</b>	
Instance on Room D330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms D325, D327, D328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D324	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E299	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E297	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D230	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D228	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D224	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D218	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room D330	Does not Exist
Instance on Rooms D325, D327, D328	Does not Exist
Instance on Room D324	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room D322	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E310	Does not Exist
Instance on Room E299	Does not Exist
Instance on Room E297	Does not Exist
Instance on Room D230	Does not Exist
Instance on Room D228	Does not Exist
Instance on Room D224	Does not Exist
Instance on Room D222	Does not Exist
Instance on Room D218	Does not Exist
<b>SCIENCE LAB</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE LAB</b>	
Instance on Room E106	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room E112	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room E204	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room E212	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room E304	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Rooms E316, D318	Inspected
Power Panel	Yes
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Rooms E316, D318	Inspected
Instance on Room E304	Inspected
Instance on Room E212	Inspected
Instance on Room E204	Inspected
Instance on Room E112	Inspected
Instance on Room E106	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms E316, D318	Inspected
Instance on Room E304	Inspected
Instance on Room E212	Inspected
Instance on Room E204	Inspected
Instance on Room E112	Inspected
Instance on Room E106	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E212	Does not Exist
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Surface Mounted</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E304	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E204	Inspected
Condition	3 - Fair

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency	No deficiencies recorded
Instance on Room E112	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E106	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E304	Does not Exist
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E304	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms E316, D318	Inspected
Instance on Room E304	Does not Exist
Instance on Room E212	Inspected
Instance on Room E204	Does not Exist
Instance on Room E112	Inspected
Instance on Room E106	Does not Exist
<b>Pendant Mounted</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E112	Does not Exist
<b>Surface Mounted</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Violations	No violations recorded.
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room E112	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E112	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E304	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room E112	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E106	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E112	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E106	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Rooms E316, D318	Inspected
Instance on Room E304	Inspected
Instance on Room E212	Inspected
Instance on Room E204	Inspected
Instance on Room E112	Inspected
Instance on Room E106	Inspected
<b>Instructor Unit</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E304	Does not Exist
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Student Unit</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Student Unit</b>	
Deficiency	No deficiencies recorded
Instance on Room E304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E112	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E106	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms E316, D318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E304	Does not Exist
Instance on Room E212	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>Projection System</b>	
Instance on Rooms E316, D318	Does not Exist
Instance on Room E304	Does not Exist
Instance on Room E212	Does not Exist
Instance on Room E204	Does not Exist
Instance on Room E112	Does not Exist
Instance on Room E106	Does not Exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room E108	Inspected
Power Panel Alternative use	No Yes
Instance on Room E208	Inspected
Power Panel Alternative use	Yes No
Instance on Room E306	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	
Instance on Room E306	Inspected
Instance on Room E208	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
Instance on Room E108	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room E306	Inspected
Instance on Room E208	Inspected
Instance on Room E108	Inspected
<b>Pendant Mounted</b>	
Instance on Room E306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E208	Does not Exist
Instance on Room E108	Does not Exist
<b>Surface Mounted</b>	
Instance on Room E306	Does not Exist
Instance on Room E208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E108	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room E306	Does not Exist
Instance on Room E208	Does not Exist
Instance on Room E108	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room E306	Does not Exist
Instance on Room E208	Does not Exist
Instance on Room E108	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room E306	Does not Exist
Instance on Room E208	Does not Exist
Instance on Room E108	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room E306	Does not Exist
Instance on Room E208	Does not Exist
Instance on Room E108	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room E306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E108	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room E306	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Emergency Shut-Off Power</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E108	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Room E306	Inspected
Instance on Room E208	Inspected
Instance on Room E108	Inspected
<b>Instructor Unit</b>	
Instance on Room E306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room E108	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Inspected
Instance on 1st Floor	Under Construction
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	409,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Under Construction
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridors By Rooms (E104, E106)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Staff Cafeteria, Corridors By Rooms (Multipurpose Room, Cafeteria 2nd Floor, B169, C147, G19M, E112), 1st Floor Corridors By Staircases (C, E, F), 1st Floor Corridor By Exit 21, 2nd Floor By Staircase C
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>EXIT LIGHT</b>	Inspected
<b>Non Battery Pack</b>	
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	409,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby, Room A2

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	F.A.C.P. #1, 2
Model	N/A
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	12063435K
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Under Construction
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Under Construction
<b>Tamper Flow Switch/Chain</b>	Under Construction
<b>GROUNDING SYSTEM</b>	Under Construction
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Under Construction
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Under Construction
<b>PANEL BOARD</b>	Under Construction
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	409,000
Replacement Uom	S.F.
Instance	Administrative Office (Room F173)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	Administrative Office (Room F173)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Under Construction
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	409,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1997
Source of Installation	Inspector Estimate
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	126
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room (Inside 1st Floor Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Main Service
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Inside 1st Floor Cafeteria)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room (Inside 1st Floor Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Commercial Power
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Inside 1st Floor Cafeteria)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room (Inside 1st Floor Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	MDP-A, B
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Inside 1st Floor Cafeteria)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room (Inside 1st Floor Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q410

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Inside 1st Floor Cafeteria)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Does not Exist