

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

Q416

Asset: CARDOZO AF - QUEENS, 57-00 223 STREET, New York, 11364

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q416	Mechanical	2017-12-27 8:31 AM	2017-12-28 12:44 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	N/A
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

No condition recorded

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inaccessible
CLIMATE CONTROL SYSTEM	Inaccessible
COMPACTOR	Inaccessible
CONVEYING	Inaccessible
DOMESTIC WATER SYSTEM	Inaccessible
DRAIN/WASTE/VENT AND STORM SYSTEM	Inaccessible
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Inaccessible
FIXTURES	Inaccessible
GAS FIRED FURNACE	Inaccessible
GAS SERVICE	Inaccessible
HEATING	Inaccessible
HEATING PLANT	Inaccessible
Enclosed IDF Room	Inaccessible
MDF Room	Inaccessible
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inaccessible
VENTILATION	Inaccessible