

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Asset: FAR ROCKAWAY HS - Q, 8-21 BAY 25 STREET, New York, 11691

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q465	Electrical	2018-11-05 8:53 AM	2018-11-28 3:41 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Swimming Pool
	Years: Under Construction
	Systems: Exit/Emergency Light
	Years: 2018
	Systems: Gymnasium - West (Scoreboard, Local Sound System)
	Years: 2017
	Systems: Fire Alarm System (Printer), Gymnasium (LED Lighting), Exit Light (Battery Pack), Partial Emergency Lighting (Non Battery Pack), Cafeteria (Surface Fluorescent Lighting)
	Years: 2015
	Systems: Auditorium (Except Local Sound System)
	Years: 2014
	Systems: Public Address System, Telephone System, Auditorium (Local Sound System)
	Years: 2010
	Systems: Intercom System (Elevator)
	Years: 2009
	Systems: Most Motor Starters, Recessed Fluorescent Lighting, Projection System (Science Lab - Room 339/343, Science Demo Room 373)
	Years: 2008
	Systems: Science Demo Room 373
	Years: 2007
	Systems: IPDVS/CCTV System
	Years: 2005
	Systems: Fused Disconnect Switch Type Panel Board, Interior Fluorescent Lighting, Incandescent Lighting
	Years: 2001
	Systems: Intrusion Alarm System, Fire Alarm System (Except Sub-Panels)
	Years: 2000
	Systems: Emergency Light/Exit Light Panel
	Years: 1998
	Systems: Security Lights, Fire Alarm System (Electronic Sub-Panel)
	Years: 1990
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1985, 1998, 2001, 2008, 2016

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

No	Emergency Lighting - Battery Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	Auditorium, Gymnasiums, Cafeteria, Corridors, Staircases	Alan Wagner	Custodian	Sent to DSF
Yes	Fire Alarm System - Not Connected to Central Station	N/A	FIRE ALARM SYSTEM Fire Alarm Digital Communicator	Electrical Room	Nando Holiprosad	Fireman	Sent to DSF
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Alan Wagner	Custodian	Sent to DSF
Yes	Water Leaks onto Electrical Equipment	N/A	Electrical Equipment	Mechanical Room under Swimming Pool	Alan Wagner	Custodian	Sent to DSF
Yes	Exposed Electrical Wires	N/A	Junction Box, Electrical Conduit	Room B44, Corridor by Room B43, Gymnasium - East	Nando Holiprosad	Fireman	Sent to DSF

Inspection

Question

Response

Electrical

AUDITORIUM

Inspected

Instance on 1st Floor

Inspected

House Lighting

Inspected

Does a Chandelier exist?

No

Instance on 1st Floor

Inspected

Lighting Fixture - Fluorescent

Instance on 1st Floor

Inspected

Pendant Mounted

Does not Exist

Instance on 1st Floor

Does not Exist

Surface Mounted

Inspected

Instance on 1st Floor

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Recessed Mounted

Does not Exist

Instance on 1st Floor

Does not Exist

Lighting Fixture - HID

Instance on 1st Floor

Does not Exist

Lighting Fixture - Incandescent

Instance on 1st Floor

Does not Exist

Lighting Fixture - LED

Instance on 1st Floor

Inspected

Pendant Mounted

Inspected

Instance on 1st Floor

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Surface Mounted

Inspected

Instance on 1st Floor

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - LED	
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	
	Inspected
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected
Instance on Basement	Inspected
Lighting	
	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	
	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
	Inspected
Instance on Basement	Inspected
Installation Year	1996
Deficiency	BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
CAFETERIA	
Local Sound System	
Deficiency Location/Instance	CAFETERIA - Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	
	Does not Exist
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not Exist
Lighting Fixture - Incandescent	
	Does not Exist
Lighting Fixture - LED	
	Does not Exist
COMPUTER LAB	
	Inspected
Instance on Room 342	Inspected
Power Panel	Yes
Instance on Rooms 247, 249	Inspected
Power Panel	Yes

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
COMPUTER LAB	
Lighting	Inspected
Instance on Rooms 247, 249	Inspected
Instance on Room 342	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 247, 249	Inspected
Instance on Room 342	Inspected
Pendant Mounted	Inspected
Instance on Rooms 247, 249	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 342	Does not Exist
Surface Mounted	Does not Exist
Instance on Rooms 247, 249	Does not Exist
Instance on Room 342	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Rooms 247, 249	Does not Exist
Instance on Room 342	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 247, 249	Does not Exist
Instance on Room 342	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 247, 249	Does not Exist
Instance on Room 342	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 247, 249	Does not Exist
Instance on Room 342	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 247, 249	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 342	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor - East	Inspected
Instance on 1st Floor - West	Inspected
Lighting	Inspected
Instance on 1st Floor - West	Inspected
Instance on 1st Floor - East	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
Lighting Fixture - Incandescent	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - West	Inspected
Instance on 1st Floor - East	Inspected
Pendant Mounted	
Instance on 1st Floor - West	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - East	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - West	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - East	Does not Exist
Recessed Mounted	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
Local Sound System	
Instance on 1st Floor - West	Inspected
Installation Year	2017
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - East	Does not Exist
Projection System	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
Scoreboard	
Instance on 1st Floor - West	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - East	Does not Exist
Theater Lighting System	
Instance on 1st Floor - West	Does not Exist
Instance on 1st Floor - East	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Inspected
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not Exist
Raceway With Receptacles	Inspected
Instance on 3rd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
LOCKER ROOM	Inspected
Instance on Basement - Boys	Inspected
Alternative use	No
Instance on Stair G/2 - Girls	Inspected
Alternative use	No

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
LOCKER ROOM	
Lighting	Inspected
Instance on Stair G/2 - Girls	Inspected
Instance on Basement - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Stair G/2 - Girls	Inspected
Instance on Basement - Boys	Inspected
Pendant Mounted	Does not Exist
Instance on Stair G/2 - Girls	Does not Exist
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Stair G/2 - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Stair G/2 - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - HID	
Instance on Stair G/2 - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - Incandescent	
Instance on Stair G/2 - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - LED	
Instance on Stair G/2 - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 236	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room 239	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room 243	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 240, 242, 336	Inspected
Power Panel	No
Alternative use	No
Instance on Room 248	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 252, 254	Inspected
Power Panel	No
Alternative use	No

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
SCIENCE DEMO ROOM	
Instance on Room 373	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 373	Inspected
Instance on Rooms 252, 254	Inspected
Instance on Room 248	Inspected
Instance on Rooms 240, 242, 336	Inspected
Instance on Room 243	Inspected
Instance on Room 239	Inspected
Instance on Room 236	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 373	Inspected
Instance on Rooms 252, 254	Inspected
Instance on Room 248	Inspected
Instance on Rooms 240, 242, 336	Inspected
Instance on Room 243	Inspected
Instance on Room 239	Inspected
Instance on Room 236	Inspected
Pendant Mounted	
Instance on Room 373	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 248	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 239	Does not Exist
Instance on Room 236	Does not Exist
Surface Mounted	
Instance on Room 373	Does not Exist
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 239	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not Exist
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 373	Does not Exist
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 239	Does not Exist
Instance on Room 236	Does not Exist
Lighting Fixture - HID	
Instance on Room 373	Does not Exist
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 239	Does not Exist
Instance on Room 236	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 373	Does not Exist
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Inspected
Instance on Room 243	Does not Exist
Instance on Room 239	Does not Exist
Instance on Room 236	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 236	Does not Exist
Surface Mounted	Inspected
Instance on Rooms 240, 242, 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 236	Does not Exist
Lighting Fixture - LED	
Instance on Room 373	Does not Exist
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE DEMO ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Room 239	Does not Exist
Instance on Room 236	Does not Exist
Projection System	Inspected
Instance on Room 373	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Does not Exist
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 239	Does not Exist
Instance on Room 236	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 373	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 248	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 240, 242, 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 239	Does not Exist
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 373	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 248	Does not Exist
Instance on Rooms 240, 242, 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 239	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 373	Inspected
Instance on Rooms 252, 254	Inspected
Instance on Room 248	Inspected
Instance on Rooms 240, 242, 336	Inspected
Instance on Room 243	Inspected
Instance on Room 239	Inspected
Instance on Room 236	Inspected
Instructor Unit	
Instance on Room 373	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 248	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 240, 242, 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 239	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 373	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 254	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 248	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 240, 242, 336	Does not Exist
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 239	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
SCIENCE DEMO ROOM	Inspected
Power Supply	Inspected
Meter Demonstration Unit	
Instance on Room 236	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 244	Inspected
Power Panel Alternative use	Yes No
Instance on Room 245	Inspected
Power Panel Alternative use	No No
Instance on Room 339/343	Inspected
Power Panel Alternative use	Yes No
Lighting	Inspected
Instance on Room 339/343	Inspected
Instance on Room 245	Inspected
Instance on Room 244	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 339/343	Inspected
Instance on Room 245	Inspected
Instance on Room 244	Inspected
Pendant Mounted	Does not Exist
Instance on Room 339/343	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Surface Mounted	Inspected
Instance on Room 339/343	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 339/343	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Lighting Fixture - HID	
Instance on Room 339/343	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 339/343	Does not Exist
Instance on Room 245	Inspected
Instance on Room 244	Inspected
Pendant Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE LAB	Inspected
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Surface Mounted	Inspected
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Lighting Fixture - LED	
Instance on Room 339/343	Does not Exist
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 339/343	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 339/343	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 339/343	Inspected
Instance on Room 245	Inspected
Instance on Room 244	Inspected
Instructor Unit	
Instance on Room 339/343	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 339/343	Does not Exist
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 339/343	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 339/343	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 245	Does not Exist
Instance on Room 244	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 241	Inspected
Power Panel Alternative use	Yes Yes
Instance on Room 244A	Inspected
Power Panel Alternative use	No No
Instance on Room 245A	Inspected
Power Panel Alternative use	Yes No
Instance on Room 339A	Inspected
Power Panel Alternative use	No No
Lighting	
Instance on Room 339A	Inspected
Instance on Room 245A	Inspected
Instance on Room 244A	Inspected
Instance on Room 241	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 339A	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 245A	Inspected
Instance on Room 244A	Inspected
Instance on Room 241	Inspected
Pendant Mounted	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Does not Exist
Instance on Room 244A	Does not Exist
Instance on Room 241	Does not Exist
Surface Mounted	
Instance on Room 339A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Does not Exist
Instance on Room 244A	Does not Exist
Instance on Room 241	Does not Exist
Lighting Fixture - HID	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Does not Exist
Instance on Room 244A	Does not Exist
Instance on Room 241	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Does not Exist
Instance on Room 244A	Does not Exist
Instance on Room 241	Does not Exist
Lighting Fixture - LED	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Does not Exist
Instance on Room 244A	Does not Exist
Instance on Room 241	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 339A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve	
Instance on Room 245A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 339A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 245A	Does not Exist
Instance on Room 244A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 241	Does not Exist
Power Supply	
Instance on Room 339A	Does not Exist
Instance on Room 245A	Inspected
Instance on Room 244A	Inspected
Instance on Room 241	Inspected
Instructor Unit	
Instance on Room 245A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 244A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
Instance on Basement	Under Construction
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Does not Exist	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	227,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	4 - Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Gymnasiums, Cafeteria, Corridors, Staircases
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
EMERGENCY LIGHTING	Inspected
Non Battery Pack	Inspected
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	Corridor by General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	227,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Gymnasium - East
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
FIRE ALARM SYSTEM	
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Radionics
Equipment	Fire Alarm Communicator
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2000
Source of Installation	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Fire Alarm & Systems Technology Inc
Equipment	Fire Alarm Control Panel
Model	IRC - 3
Capacity/Size Quantity	36
Capacity/Size UOM	Zones

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	E476104
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	N/A
Model	N/A
Capacity/Size Quantity	6
Capacity/Size UOM	Zones
Source of Capacity/Size	Diagram
Installation Year	1987
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Equipment	Sprinkler Alarm
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	227,000
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms by (Auditorium, Cafeteria, Library), Corridors by Rooms 226, 328
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Fan Room - Staircase A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Corridor by Rooms B43, 102, 339
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Fan Room - Staircase A, Corridor by Room 102
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement, 1st, 2nd, 3rd Floor Corridors, Cafeteria, Kitchen, Projection Room
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	227,000
Replacement Uom	S.F.
Instance	Room next to Room 272
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	227,000
Replacement Uom	S.F.
Installation Year	2005
Source of Installation	Inspector Estimate
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SECURITY	
IPDVS/CCTV System	Inspected
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	227,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Room 158
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inaccessible
SERVICE SWITCH	
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
SERVICE SWITCH	
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Service B
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Bulldog Electric Product Co.
Equipment	KITCHEN PWR. PNL.
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	Inspected
Number of Spares	3
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q465

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1960
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q465

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist