

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Asset: CAMPUS MAGNET HS (JACKSON) - Q, 207-01 116TH AVENUE, New York, 11411

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q490	Electrical	2018-01-17 7:37 AM	2018-01-25 12:55 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LED Lighting (Classrooms)
	Years: 2017
	Systems: Security Lights
	Years: 2015
	Systems: Exit Lights (Battery Pack), Auditorium (Projection System)
	Years: 2014
	Systems: Cafeteria (Local Sound System)
	Years: 2012
	Systems: Intrusion Alarm System (Except Siren), Library
	Years: 2011
	Systems: Public Address System (Amplifier)
	Years: 2010
	Systems: IPDVS/CCTV System, Boys Gymnasium (Scoreboard)
	Years: 2009
	Systems: Auditorium (Local Sound System, Theater Lighting System, Surface Fluorescent Lighting)
	Years: 2008
	Systems: Science Lab - Room 347 (Incandescent Lighting)
	Years: 2006
	Systems: Science Rooms (Incandescent Lighting), Fire Alarm System (Elevator Recall, Fan Shutdown Control, Duct Smoke Detector)
	Years: 2003
	Systems: HID Lighting
	Years: 2002
	Systems: Recessed Fluorescent Lighting (Except Kitchen)
	Years: 1997, 2003, 2010
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1997, 2003, 2006, 2011
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 1995, 2001
	Systems: Emergency Light/Exit Light Panel
	Years: 1995
	Systems: Interior Fluorescent Lighting
	Years: 1994
	Systems: Fire Alarm System
	Years: 1992

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

No	Emergency Lighting - Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	Corridors (1st, 2nd, 3rd Floors), Girls Locker Room, Girls Shower Room, Cafeteria, Auditorium, Library	Tim Joyce	Fireman	Sent to DSF
Yes	Fire Alarm System - Defective	The contractor was working on the problem at the inspection time.	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Tim Joyce	Fireman	Sent to DSF
Yes	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM Elevator	Elevator- Device ID: 4P956	Tim Joyce	Fireman	Sent to DSF

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	Yes
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - HID	
Recessed Mounted	
Violations	No violations recorded.
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2008
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	2012
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	Yes
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Recessed Mounted	Does not Exist
COMPUTER LAB	
Instance on Rooms 321, 325	Inspected
Power Panel	Yes
Instance on Rooms 203, 222	Inspected
Power Panel	No
Lighting	Inspected
Instance on Rooms 203, 222	Inspected
Instance on Rooms 321, 325	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 203, 222	Inspected
Instance on Rooms 321, 325	Inspected
Pendant Mounted	
Instance on Rooms 203, 222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 321, 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 203, 222	Does not Exist
Instance on Rooms 321, 325	Does not Exist
Recessed Mounted	
Instance on Rooms 203, 222	Does not Exist
Instance on Rooms 321, 325	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 203, 222	Does not Exist
Instance on Rooms 321, 325	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 203, 222	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Rooms 321, 325	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 203, 222	Does not Exist
Instance on Rooms 321, 325	Does not Exist
Raceway With Receptacles	
Instance on Rooms 203, 222	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 321, 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
Lighting	
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Pendant Mounted	
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Recessed Mounted	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Local Sound System	
Instance on 1st Floor - Boys	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
GYMNASIUM	
Local Sound System	
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Girls	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Scoreboard	Inspected
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 300	Inspected
Lighting	
Instance on Room 300	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 300	Inspected
Pendant Mounted	
Instance on Room 300	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 300	Does not Exist
Recessed Mounted	
Instance on Room 300	Does not Exist
Lighting Fixture - HID	
Instance on Room 300	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 300	Does not Exist
Lighting Fixture - LED	
Instance on Room 300	Does not Exist
Raceway With Receptacles	
Instance on Room 300	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 300	Does not Exist
LOCKER ROOM	
Instance on Basement - Boys, Basement - Girls	Inspected
Alternative use	No
Lighting	
Instance on Basement - Boys, Basement - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Boys, Basement - Girls	Inspected
Pendant Mounted	
Instance on Basement - Boys, Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Boys, Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
Lighting Fixture - HID	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys, Basement - Girls	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Boys, Basement - Girls	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 231	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 229, 238	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE DEMO ROOM	
Power Panel	No
Alternative use	No
Instance on Room 331	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Instance on Room 331	Inspected
Instance on Rooms 229, 238	Inspected
Instance on Room 231	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Instance on Room 331	Inspected
Instance on Rooms 229, 238	Inspected
Instance on Room 231	Inspected
Pendant Mounted	Inspected
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 138, 139, 141, 247, 338A	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 331	Inspected
Instance on Rooms 229, 238	Inspected
Instance on Room 231	Inspected
Pendant Mounted	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Surface Mounted	
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Projection System	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Does not Exist
Instance on Room 231	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Instance on Room 331	Inspected
Instance on Rooms 229, 238	Inspected
Instance on Room 231	Inspected
Instructor Unit	
Instance on Rooms 138, 139, 141, 247, 338A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 138, 139, 141, 247, 338A	Does not Exist
Instance on Room 331	Does not Exist
Instance on Rooms 229, 238	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 231	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	Inspected
Instance on Room 347	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 140, 240, 340	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE LAB	
Power Panel	Yes
Alternative use	No
Instance on Room 241	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 241	Inspected
Instance on Rooms 140, 240, 340	Inspected
Instance on Room 347	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 241	Inspected
Instance on Rooms 140, 240, 340	Inspected
Instance on Room 347	Inspected
Pendant Mounted	Inspected
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Lighting Fixture - HID	
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 241	Inspected
Instance on Rooms 140, 240, 340	Inspected
Instance on Room 347	Inspected
Pendant Mounted	Does not Exist
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Surface Mounted	Inspected
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Lighting Fixture - LED	
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 241	Inspected
Instance on Rooms 140, 240, 340	Inspected
Instance on Room 347	Inspected
Instructor Unit	
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Does not Exist
Meter Demonstration Unit	
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Does not Exist
Projection System	
Instance on Room 241	Does not Exist
Instance on Rooms 140, 240, 340	Does not Exist
Instance on Room 347	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 135A	Inspected
Power Panel Alternative use	No No
Instance on Room 140A	Inspected
Power Panel Alternative use	Yes No
Instance on Room 238A	Inspected
Power Panel Alternative use	No Yes
Instance on Room 336B	Inspected
Power Panel Alternative use	No Yes
Instance on Room 239A	Inspected
Power Panel Alternative use	Yes No
Lighting	
Instance on Room 239A	Inspected
Instance on Room 336B	Inspected
Instance on Room 238A	Inspected
Instance on Room 140A	Inspected
Instance on Room 135A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 239A	Inspected
Instance on Room 336B	Inspected
Instance on Room 238A	Inspected
Instance on Room 140A	Inspected
Instance on Room 135A	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 238A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 135A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 239A	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Does not Exist
Instance on Room 135A	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 239A	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Does not Exist
Instance on Room 135A	Does not Exist
Lighting Fixture - HID	
Instance on Room 239A	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Does not Exist
Instance on Room 135A	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 239A	Inspected
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Does not Exist
Instance on Room 135A	Does not Exist
Pendant Mounted	Does not Exist
Instance on Room 239A	Does not Exist
Surface Mounted	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Incandescent	
Recessed Mounted	Does not Exist
Instance on Room 239A	Does not Exist
Lighting Fixture - LED	
Instance on Room 239A	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Does not Exist
Instance on Room 135A	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 238A	Does not Exist
Instance on Room 140A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 135A	Does not Exist
Emergency Shut-Off Power	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 135A	Does not Exist
Power Supply	Inspected
Instance on Room 239A	Inspected
Instance on Room 336B	Does not Exist
Instance on Room 238A	Does not Exist
Instance on Room 140A	Inspected
Instance on Room 135A	Does not Exist
Instructor Unit	
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
Instance on Basement	Inspected
Lighting	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SWIMMING POOL	
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Does not Exist
Scoreboard	
Instance on Basement	Does not Exist
TOILET ROOM - STAFF	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
TOILET ROOM - STUDENT	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	260,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	4 - Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridors (1st, 2nd, 3rd Floors), Girls Locker Room, Girls Shower Room, Cafeteria, Auditorium, Library
Deficiency Quantity	44
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	260,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	By Rooms (B2, B12, B25, 110, 115, 126, 135, 141, 145, 151, 225A, 229, 243, 326, 345, Boys Gymnasium), Basement Stair M, Girls Gymnasium, Boys Gymnasium, Cafeteria, Boiler Room, Swimming Pool Mechanical Room
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
FIRE ALARM SYSTEM	
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Fire Command Station
Model	XP Series
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1992
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	E450056
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	N/A
Model	N/A
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1992
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Panel	Inspected
Condition	4 - Between Fair and Poor
Deficiency	PANEL NOT OPERATIONAL
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	3 - Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator- Device ID: 4P956
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	PVT587840
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Swimming Pool Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Swimming Pool Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Swimming Pool Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	By Room 239A
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Girls Shower Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms (B3, 300, 323), Kitchen, Cafeteria
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (B12, B19, B30A, 106, 125, 110B, 123, 149, 131, 139, 239A, 231, 249, 223, 210B, 206, 312, 347, 339A, 334B, 331, Multipurpose Room, Boys Gymnasium), Library Mechanical Room, Electrical Room, Boiler Room, Cafeteria, Kitchen, Mechanical Room B10, Girls Gymnasium Mechanical Room, Girls Shower Room
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	260,000
Replacement Uom	S.F.
Instance	General Office - Room 127
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland FAX 250
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Location/Instance	Classrooms and Corridors, Gymnasium, Cafeteria
Deficiency Quantity	260,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 127
Deficiency Quantity	260,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
SECURITY	Inspected
<hr/>	
IPDVS/CCTV System	Inspected
Replacement Quantity	260,000
Replacement Uom	S.F.
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<hr/>	
Intrusion Alarm System	Inspected
Replacement Quantity	260,000
Replacement Uom	S.F.
<hr/>	
Central Control Panel	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2011
Source of Installation	Documented
Deficiency	No deficiencies recorded
<hr/>	
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<hr/>	
Panic Switch	Does not Exist
<hr/>	
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<hr/>	
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<hr/>	
Ultrasonic Sensor	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q490

Question	Response
SECURITY	
Lighting - Security	Inspected
Replacement Quantity	60
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Main Service Switch
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 127
Deficiency Quantity	260,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	7
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 127
Deficiency Quantity	260,000
Quantity Uom	S.F.
Potential Action	REPLACE

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q490

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	
	Does not Exist