

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

Asset: SKILLMAN HIGH SCHOOL - QUEENS, 24-30 SKILLMAN AVENUE, New York, 11101

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : Q667 | Electrical | 2018-11-29 8:07 AM | 2019-05-31 1:25 PM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: LAN |
| | Years: 2016 |
| | Systems: All Other Electrical Systems and Components |
| | Years: 2005 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---|-----------------------|--|-------------------------------|--------------------|-----------------|-------------|------------|
| No | Fire Alarm System - Components Not Operational | N/A | FIRE ALARM SYSTEM Tamper Flow Switch/Chain | Water/Fire Room 129 | Stephen Oshea | Fireman | Sent to DSF | |
| No | Intercom - Not Connected to Remote Monitoring Station | N/A | INTERCOM SYSTEM Elevator | Elevator - Device ID: 4P11017 | Stephen Oshea | Fireman | Sent to DSF | |

Inspection

| Question | Response |
|--|--------------------------|
| Electrical | |
| AUDITORIUM | Does not Exist |
| CAFETERIA | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q667

| Question | Response |
|--|------------------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor | Inspected |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| COMPUTER LAB | Does not Exist |
| GYMNASIUM | Does not Exist |
| KITCHEN | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q667

| Question | Response |
|--|--------------------------|
| KITCHEN | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not Exist |
| LIBRARY | Inspected |
| Instance on Room 110 | Inspected |
| Lighting | Inspected |
| Instance on Room 110 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 110 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Room 110 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Room 110 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room 110 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 110 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 110 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 110 | Does not Exist |
| Raceway With Receptacles | Does not Exist |
| Instance on Room 110 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 110 | Does not Exist |
| LOCKER ROOM | Does not Exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor, 2nd Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor, 2nd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor, 2nd Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Recessed Mounted | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|--|--------------------------|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on 1st Floor, 2nd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor, 2nd Floor | Inspected |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor, 2nd Floor | Does not Exist |
| SCIENCE DEMO ROOM | Inspected |
| Instance on Rooms 204, 205 | Inspected |
| Power Panel | No |
| Alternative use | Yes |
| Lighting | Inspected |
| Instance on Rooms 204, 205 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 204, 205 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Rooms 204, 205 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Rooms 204, 205 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 204, 205 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Rooms 204, 205 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| Emergency Gas Shut-Off Valve | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| Emergency Shut-Off Power | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q667

| Question | Response |
|---|-------------------------------|
| SCIENCE DEMO ROOM | Inspected |
| Emergency Shut-Off Power | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| Power Supply | Does not Exist |
| Instance on Rooms 204, 205 | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 53,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Inspected |
| Automatic Transfer Switch (ATS) | Inspected |
| Instance | Electrical Closet - Room 111B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Kohler Power Systems |
| Equipment | ATS 1 |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|--|--|
| EMERGENCY GENERATOR SET | |
| Automatic Transfer Switch (ATS) | |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Closet - Room 111B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | ATS 3 (Automatic Transfer Switch for Fire Alarm Control Panel) |
| Capacity/Size Quantity | 70 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Water/Fire Room 129 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Tornatech |
| Equipment | ATS 2 (Sprinkler) |
| Capacity/Size Quantity | 8 |
| Capacity/Size UOM | HP |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Battery Charger | Inspected |
| Instance | Outdoor Generator Enclosure |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | SENS |
| Equipment | Battery Charger |
| Capacity/Size Quantity | 10 |
| Capacity/Size UOM | AmpsDC |
| Capacity/Size2 Quantity | 24 |
| Capacity/Size2 UOM | VDC |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Diesel | Inspected |
| Instance | Outdoor Generator Enclosure |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Kohler Power Systems |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q667

| Question | Response |
|---|---------------------------|
| EMERGENCY GENERATOR SET | |
| Diesel | |
| Equipment | Emergency Generator |
| Capacity/Size Quantity | 169 |
| Capacity/Size UOM | KVA |
| Capacity/Size2 Quantity | 135 |
| Capacity/Size2 UOM | KW |
| Capacity/Size3Quantity | 468 |
| Capacity/Size3 UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Natural Gas | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not Exist |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Does not Exist |
| CITY FIRE ALARM SYSTEM | Does not Exist |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 53,000 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|--|----------------------------|
| FIRE ALARM SYSTEM | |
| Area Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not Exist |
| Heat Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Does not Exist |
| Fused Cutout Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Inspected |
| Instance | MDF Room 124 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Fire Lite |
| Equipment | Fire Control/Communicator |
| Capacity/Size Quantity | 10 |
| Capacity/Size UOM | Zones |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Notifier |
| Equipment | Interior Fire Alarm System |
| Model | NFS - 3030 |
| Capacity/Size Quantity | 24 |
| Capacity/Size UOM | Zones |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Diagram |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|--|--|
| FIRE ALARM SYSTEM | |
| Sub-Panel | Inspected |
| Bell At Panel | Does not Exist |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Notifier |
| Equipment | Purge Control System |
| Model | N/A |
| Capacity/Size Quantity | 24 |
| Capacity/Size UOM | Zones |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not Exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not Exist |
| Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | SWITCH NOT OPERATIONAL |
| Deficiency Location/Instance | Water/Fire Room 129 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | E479016 |
| GROUNDING SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 3 - Fair |
| Deficiency | NOT CONNECTED TO REMOTE MONITORING STATION |
| Deficiency Location/Instance | Elevator - Device ID: 4P11017 |
| Deficiency Quantity | 1 |

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q667

| Question | Response |
|---|--|
| INTERCOM SYSTEM | |
| Elevator | |
| Quantity Uom | EACH |
| Potential Action | INSTALL CONNECTION |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Holding Area | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not Exist |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Does not Exist |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 53,000 |
| Replacement Uom | S.F. |
| Instance | MDF Room 124 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Biamp MPA 250 |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | 1st Floor Corridor by Room 100, Custodian's Workshop |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|-------------------------------|---------------------------|
| SECURITY | |
| IPDVS/CCTV System | |
| Replacement Quantity | 53,000 |
| Replacement Uom | S.F. |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | |
| Replacement Quantity | 53,000 |
| Replacement Uom | S.F. |
| Central Control Panel | |
| Instance | Inspected |
| Instance Condition | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128BP |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | |
| Condition | Does not Exist |
| Lighting - Security | |
| Replacement Quantity | Inspected |
| Replacement Quantity | 25 |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | |
| Instance | Inspected |
| Instance | Electrical Room 111 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Atlas |
| Equipment | Main Service Switch |
| Capacity/Size Quantity | 2,000 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|---|-----------------------------------|
| SERVICE SWITCH | Inspected |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | Inspected |
| Number of Spares | 0 |
| Air Circuit Breaker Type | Does not Exist |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room 111 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Atlas Switch |
| Equipment | SERVICE-DIST-SWBD |
| Capacity/Size Quantity | 2,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Instance | Outdoor Generator Enclosure |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Square D |
| Equipment | (Emergency Generator Switchboard) |
| Capacity/Size Quantity | 1,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2005 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not Exist |
| TV SYSTEM | Inspected |
| Cable System Exist? | Yes |
| Operational? | No |
| Main Equipment Rack | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q667

| Question | Response |
|----------------------------|--------------------------|
| TV SYSTEM | |
| Main Equipment Rack | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |