Building Condition Assessment Survey 2021-2022

Electrical Inspection R057

School:	P.S. 57 - STATEN ISLAND, 140 PALMA DRIVE, ST	ATEN ISLAND, NY, 1	0304	
InspectionId	Inspection Type		Time In	Last Edited
4641	ELECTRICAL		2022-03-28 09:28AM	2022-04-12 03:07PN
set Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Exit / Emergency Lights, Partial (Battery Pack), Partial Exit Light Partial Variable Frequency Drive	ts (Battery Pack),
		Years:	2018	
		Systems:	Fire Alarm System (Printer)	
		Years:	2015	
		Systems:	Interior Lighting, Emergency Lig Pack)	ghting (Non Battery
		Years:	2014	
		Systems:	Telephone System	
		Years:	2013	
		Systems:	Emergency DC Standby Battery	Power
		Years:	2012	
		Systems:	Most Security Lighting	
		Years:	2011, 2000	
		Systems:	IPDVS / CCTV System	
		Years:	2010	
		Systems:	Partial Molded Case Circuit Brea	iker Panel Board
		Years:	2009, 2008, 1997	
		Systems:	Partial Service Switch, Partial Sv	vitchboard
		Years:	2009	
		Systems:	Fire Alarm System	
		Years:	2005	
		Systems:	Public Address System, Local So	ound System
		Years:	2004	
		Systems:	Intrusion Alarm System	
		Years:	1995	
Type of Service		Below Gro	ound	
Does Interactive	e Whiteboard (IWB) Exist?	Yes		
	on In Electrical Room?	No		
	O INTERCOMS IN FIRE RESCUE AREAS		_	
Are there any your building	Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holdin		Response No	

Priority Condition

Question

Electrical

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor by Room 335	John Accardo	Fireman	No Photo Taken
Yes	Emergency DC Standby Battery Power - Battery Bank Not Operational	N/A	Emergency DC Standby Battery Power	Basement Crawl Space - Emergency Lighting Room	John Accardo	Fireman	No Photo Taken

Response

Puestion	Response	
ATHLETIC FIELD	Does not exist	
	Does not exist	
AUDITORIUM	T 4.1	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	_
Lighting Fixture - Fluorescent	Y 4.1	_
Instance on 1st Floor	Inspected	
Pendant Mounted		_
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		_
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		_
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Recessed Mounted	2 040 100 0.1100	
Instance on 1st Floor	Inspected	-
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiences recorded	
Instance on 1st Floor	Does not exist	_
	Does not exist	
Local Sound System	Y1	
Instance on 1st Floor	Inspected 3- Fair	
Instance Condition		
Installation Year Source of Installation Year	2004 Documented	
Deficiency	No deficiencies recorded	
	140 deficiencies recorded	
Projection System Instance on 1st Floor	Incurated	
	Inspected 5- Poor	
Instance Condition		
Is the projector on a cart or installed on the ceiling?	Ceiling VIDEO PROJECTOR IS NOT OPERATIONAL	-
Deficiency Deficiency Quantity	VIDEO PROJECTOR IS NOT OPERATIONAL 1	
Quantity Uom	I EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	rvo violations recorded	_
Theater Lighting System Instance on 1st Floor	Inspected	_

Building Condition Assessment Survey 2021-2022

ctrical Inspection	R05/
Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - Incandescent	2000 101 01101
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
	DOGS HOT CAIST
Lighting Fixture - LED Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected

Electrical Inspection Rus

veus inspection	1100
Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Local Sound System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Theater Lighting System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
	Does not exist Does not exist
Lighting Fixture - Incandescent	Inspected
Lighting Fixture - LED Pendant Mounted	Does not exist
	Inspected
Recessed Mounted Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded Does not exist
Surface Mounted	
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	5- Poor
Deficiency Deficiency Location/Instance	BATTERY BANK NOT OPERATIONAL Basement Crawl Space - Emergency Lighting Room

Electrical Inspection	<u> </u>	R057	

trical inspection	R05/
Question	Response
EMERGENCY DC STANDBY BATTERY POWER	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Fire Alarm Digital Communicator	
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2021-2022

estion	Response	
IRE ALARM SYSTEM		
Fused Cutout Panel		
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	CONTACTOR NOT OPERATIONAL	
Deficiency Location/Instance	Corridor by Room 335	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Capacity/Size Quantity	12	
Capacity/Size UOM	Zones	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Diagram	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2021-2022

icui inspection		KU3/
question	Response	
FIRE ALARM SYSTEM		
Strobe		
Deficiency	No deficiencies recorded	
Sub-Panel	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM		
Instance on 1st Floor	Inspected	
Lighting	nispected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	mspecieu	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED Instance on 1st Floor	Turnoctod	
	Inspected	
Pendant Mounted	D	
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	Y 1	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year Source of Installation Year	2004	
	Documented No deficiencies recorded	
Deficiency	No deliciencies recorded	
Projection System	D	
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
KITCHEN		
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	

rical Inspection	n.	RO
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIBRARY		
Instance on Room 215	Inspected	
Lighting	A	
Instance on Room 215	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 215	Inspected	
Pendant Mounted	, A	
Instance on Room 215	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		

Building Condition Assessment Survey 2021-2022

uestion	Response
LIBRARY	
Raceway With Receptacles Deficiency	No deficiencies recorded
i	
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	MCC Roof Exhaust
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate 1975
Installation Year	
Source of Installation Year	Documented Vision Vision Vision Control (Vision Vision Vis
Deficiency	MCC INDICATOR LIGHT NOT OPERATIONAL
Deficiency Quantity	24 FACH
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action Violations	LEVEL 2
	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Boiler Room
	1 EACH
Quantity Uom	EACH DEPLACE
Potential Action	REPLACE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action Violations	No violations recorded
MOTOR STARTER	Inspected
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	VARIABLE FREQUENCY DRIVE NOT OPERATIONAL
Deficiency Location/Instance	Penthouses
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse, Boiler Room, Mechanical Equipment Room below

Building Condition Assessment Survey 2021-2022

estion	Response
ANEL BOARD	
Fused Disconnect Switch Type	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	
	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Auditorium, Corridors by Rooms (106, 131)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action	
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 107
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2004
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
· · · · · · · · · · · · · · · · · · ·	
Deficiency Overtity	Corridor by Room 312K
Deficiency Quantity	1 EACH
Quantity Uom	EACH DEPLACE
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CIENCE DEMO ROOM	Does not exist

Building Condition Assessment Survey 2021-2022

rical Inspection	KU5/
uestion	Response
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 113
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1995
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office - Room 113
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Replacement Quantity	43
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Exterior Canopies
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Exterior Wall Facing Hanover Avenue
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3

Electrical Inspection	R057

	n.	KU57
uestion	Response	
SECURITY		
Lighting - Security		
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E.	
EquipmentId	Main S.W. Power	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1975	
Source of Installation Year	Documented Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance Deficiency Quantity	Electrical Room	
	I EACH	
Quantity Uom Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room 3- Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Manufacturer	I.T.E.	
EquipmentId	Main S.W. Lighting	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1975	
Source of Installation Year	Documented Private Name 1	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH PERMACE	
Potential Action	REPLACE	
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2	
•		
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Manufacturer	I.T.E.	
EquipmentId	Heat Main S. W.	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1975	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	_
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	

Electrical Inspection	RU5/

<u> </u>		
Question	Response	
SERVICE SWITCH		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	All City Switchboard	
Manufacturer	SS #4 AC Panel	
EquipmentId Capacity/Size Quantity	1000	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWIMMING POOL	Does not exist	
SWITCHBOARD	Inspected	
Number of Spares	6	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E. Imperial Corp.	
EquipmentId	LGT. Dist. PNL	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1975	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E. Imperial Corp.	
EquipmentId	Power Dist. PNL	
Capacity/Size Quantity	1200	
Capacity/Size Quantity Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	Amps Total 2	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1975	
Source of Installation Year	Documented	
Source of installation Teal	Documented	

Building Condition Assessment Survey 2021-2022

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	HDB SEC 1, HDP SEC 2
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
ile Validity Version 2.0 (P) Page 14 of 15	Print Data: 6/26/2022

Building Condition Assessment Survey 2021-2022

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist