Asset:	P.S. 1 - BR	ONX, 335 EAS	T 152 STREET,	New York, 104	51			
Inspection Io			1 132 STREET,	11011, 101	<u> </u>	Time In		Last Edited
EE : X00						2017-10-	10 8:35 AM	2017-12-15 4:01
et Data	71 2100011001					2017 10	10 0.00 11.1	2017 12 10 1101
Question					Answer			
Type of Service	ce				Below Grou	nd		
	ve Whiteboard (	IWB) Exist?			Yes			
					No			
Water Penetration in Electrical Room?  Have any Systems/Major Building Components been upgraded?					Yes			
, ,	J		10		Systems:	Auditorium (Proj Sound System)	jection System).	Gymnasium (Local
					Years:	2016		
					Systems:	Intrusion Alarm (Battery Pack)	System, Telepho	one System, Exit Light
					Years:	2015		
					Systems:	Gymnasium (LE	D Lighting)	
					Years:	2014		
					Systems:	IPDVS/CCTV S	ystem	
					Years:	2012		
					Systems:	Gymnasium (Sco (Battery Pack), S		l Emergency Lighting
					Years:	2009		
					Systems:	LAN, Cafeteria (	Projection Syste	em)
					Years:	2007		
					Systems:	Fused Disconnec	t Switch Type F	anel Board
					Years:	2006		
					Systems:	Library		
					Years:	2005		
					Systems:	Interior Fluoresco (Auditorium, Cat		cal Sound System
					Years:	2004		
					Systems:	Partial Molded C	ase Circuit Brea	iker Panel Board
					Years:	1998, 2004, 2006	5	
					Systems:	Emergency Light	t/Exit Light Pan	el
					Years:	1992		
DEDICATEI	) INTERCOMS	S IN FIRE RESC	UE AREAS					
Question					Response			
	Life Rescue As ng Rooms in you	sistance Areas, Fi r building?	re Rescue Areas,		No			
ority Conditi								
riority ondition Exist ast Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
	Emergency Lighting - Not Operational	N/A.	EMERGENCY LIGHTING   Battery Pack	Basement by Stairway (A, E&F, B&C), Basement by Exit 5&6, 1st Floor by Exit (3, 9&10), 1st Floor by Stairway D, By Rooms (142, 158, B7, B10), Gymnasium, Auditorium by	Richard Gallino	Fireman	Sent to DSF	

### **Building Condition Assessment Survey 2017 - 2018**

**Electrical Inspection** 

X001

Local Sound N/A Local Sound Auditorium, Richard Gallion Fireman Sent to DSF System - Not Gymnasium System Connected to Public Address System Inspection Question Response Electrical AUDITORIUM Inspected Instance on 1st Floor Inspected **House Lighting** Inspected Does a Chandelier exist? No Instance on 1st Floor Inspected **Lighting Fixture - Fluorescent** Instance on 1st Floor Inspected **Pendant Mounted** Inspected Instance on 1st Floor Inspected Condition 3 - Fair Deficiency No deficiencies recorded **Surface Mounted** Inspected Instance on 1st Floor Inspected Condition 3 - Fair Deficiency No deficiencies recorded Recessed Mounted Inspected Instance on 1st Floor Inspected Condition 3 - Fair Deficiency LIGHTING FIXTURE BALLAST DEFECTIVE **Deficiency Quantity** 5 Quantity Uom **EACH** REPLACE BALLAST Potential Action PRIORITY 3 Urgency of Action LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded. **Lighting Fixture - HID** Instance on 1st Floor Does not Exist **Lighting Fixture - Incandescent** Instance on 1st Floor Does not Exist **Lighting Fixture - LED** Instance on 1st Floor Does not Exist **Local Sound System** Inspected Instance on 1st Floor Inspected Installation Year 2004 Source of Installation Custodial Staff Condition 3 - Fair NOT CONNECTED TO PUBLIC ADDRESS SYSTEM Deficiency Deficiency Quantity **EACH** Quantity Uom INSTALL CONNECTION Potential Action Urgency of Action PRIORITY 5

estion	Response
UDITORIUM	
Local Sound System	
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Cart
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
AFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2004

trical Inspection		<u> </u>
uestion	Response	
CAFETERIA		
Local Sound System	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Inspected	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System	Does not Exist	
Instance on 1st Floor	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Inspected	
Instance on Room 307	Inspected	
Power Panel	No	
Lighting	Inspected	
Instance on Room 307	Inspected	
	nispected	
Lighting Fixture - Fluorescent	Inamostod	
Instance on Room 307	Inspected	
Pendant Mounted	Does not Exist	
Instance on Room 307	Does not Exist	
Surface Mounted	Inspected	
Instance on Room 307	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Room 307	Does not Exist	
Lighting Fixture - HID		
Instance on Room 307	Does not Exist	
<b>Lighting Fixture - Incandescent</b>		
Instance on Room 307	Does not Exist	
Lighting Fixture - LED		
Instance on Room 307	Does not Exist	
Raceway With Receptacles	Inspected	

trical Inspection	X0
uestion	Response
COMPUTER LAB	Inspected
Raceway With Receptacles	
Instance on Room 307	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
	DOGS HOT EXIST
Lighting Fixture - LED	Invested .
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	2016
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on Basement	Does not Exist
Scoreboard	
Instance on Basement	Inspected
	Inspected
Condition	2 - Between Good and Fair
Deficiency Theorem Lighting System	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected

trical Inspection		X00
uestion	Response	
KITCHEN		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not Exist	
LIBRARY	Inspected	
Instance on Room 255	Inspected	
Lighting	Inspected	
Instance on Room 255	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 255	Inspected	
Pendant Mounted	Inspected	
Instance on Room 255	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Instance on Room 255	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on Room 255	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 255	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 255	Does not Exist	
Lighting Fixture - LED		
Instance on Room 255	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 255	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Inspected	

question	Response	
LIBRARY	Inspected	
Projection System		
Instance on Room 255	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative use	Yes	
Lighting	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
	Does not Exist	
Pendant Mounted		
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	

etrical Inspection	X00
uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	96,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Basement by Stairway (A, E&F, B&C), Basement by Exit 5&6, 1s Floor by Exit (3, 9&10), 1st Floor by Stairway D, By Rooms (142, 158, B7, B10), Gymnasium, Auditorium by Rear Exit
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1

trical Inspection		X001
nestion	Response	
EMERGENCY LIGHTING		
Non Battery Pack		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3 - Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Boiler Room, Gymnasium	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
EXIT/EMERGENCY LIGHT	Does not Exist	
CITY FIRE ALARM SYSTEM	Inspected	
Condition	5 - Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Location/Instance	Outside Principal's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
FIRE ALARM SYSTEM	Inspected	
Replacement Quantity	96,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not Exist	
Manual Pull Station	Inspected	
Condition	3 - Fair	
	No deficiencies recorded	
Deficiency For Shytdown Control		
Fan Shutdown Control	Does not Exist	
Duct Smoke Detector	Does not Exist	
Area Smoke Detector	Does not Exist	
CO Detector	Does not Exist	

rical Inspection	X
estion	Response
TIRE ALARM SYSTEM	
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
	Fire Alarm Control Panel
Equipment Capacity/Size Quantity	7
Capacity/Size UOM	Circuits
Source of Capacity/Size  Installation Year	Inspector Estimate 1961
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	96,000 S.F.
Quantity Uom	S.F.
Potential Action Urgency of Action	REPLACE PRIORITY I
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Sprinkler Alarm Control Board
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate

vuestion	Response
FIRE ALARM SYSTEM	Корольс
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Installation Year	1961
Source of Installation	Documented
Deficiency	
Deficiency Location/Instance	BEYOND USEFUL LIFE Boiler Room
Deficiency Quantity	96,000
Quantity Uom	90,000 S.F.
Potential Action	REPLACE
	PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	No photo recorded  No violations recorded.
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER INDICATOR LIGHT NOT OPERATIONA
Deficiency Location/Instance	Boiler Room, Basement - Fan Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	Inspected
	•
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

ctrical Inspection	X00		
Question	Response		
PANEL BOARD			
Fused Knife Switch Type	Does not Exist		
Fused Toggle Switch Type	Inspected		
Condition	3 - Fair		
Deficiency	PANEL BOARD BEYOND USEFUL LIFE		
Deficiency Location/Instance	Electrical Room		
Deficiency Quantity	2		
Quantity Uom	EACH		
Potential Action	REPLACE-UPGRADE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Molded Case Circuit Breaker Type	Inspected		
Condition	3 - Fair		
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING		
Deficiency Location/Instance	Cafeteria, Auditorium, Gymnasium, Basement - Corridor, Closet (Room 322)		
Deficiency Quantity	5		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 2		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Deficiency	PANEL BOARD DOOR LOCK IS MISSING		
Deficiency Location/Instance	Closet (Rooms 222, 314, 322), Boiler Room		
Deficiency Quantity	6		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 2		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Deficiency	NO SPARE		
Deficiency Location/Instance	Closet (Rooms 222, 314), Kitchen		
Deficiency Quantity	3		
Quantity Uom	EACH		
Potential Action	INSTALL NEW PANEL BOARD		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Deficiency Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Corridors (Basement, 1st, 2nd, 3rd Floor), Boiler Room, Gymnasiu		
	Auditorium, Basement - Fan Room, Projection Room		
Deficiency Quantity	13		
Quantity Uom	EACH		
Potential Action	REPLACE-UPGRADE		

ectrical Inspection	X001
Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms (153, 209, 224, 324), Boiler Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	96,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TAX 125C
Installation Year	1961
Source of Installation	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Room 243
Deficiency Quantity	96,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	96,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	96,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

trical Inspection	X00
nestion	Response
PUBLIC ADDRESS SYSTEM	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	96,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	96,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BPT
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	30
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	By East 152nd & 153rd Street
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded

uestion	Response	
SECURITY	Inspected	
Lighting - Security	•	
Violations	No violations recorded.	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Empire Switchboard	
Equipment	Service A	
Capacity/Size Quantity	800	
Capacity/Size UOM		
	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1961	
Source of Installation	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	96,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Empire Switchboard	
Equipment	Service B	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1961	
Source of Installation	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
•	Boiler Room 96,000	
Deficiency Location/Instance		
Deficiency Location/Instance Deficiency Quantity	96,000	
Deficiency Location/Instance Deficiency Quantity Quantity Uom	96,000 S.F.	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	96,000 S.F. REPLACE	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	96,000 S.F. REPLACE PRIORITY 1	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	96,000 S.F. REPLACE PRIORITY 1 LEVEL 2	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	96,000 S.F. REPLACE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1	96,000 S.F. REPLACE PRIORITY 1 LEVEL 2 No photo recorded	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	96,000 S.F. REPLACE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded. Inspected	
Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  SWITCHBOARD Number of Spares	96,000 S.F. REPLACE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 1	

# **Building Condition Assessment Survey 2017 - 2018**

uestion	Response	
SWITCHBOARD	кезропяс	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Empire Switchboard	
Equipment	N/A	
Capacity/Size Quantity	875	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	1961	
Source of Installation	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	96,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	
TV SYSTEM	Inspected	
Cable System Exist?	Yes	

Does not Exist

Main Equipment Rack