

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

**Asset: JONAS BRONCK ACADEMY - BRONX, 400 EAST FORDHAM ROAD, New York, 10458**

Inspection Id	Inspection Type	Time In	Last Edited
EE : X283	Electrical	2017-12-11 11:52 AM	2017-12-21 4:31 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components
	Years: 2009

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM   Sub-Panel   Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Marty Markov	Fireman	Sent to DSF	

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Inspected
Instance on 5th Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 5th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Local Sound System</b>	Inspected
Instance on 5th Floor	Inspected
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 5th Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 5th Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 5th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	Inspected
Instance on Room 401	Inspected
<b>Lighting</b>	Inspected
Instance on Room 401	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 401	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 401	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 401	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 401	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 401	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 401	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 401	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 4th Floor - Boys	Inspected
Alternative use	No
Instance on 4th Floor - Girls	Inspected
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on 4th Floor - Girls	Inspected
Instance on 4th Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor - Girls	Inspected
Instance on 4th Floor - Boys	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 4th Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor - Boys	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on 4th Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 4th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 4th Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 4th Floor	Inspected
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 509	Inspected
Power Panel	No
Alternative use	No

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Lighting</b>	Inspected
Instance on Room 509	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 509	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 509	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 509	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 509	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected
Instance on Room 509	Inspected
<b>Instructor Unit</b>	
Instance on Room 509	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 509	Does not Exist
<b>Meter Demonstration Unit</b>	
Instance on Room 509	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
Instance on Room 511	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 511	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 511	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 511	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 511	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 511	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 511	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 511	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 511	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 511	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 511	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 511	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Room 425A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #11
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 425A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #12
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Does not Exist
<b>Diesel</b>	Does not Exist
<b>Natural Gas</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	4th Floor Corridor by General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Does not Exist
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Does not Exist
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Does not Exist



**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 3
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Source of Capacity/Size	Diagram
Installation Year	2009
Source of Installation	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Does not Exist
<b>Tamper Flow Switch/Chain</b>	Does not Exist
<b>GROUNDING SYSTEM</b>	
	Does not Exist
<b>INTERCOM SYSTEM</b>	
	Inspected
<b>Elevator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>LAN</b>	Inspected
<b>Main Equipment Rack (MDF)</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Rooms (402, 425)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Instance	Room 419C
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA 250
Installation Year	2009
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Girls Locker Room, Multipurpose Room, Room 425
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

Question	Response
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Custodian's Office - Room 424
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
	Inspected
Condition	3 - Fair
Deficiency	ANNUNCIATOR NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office - Room 424
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Siren/Strobe</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	
	Does not Exist
<b>Lighting - Security</b>	
	Does not Exist
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Room 419B
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MDB
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X283

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	Inspected
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	3
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room 419B
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MDB
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Does not Exist