

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

School: HIGHBRIDGE ENVIRONMENTAL EDUCATION CAMPUS - BRONX, 200 WEST 167 STREET, BRONX, NY, 10452

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 3928 | ELECTRICAL | 2019-04-16 01:14PM | 2019-05-21 03:25PM |

Asset Data

| Question | Answer |
|---|---|
| Have any Systems/Major Building Components been upgraded? | Systems: All Electrical Systems and Components Years: 2013 |
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration In Electrical Room? | No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|------------------|--|-----------------------|---------------------------------|--------------------------------|--------------------|-----------------|----------------|
| No | Fire Alarm System - Components Not Operational | N/A | Fire Alarm System - CO Detector | 4th Floor Corridor By Room 416 | Eduardo Lugo | Fireman | No Photo Taken |

Inspection

| Question | Response |
|--|--------------------------|
| Electrical | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Does not exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| CAFETERIA | |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|------------------------------------|
| CAFETERIA | |
| Local Sound System | |
| Instance Condition | 2- Between Good and Fair |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on 1st Floor | Does not exist |
| Theater Lighting System | |
| Instance on 1st Floor | Does not exist |
| CITY FIRE ALARM SYSTEM | |
| | Does not exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| | Inspected |
| Lighting | |
| Does a Chandelier Exist? | Inspected |
| | No |
| Lighting Fixture - Fluorescent | |
| | Inspected |
| Pendant Mounted | |
| | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| | Does not exist |
| Lighting Fixture - Incandescent | |
| | Does not exist |
| Lighting Fixture - LED | |
| | Does not exist |
| COMPUTER LAB | |
| | Does not exist |
| EMERGENCY DC STANDBY BATTERY POWER | |
| | Does not exist |
| EMERGENCY GENERATOR SET | |
| | Inspected |
| Automatic Transfer Switch (ATS) | |
| | Inspected |
| Instance | Room C03 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | GE Zenith Controls |
| EquipmentId | N/A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Room C03 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | GE Zenith Controls |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|---|--------------------------------------|
| EMERGENCY GENERATOR SET | |
| Automatic Transfer Switch (ATS) | |
| EquipmentId | Fire Alarm Automatic Transfer Switch |
| Capacity/Size Quantity | 40 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Fire Pump Room C07 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Tornatech |
| EquipmentId | Fire Pump Power Transfer Switch |
| Capacity/Size Quantity | 30 |
| Capacity/Size UOM | HP |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Battery Charger | Inspected |
| Instance | Roof - Emergency Generator Enclosure |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | SENS |
| EquipmentId | Battery Charger |
| Capacity/Size Quantity | 10 |
| Capacity/Size UOM | AmpsDC |
| Capacity/Size 2 Quantity | 24 |
| Capacity/Size 2 UOM | VDC |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Diesel | Inspected |
| Instance | Roof - Emergency Generator Enclosure |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Caterpillar |
| EquipmentId | Emergency Generator |
| Capacity/Size Quantity | 375 |
| Capacity/Size UOM | kVA |
| Capacity/Size 2 Quantity | 300 |
| Capacity/Size 2 UOM | kW |
| Capacity/Size 3 Quantity | 1,042 |
| Capacity/Size 3 UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Natural Gas | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not exist |
| EMERGENCY LIGHTING | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|--------------------------------|
| EMERGENCY LIGHTING | |
| Battery Pack | Does not exist |
| Non Battery Pack | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | |
| | Inspected |
| Battery Pack | Inspected |
| Condition | 1- Good |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | 1st Floor By Exit 1 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Does not exist |
| EXIT/EMERGENCY LIGHT | |
| | Does not exist |
| FIRE ALARM SYSTEM | |
| | Inspected |
| Area Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Bell/Horn | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | DETECTOR NOT OPERATIONAL |
| Deficiency Location/Instance | 4th Floor Corridor By Room 416 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Heat Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|------------------------------------|
| FIRE ALARM SYSTEM | |
| Main Panel | Inspected |
| Bell At Panel | Does not exist |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| Model | FireFinder XLS |
| EquipmentId | Fire Alarm Control Panel |
| Capacity/Size Quantity | 80 |
| Capacity/Size UOM | Zones |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Manual Pull Station | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Sub-Panel | Does not exist |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Does not exist |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|---|--------------------------|
| INTERCOM SYSTEM | |
| Elevator | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not exist |
| KITCHEN | |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIBRARY | |
| Instance on Room 314 | Inspected |
| Lighting | |
| Instance on Room 314 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 314 | Inspected |
| Pendant Mounted | |
| Instance on Room 314 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 314 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - LED | |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|---|--------------------------|
| LIBRARY | |
| Lighting | |
| Lighting Fixture - LED | |
| Instance on Room 314 | Does not exist |
| Projection System | |
| Instance on Room 314 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 314 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LOCKER ROOM | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Inspected |
| Alternative Use | Yes |
| Lighting | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Inspected |
| Pendant Mounted | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Does not exist |
| Recessed Mounted | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Does not exist |
| Lighting Fixture - HID | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Does not exist |
| Lighting Fixture - LED | |
| Instance on 2nd Floor - Boys, 2nd Floor - Girls | Does not exist |
| MOTOR CONTROL CENTER | |
| | Does not exist |
| MOTOR STARTER/CONTACTOR | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| MULTIPURPOSE ROOM | |
| Instance on 2nd Floor | Inspected |
| Lighting | |
| Instance on 2nd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 2nd Floor | Inspected |
| Pendant Mounted | |
| Instance on 2nd Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 2nd Floor | Does not exist |
| Surface Mounted | |
| Instance on 2nd Floor | Does not exist |
| Lighting Fixture - HID | |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|---|--|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on 2nd Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 2nd Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 2nd Floor | Does not exist |
| Local Sound System | |
| Instance on 2nd Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | SPEAKER POORLY PROTECTED FROM PHYSICAL DAMAGE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Projection System | |
| Instance on 2nd Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 2nd Floor | Inspected |
| Dimming System | |
| Instance on 2nd Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting | |
| Instance on 2nd Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | |
| | Inspected |
| Fused Disconnect Switch Type | Does not exist |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | Room 413, Kitchen |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| | Inspected |
| Instance | Telecom Room 212 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|--------------------------|
| PUBLIC ADDRESS SYSTEM | |
| Model | Telecor II |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SCIENCE DEMO ROOM | |
| | Does not exist |
| SCIENCE LAB | |
| Instance on Room 416 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 416 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 416 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Lighting | |
| Instance on Room 416 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 416 | Inspected |
| Pendant Mounted | |
| Instance on Room 416 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 416 | Does not exist |
| Surface Mounted | |
| Instance on Room 416 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 416 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 416 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 416 | Does not exist |
| Power Supply | |
| Instance on Room 416 | Does not exist |
| Projection System | |
| Instance on Room 416 | Does not exist |
| SCIENCE PREP ROOM | |
| Instance on Room 415 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 415 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 415 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Lighting | |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|-------------------------------|
| SCIENCE PREP ROOM | |
| Lighting | |
| Instance on Room 415 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 415 | Inspected |
| Pendant Mounted | |
| Instance on Room 415 | Does not exist |
| Recessed Mounted | |
| Instance on Room 415 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 415 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 415 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 415 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 415 | Does not exist |
| Power Supply | |
| Instance on Room 415 | Does not exist |
| SECURITY | Inspected |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | Custodian's Office - Room 126 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128BP |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | Does not exist |
| IPDVS/CCTV System | Inspected |
| Condition | 2- Between Good and Fair |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inspected |
| Condition | 2- Between Good and Fair |
| Replacement Quantity | 38 |
| Replacement Uom | EACH |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|-----------------------------|---|
| SECURITY | |
| Lighting - Security | |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | Service Switch #1 |
| Capacity/Size Quantity | 2000 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | Service Switch #2 - Feeds PNL "EDP" Via ATS |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | Service Switch #3 |
| Capacity/Size Quantity | 2000 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | Service Switch #6 (Fire Pump) |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SWIMMING POOL | Does not exist |
| SWITCHBOARD | Inspected |
| Number of Spares | 20 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|---|--|
| SWITCHBOARD | |
| Air Circuit Breaker Type | Does not exist |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | DPA Section #1, 2 |
| Capacity/Size Quantity | 2000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | DPB Section #1, 2 |
| Capacity/Size Quantity | 2000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Room C03 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | EDP Section #1, Section #2 (Emergency Generator Switchboard) |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Does not exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| TOILET ROOM - STAFF | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X285

| Question | Response |
|--|--------------------------|
| TOILET ROOM - STAFF | |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TRANSFORMER | Does not exist |
| TV SYSTEM | Inspected |
| Cable System Exist? | Yes |
| Operational? | No |
| Main Equipment Rack | Does not exist |