

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Asset: HERBERT H. LEHMAN HS - X, 3000 EAST TREMONT AVENUE, New York, 10461

Inspection Id	Inspection Type	Time In	Last Edited
EE : X405	Electrical	2017-11-20 8:22 AM	2018-06-14 12:40 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Computer Lab - Room 103, Computer Lab - Room B24 (Raceway With Receptacles), LED Lighting - Rooms (103, 109, 123, 437)
	Years: 2017
	Systems: Gymnasiums (LED Lighting), Boys C/D Gymnasium (Scoreboard), Lightning Protection, Telephone System
	Years: 2016
	Systems: Computer Lab - Room 455
	Years: 2014
	Systems: Computer Lab - Room 420B
	Years: 2013
	Systems: Partial Service Switch, Partial Switchboard, Emergency Generator Set, Fire Alarm System, Transformer
	Years: 2012
	Systems: Public Address System, Local Sound System, Students Cafeteria (Recessed Fluorescent Lighting), Football Team Locker Room
	Years: 2010
	Systems: Exit/Emergency Lights
	Years: 2009
	Systems: Recessed Incandescent Lighting, Science Lab - Rooms (362, 366), Science Prep Room 364, IPDVS/CCTV System
	Years: 2006
	Systems: Auditorium (Theater Lighting System)
	Years: 2005
	Systems: Auditorium (Fluorescent Lighting)
	Years: 2004
	Systems: Interior Fluorescent Lighting, Most Recessed Fluorescent Lighting (Retrofitted)
	Years: 1997
	Systems: Intrusion Alarm System
	Years: 1996
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 1995, 2016
	Systems: Most Molded Case Circuit Breaker Panel Board
	Years: 1995, 2005, 2011
	Systems: Partial Security Lights
	Years: 1995, 2004, 2011, 2016

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

NYC Department of Education

Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Emergency Gas Shut-Off Valve - Not Operational	N/A	SCIENCE LAB Emergency Gas Shut-Off Valve	Room 332	Celestino Fernandez	Custodian	Sent to DSF	
No	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM Elevator	Elevator Device ID: 2P4424	Celestino Fernandez	Custodian	Sent to DSF	
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture, Panel Board	Boiler Room	Celestino Fernandez	Custodian	Sent to DSF	
Yes	Emergency Lighting - Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	Boys Locker Room, Basement Floor Corridor, Outside Generator Enclosure, 1st Floor Corridor by Room 168	Celestino Fernandez	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Magnetic Door Holder/Contacto r	Students Cafeteria	Celestino Fernandez	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	Yes
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	49
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement - Students A/B	Inspected
Instance on Basement - Staff	Inspected
Lighting	
Instance on Basement - Staff	Inspected
Instance on Basement - Students A/B	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Staff	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement - Students A/B	Inspected
Pendant Mounted	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
Surface Mounted	
Instance on Basement - Staff	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Students A/B	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
Local Sound System	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
CAFETERIA	
Projection System	Does not Exist
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - Staff	Does not Exist
Instance on Basement - Students A/B	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Condition	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	72
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Condition	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Condition	Inspected
Pendant Mounted	
Condition	Does not Exist
Surface Mounted	
Condition	Does not Exist
Recessed Mounted	
Condition	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	
Condition	Inspected
Instance on Room 103	Inspected
Power Panel	Yes
Instance on Rooms 205, 208	Inspected
Power Panel	No
Instance on Room 207	Inspected
Power Panel	Yes
Instance on Room 420B	Inspected
Power Panel	No
Instance on Room 455	Inspected
Power Panel	Yes
Instance on Room B24	Inspected
Power Panel	Yes
Lighting	
Condition	Inspected
Instance on Room B24	Inspected
Instance on Room 455	Inspected
Instance on Room 420B	Inspected
Instance on Room 207	Inspected
Instance on Rooms 205, 208	Inspected
Instance on Room 103	Inspected
Lighting Fixture - Fluorescent	
Instance on Room B24	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 455	Inspected
Instance on Room 420B	Inspected
Instance on Room 207	Inspected
Instance on Rooms 205, 208	Inspected
Instance on Room 103	Inspected
Pendant Mounted	Inspected
Instance on Room B24	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 455	Does not Exist
Instance on Room 420B	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 207	Does not Exist
Instance on Rooms 205, 208	Does not Exist
Instance on Room 103	Does not Exist
Surface Mounted	Does not Exist
Instance on Room B24	Does not Exist
Instance on Room 455	Does not Exist
Instance on Room 420B	Does not Exist
Instance on Room 207	Does not Exist
Instance on Rooms 205, 208	Does not Exist
Instance on Room 103	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room B24	Does not Exist
Instance on Room 455	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 420B	Does not Exist
Instance on Room 207	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 205, 208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 103	Does not Exist
Lighting Fixture - HID	
Instance on Room B24	Does not Exist
Instance on Room 455	Does not Exist
Instance on Room 420B	Does not Exist
Instance on Room 207	Does not Exist
Instance on Rooms 205, 208	Does not Exist
Instance on Room 103	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room B24	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 455	Does not Exist
Instance on Room 420B	Does not Exist
Instance on Room 207	Does not Exist
Instance on Rooms 205, 208	Does not Exist
Instance on Room 103	Does not Exist
Lighting Fixture - LED	
Instance on Room B24	Does not Exist
Instance on Room 455	Does not Exist
Instance on Room 420B	Does not Exist
Instance on Room 207	Does not Exist
Instance on Rooms 205, 208	Does not Exist
Instance on Room 103	Inspected
Pendant Mounted	
Instance on Room 103	Does not Exist
Surface Mounted	
Instance on Room 103	Does not Exist
Recessed Mounted	
Instance on Room 103	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room B24	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 455	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 420B	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 207	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 205, 208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 103	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on Basement - Girls A/B	Inspected
Instance on Basement - Boys C/D	Inspected
Lighting	
Instance on Basement - Boys C/D	Inspected
Instance on Basement - Girls A/B	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Lighting Fixture - HID	
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Boys C/D	Inspected
Instance on Basement - Girls A/B	Inspected
Pendant Mounted	
Instance on Basement - Boys C/D	Inspected
Condition	1 - Good
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Girls A/B	Inspected
Condition	1 - Good
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Recessed Mounted	
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Local Sound System	
Instance on Basement - Boys C/D	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
GYMNASIUM	
Local Sound System	
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Girls A/B	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
Scoreboard	Inspected
Instance on Basement - Boys C/D	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Basement - Girls A/B	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Does not Exist
Instance on Basement - Boys C/D	Does not Exist
Instance on Basement - Girls A/B	Does not Exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 107	Inspected
Lighting	
Instance on Room 107	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 107	Inspected
Pendant Mounted	Does not Exist
Instance on Room 107	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 107	Does not Exist
Recessed Mounted	Inspected
Instance on Room 107	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 107	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 107	Does not Exist
Lighting Fixture - LED	
Instance on Room 107	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 107	Does not Exist
Projection System	Does not Exist
Instance on Room 107	Does not Exist
LOCKER ROOM	
Instance on Basement - Boys	Inspected
Alternative use	No
Instance on Basement - Girls	Inspected
Alternative use	No
Instance on Basement - Football Team	Inspected
Alternative use	No
Instance on Basement - Room B48	Inspected
Alternative use	Yes

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
LOCKER ROOM	
Instance on Basement - Room B49	Inspected
Alternative use	No
Lighting	Inspected
Instance on Basement - Room B49	Inspected
Instance on Basement - Room B48	Inspected
Instance on Basement - Football Team	Inspected
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Room B49	Inspected
Instance on Basement - Room B48	Inspected
Instance on Basement - Football Team	Inspected
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Pendant Mounted	
Instance on Basement - Room B49	Does not Exist
Instance on Basement - Room B48	Does not Exist
Instance on Basement - Football Team	Does not Exist
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Surface Mounted	
Instance on Basement - Room B49	Does not Exist
Instance on Basement - Room B48	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Football Team	Does not Exist
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
	Inspected
Instance on Basement - Room B49	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Basement - Room B48	Does not Exist
Instance on Basement - Football Team	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement - Room B49	Does not Exist
Instance on Basement - Room B48	Does not Exist
Instance on Basement - Football Team	Does not Exist
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Room B49	Does not Exist
Instance on Basement - Room B48	Does not Exist
Instance on Basement - Football Team	Does not Exist
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Room B49	Does not Exist
Instance on Basement - Room B48	Does not Exist
Instance on Basement - Football Team	Does not Exist
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	
	Inspected
Instance on Room 301	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 324, 344, 348	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 327, 351, 353, 354, 356	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE DEMO ROOM	
Power Panel	No
Alternative use	Yes
Instance on Room 328	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 337, 339	Inspected
Power Panel	No
Alternative use	Yes
Lighting	Inspected
Instance on Rooms 337, 339	Inspected
Instance on Room 328	Inspected
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Instance on Rooms 324, 344, 348	Inspected
Instance on Room 301	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 337, 339	Inspected
Instance on Room 328	Inspected
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Instance on Rooms 324, 344, 348	Inspected
Instance on Room 301	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Surface Mounted	Does not Exist
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Recessed Mounted	Inspected
Instance on Rooms 337, 339	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 324, 344, 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 337, 339	Inspected
Instance on Room 328	Inspected
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Instance on Rooms 324, 344, 348	Inspected
Instance on Room 301	Inspected
Pendant Mounted	
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Surface Mounted	
Instance on Rooms 337, 339	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 324, 344, 348	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Projection System	
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 337, 339	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	
Deficiency	No deficiencies recorded
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 324, 344, 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 337, 339	Does not Exist
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Does not Exist
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Does not Exist
Power Supply	Inspected
Instance on Rooms 337, 339	Inspected
Instance on Room 328	Inspected
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Instance on Rooms 324, 344, 348	Inspected
Instance on Room 301	Inspected
Instructor Unit	
Instance on Rooms 337, 339	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 328	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 324, 344, 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 337, 339	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 328	Does not Exist
Instance on Rooms 327, 351, 353, 354, 356	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Meter Demonstration Unit	
Deficiency	No deficiencies recorded
Instance on Rooms 324, 344, 348	Does not Exist
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance on Room 308	Inspected
Power Panel Alternative use	Yes Yes
Instance on Room 323	Inspected
Power Panel Alternative use	No No
Instance on Room 325	Inspected
Power Panel Alternative use	No No
Instance on Room 332	Inspected
Power Panel Alternative use	Yes No
Instance on Room 340	Inspected
Power Panel Alternative use	No No
Instance on Room 362	Inspected
Power Panel Alternative use	Yes No
Instance on Room 366	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room 366	Inspected
Instance on Room 362	Inspected
Instance on Room 340	Inspected
Instance on Room 332	Inspected
Instance on Room 325	Inspected
Instance on Room 323	Inspected
Instance on Room 308	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 366	Inspected
Instance on Room 362	Inspected
Instance on Room 340	Inspected
Instance on Room 332	Inspected
Instance on Room 325	Inspected
Instance on Room 323	Inspected
Instance on Room 308	Inspected
Pendant Mounted	
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Recessed Mounted	Inspected
Instance on Room 366	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 362	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 332	Inspected
Instance on Room 325	Inspected
Instance on Room 323	Inspected
Instance on Room 308	Inspected
Pendant Mounted	
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Surface Mounted	
Instance on Room 340	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Lighting Fixture - LED	
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 362	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 362	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 366	Inspected
Instance on Room 362	Inspected
Instance on Room 340	Inspected
Instance on Room 332	Inspected
Instance on Room 325	Inspected
Instance on Room 323	Inspected
Instance on Room 308	Inspected
Instructor Unit	
Instance on Room 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 362	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 340	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 332	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 366	Does not Exist
Instance on Room 362	Does not Exist
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Does not Exist
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 362	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 323	Does not Exist
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 366	Does not Exist
Instance on Room 366	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE LAB	
Projection System	
Instance on Room 362	Does not Exist
Instance on Room 340	Does not Exist
Instance on Room 332	Does not Exist
Instance on Room 325	Does not Exist
Instance on Room 323	Does not Exist
Instance on Room 308	Does not Exist
SCIENCE PREP ROOM	
	Inspected
Instance on Rooms 305, 307	Inspected
Power Panel Alternative use	No No
Instance on Room 336	Inspected
Power Panel Alternative use	No No
Instance on Room 336B	Inspected
Power Panel Alternative use	No No
Instance on Room 364	Inspected
Power Panel Alternative use	No No
Lighting	
	Inspected
Instance on Room 364	Inspected
Instance on Room 336B	Inspected
Instance on Room 336	Inspected
Instance on Rooms 305, 307	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 364	Inspected
Instance on Room 336B	Inspected
Instance on Room 336	Inspected
Instance on Rooms 305, 307	Inspected
Pendant Mounted	
	Does not Exist
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 305, 307	Does not Exist
Surface Mounted	
	Does not Exist
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Does not Exist
Recessed Mounted	
	Inspected
Instance on Room 364	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 336	Inspected
Instance on Rooms 305, 307	Inspected
Pendant Mounted	
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Does not Exist
Surface Mounted	
Instance on Room 336	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 305, 307	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Does not Exist
Lighting Fixture - LED	
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
SCIENCE PREP ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Room 336	Does not Exist
Instance on Rooms 305, 307	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 364	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 305, 307	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 364	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 305, 307	Does not Exist
Power Supply	Does not Exist
Instance on Room 364	Does not Exist
Instance on Room 336B	Does not Exist
Instance on Room 336	Inspected
Instance on Rooms 305, 307	Does not Exist
Instructor Unit	
Instance on Room 336	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not Exist
TOILET ROOM - STAFF	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	379,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room B04
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-FA

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room B04
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-EDB
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room B04
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-EDB-2
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room B04
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-DP-EM
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Outside Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
EMERGENCY GENERATOR SET	
Battery Charger	
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Outside Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Marathon Electric
Equipment	Emergency Generator
Capacity/Size Quantity	625
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	500
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,734
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Outside Generator Enclosure, 1st Floor Corridor by Room 168, Boys Locker Room, Basement Floor Corridor
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Boys Gymnasium, Girls Gymnasium
Deficiency Quantity	2

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
EMERGENCY LIGHTING	
Non Battery Pack	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT LIGHT	
	Inspected
Battery Pack	
	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Basement Corridor by Girls Locker Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor by Rooms (277, 279)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	
	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium Stage, Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	
	Inspected
Condition	4 - Between Fair and Poor
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Clinic Room B34
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
EXIT/EMERGENCY LIGHT	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	379,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Mechanical Room A, Mechanical Room B, Gymnasium Mechanical Room, Boys Gymnasium, 2nd Floor Corridor by Stair C/D, Cafeteria, Basement Corridor by Room B55
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	5 - Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Students Cafeteria
Deficiency Quantity	4
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Cutout Panel	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Fire Alarm Digital Communicator	
	Does not Exist
Main Panel	
	Inspected
Bell At Panel	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Fire Alarm Control Panel (Electronic)	
Instance	Inspected
Instance Condition	Main Entrance Lobby
Instance Quantity	2 - Between Good and Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	General Electric
Model	Fire Alarm Control Panel
Capacity/Size Quantity	EST 3
Capacity/Size UOM	36
Capacity/Size2 Quantity	Zones
Capacity/Size2 UOM	1
Source of Capacity/Size	Section(S)
Installation Year	Inspector Estimate
Source of Installation	2012
Deficiency	Documented
Fire Alarm Control Panel (Standard)	
	Does not Exist
Sub-Panel	
	Does not Exist
Remote Annunciator	
	Inspected
Display Monitor	
	Does not Exist
Panel	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Printer	
Condition	No deficiencies recorded
Deficiency	No deficiencies recorded
Punch Register	
	Does not Exist
Sprinkler Flow/Air Pressure Switch	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Tamper Flow Switch/Chain	
Condition	No deficiencies recorded
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator ID# 2P4424
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	PVT584873
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (L/DF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room B, Mechanical Room A, Gymnasium Mechanical Room, Mechanical Room 274A, Boiler Room, Electrical Room
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Condition	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 238
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Electrical Room, 1st Floor Corridor by Room 160, Girls Gymnasium, Room 301, Auditorium Stage Right side Storage Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Mechanical Room B, Closet by (4th Floor Girls Toilet Room, Room 214)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Closet by Rooms (448, 440, 414), Closet by 4th Floor Girls Toilet Room, Rooms (438, 432, 301A, 332, 308, 374A, 227A, 238, 132, 142, 134, B23C), 1st Floor Corridor by Rooms (102, 119A, 152A, 160), Basement Corridor by Elevator, Girls Gymnasium, Kitchen, Electrical Room, Mechanical Rooms (Auditorium, Stair L/M, C), Auditorium Stage Right side Storage Room
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Boys Gymnasium, Room 207
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	379,000
Replacement Uom	S.F.
Instance	Room 167C
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA 250
Installation Year	2010
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Room 167C
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Rooms (103, 109, 123)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	379,000
Replacement Uom	S.F.
Installation Year	2006
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	379,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT2
Installation Year	1996
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SWITCH MISSING
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL SWITCH
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Remote Annunciator	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Siren/Strobe	Inspected
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	186
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE PHOTOCCELL NOT OPERATIONAL
Deficiency Location/Instance	On Roof by Exit 8
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Back Plaza Deck, Parking Lot, Playground
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	124
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room B06
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Main Switch SWBD. A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SERVICE SWITCH	
Deficiency Location/Instance	Electrical Meter Room B06
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Meter Room B06
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Main Switch SWBD. B
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B06
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Meter Room B06
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	DSW-MSA-1
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	6
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Meter Room B06
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Manufacturer	Royal Switchboard Co.
Equipment	Switchboard A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B06
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Meter Room B06
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Switchboard B
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1973
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B06
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Room B04
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	DS-MSA-1, 2
Capacity/Size Quantity	1,600

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X405

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Inspected
Instance	Outside Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	SWBD GEN PANEL (Emergency Generator Switchboard)
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
	Inspected
Instance	Outside by Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Advanced Energy
Equipment	INVERTER 3
Capacity/Size Quantity	63
Capacity/Size UOM	KVA
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Outside by Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X405

Question	Response
TRANSFORMER	
Instance Manufacturer	Advanced Energy
Equipment	INVERTER 2
Capacity/Size Quantity	94
Capacity/Size UOM	KVA
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room inside Mechanical Room B
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Advanced Energy
Equipment	INVERTER 1
Capacity/Size Quantity	94
Capacity/Size UOM	KVA
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist