

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

Asset: JOHN F. KENNEDY HS - X, 99 TERRACE VIEW AVENUE, New York, 10463

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|---------------------|
| EE : X475 | Electrical | 2018-02-07 8:50 AM | 2018-03-21 11:02 AM |

Asset Data

| Question | Answer |
|---|---|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | Yes |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Computer Lab - Room 742, Science Demo -Room 668 (Projection System) |
| | Years: 2017 |
| | Systems: LED Lighting, Auditorium, Fluorescent Lighting (5th Floor Cafeteria, Computer Lab - Rooms 534, 556, 566), Computer Lab - Room 338 (Raceway with Receptacles), Science Demo - Rooms (634, 638), Science Demo Rooms (Emergency Gas Shut-Off Valve), Science Lab Rooms (Except Room 554), Science Prep Rooms, Exit Lights (Battery Pack), LAN, Telephone System |
| | Years: 2016 |
| | Systems: Library, Intrusion Alarm System |
| | Years: 2014 |
| | Systems: Fire Alarm System |
| | Years: 2013 |
| | Systems: Most Motor Starters |
| | Years: 2012 |
| | Systems: Partial Fused Disconnect Switch Type Panel Board |
| | Years: 2010, 2016 |
| | Systems: Public Address System, Local Sound System, Service Switch, Emergency Generator Set, Switchboard |
| | Years: 2010 |
| | Systems: Partial Emergency Lighting (Non-Battery Pack) |
| | Years: 2009, 2014, 2016 |
| | Systems: Fluorescent Lighting (7th Floor Cafeteria, 7th Floor Kitchen, Locker Room 193-I, 1st Floor - Baseball Locker Room, Science Demo Room 612, Computer Rooms 434, Science Lab - Room 554) |
| | Years: 2009 |
| | Systems: Exit/Emergency Light |
| | Years: 2008 |
| | Systems: IPDVS/CCTV System |
| | Years: 2007 |
| | Systems: Most Transformers |
| | Years: 2003, 2010 |
| | Systems: Interior Fluorescent Lighting |
| | Years: 1995, 2009, 2016 |
| | Systems: Lighting (1st Floor - Football Locker Room, Locker Rooms G114, 212, Science Demo Rooms (Except Rooms 612, 634, 638), Toilet Rooms) |
| | Years: 1995 |
| | Systems: Partial Security Lights |
| | Years: 1992 |
| | Systems: Partial Molded Case Circuit Breaker Panel Board |
| | Years: 1990, 2002, 2005, 2009, 2014, 2016 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| | |
|---|-----|
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---------------------------------------|-----------------------|--|---|--------------------|-----------------|-------------|------------|
| No | Exit Light - Not Operational | N/A | EXIT LIGHT Non Battery Pack | Girls Locker Room 212, Locker Room G114 | Jeric Facultad | Fireman | Sent to DSF | |
| No | Fire Alarm System - Defective | N/A | FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic) | 4th Floor - Main Entrance Lobby | Jeric Facultad | Fireman | Sent to DSF | |
| No | Water Penetration in Electrical Room | N/A | Electrical Equipment | Electrical Room | Jeric Facultad | Fireman | Sent to DSF | |
| Yes | Water Leaks onto Electrical Equipment | N/A | Lighting Fixture | Room 102 | Jeric Facultad | Fireman | Sent to DSF | |

Inspection

| Question | Response |
|--|--------------------------|
| Electrical | |
| AUDITORIUM | Inspected |
| Instance on 1st Floor | Inspected |
| House Lighting | Inspected |
| Does a Chandelier exist? | No |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---|--------------------------|
| AUDITORIUM | |
| House Lighting | |
| Lighting Fixture - LED | |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Installation Year | 2016 |
| Source of Installation | Custodial Staff |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 1st Floor | Inspected |
| Dimming System | |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting | |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| CAFETERIA | |
| Instance on 3rd Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Instance on 5th Floor | Inspected |
| Instance on 7th Floor | Inspected |
| Instance on 8th Floor | Inspected |
| Lighting | |
| Instance on 8th Floor | Inspected |
| Instance on 7th Floor | Inspected |
| Instance on 5th Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Instance on 3rd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 8th Floor | Inspected |
| Instance on 7th Floor | Inspected |
| Instance on 5th Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Instance on 3rd Floor | Inspected |
| Pendant Mounted | |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 8th Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on 7th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 5th Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on 3rd Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| CAFETERIA | |
| Local Sound System | Inspected |
| Instance on 8th Floor | Inspected |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 7th Floor | Inspected |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 5th Floor | Inspected |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Inspected |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 8th Floor | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| COMPUTER LAB | Inspected |
| Instance on Room 338 | Inspected |
| Power Panel | Yes |
| Instance on Room 342 | Inspected |
| Power Panel | No |
| Instance on Room 434 | Inspected |
| Power Panel | Yes |
| Instance on Room 504 | Inspected |
| Power Panel | No |
| Instance on Room 534 | Inspected |
| Power Panel | No |
| Instance on Room 556 | Inspected |
| Power Panel | No |
| Instance on Room 566 | Inspected |
| Power Panel | Yes |
| Instance on Room 742 | Inspected |
| Power Panel | No |
| Instance on Room 842 | Inspected |
| Power Panel | No |
| Lighting | Inspected |
| Instance on Room 842 | Inspected |
| Instance on Room 742 | Inspected |
| Instance on Room 566 | Inspected |
| Instance on Room 556 | Inspected |
| Instance on Room 534 | Inspected |
| Instance on Room 504 | Inspected |
| Instance on Room 434 | Inspected |
| Instance on Room 342 | Inspected |
| Instance on Room 338 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 842 | Inspected |
| Instance on Room 742 | Inspected |
| Instance on Room 566 | Inspected |
| Instance on Room 556 | Inspected |
| Instance on Room 534 | Inspected |
| Instance on Room 504 | Inspected |
| Instance on Room 434 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---------------------------------------|--------------------------|
| COMPUTER LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Instance on Room 342 | Inspected |
| Instance on Room 338 | Inspected |
| Pendant Mounted | |
| Instance on Room 842 | Does not Exist |
| Instance on Room 742 | Does not Exist |
| Instance on Room 566 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 556 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 534 | Does not Exist |
| Instance on Room 504 | Does not Exist |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 338 | Does not Exist |
| Surface Mounted | |
| Instance on Room 842 | Does not Exist |
| Instance on Room 742 | Does not Exist |
| Instance on Room 566 | Does not Exist |
| Instance on Room 556 | Does not Exist |
| Instance on Room 534 | Does not Exist |
| Instance on Room 504 | Does not Exist |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Does not Exist |
| Instance on Room 338 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 842 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 742 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 566 | Does not Exist |
| Instance on Room 556 | Does not Exist |
| Instance on Room 534 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 504 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 434 | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| COMPUTER LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 342 | Does not Exist |
| Instance on Room 338 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 842 | Does not Exist |
| Instance on Room 742 | Does not Exist |
| Instance on Room 566 | Does not Exist |
| Instance on Room 556 | Does not Exist |
| Instance on Room 534 | Does not Exist |
| Instance on Room 504 | Does not Exist |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Does not Exist |
| Instance on Room 338 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 842 | Does not Exist |
| Instance on Room 742 | Does not Exist |
| Instance on Room 566 | Does not Exist |
| Instance on Room 556 | Does not Exist |
| Instance on Room 534 | Does not Exist |
| Instance on Room 504 | Does not Exist |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Does not Exist |
| Instance on Room 338 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 842 | Does not Exist |
| Instance on Room 742 | Does not Exist |
| Instance on Room 566 | Does not Exist |
| Instance on Room 556 | Does not Exist |
| Instance on Room 534 | Does not Exist |
| Instance on Room 504 | Does not Exist |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Does not Exist |
| Instance on Room 338 | Does not Exist |
| Raceway With Receptacles | |
| Instance on Room 842 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 742 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 566 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| COMPUTER LAB | |
| Raceway With Receptacles | |
| Instance on Room 556 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 534 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 504 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 434 | Does not Exist |
| Instance on Room 342 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 338 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Pendant Mounted | Inspected |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| Scoreboard | Inspected |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| GYMNASIUM | Inspected |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor - 1/2, 1st Floor - 3/4 | Does not Exist |
| KITCHEN | Inspected |
| Instance on 3rd Floor, 4th Floor | Inspected |
| Instance on 5th Floor, 8th Floor | Inspected |
| Instance on 7th Floor | Inspected |
| Lighting | Inspected |
| Instance on 7th Floor | Inspected |
| Instance on 5th Floor, 8th Floor | Inspected |
| Instance on 3rd Floor, 4th Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 7th Floor | Inspected |
| Instance on 5th Floor, 8th Floor | Does not Exist |
| Instance on 3rd Floor, 4th Floor | Does not Exist |
| Pendant Mounted | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 7th Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 7th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor, 8th Floor | Does not Exist |
| Instance on 3rd Floor, 4th Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor, 8th Floor | Does not Exist |
| Instance on 3rd Floor, 4th Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 7th Floor | Does not Exist |
| Instance on 5th Floor, 8th Floor | Inspected |
| Instance on 3rd Floor, 4th Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 5th Floor, 8th Floor | Does not Exist |
| Instance on 3rd Floor, 4th Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on 5th Floor, 8th Floor | Does not Exist |
| Instance on 3rd Floor, 4th Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on 5th Floor, 8th Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on 3rd Floor, 4th Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|--------------------------|
| LIBRARY | Inspected |
| Instance on Room A164 | Inspected |
| Lighting | Inspected |
| Instance on Room A164 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room A164 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room A164 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room A164 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room A164 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room A164 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room A164 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room A164 | Does not Exist |
| Raceway With Receptacles | Inspected |
| Instance on Room A164 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Projection System | Inspected |
| Instance on Room A164 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| LOCKER ROOM | Inspected |
| Instance on 1st Floor - Football | Inspected |
| Alternative use | No |
| Instance on Room 193 - I, 1st Floor - Baseball | Inspected |
| Alternative use | No |
| Instance on Room 212 | Inspected |
| Alternative use | No |
| Instance on Room G114 | Inspected |
| Alternative use | No |
| Lighting | Inspected |
| Instance on Room G114 | Inspected |
| Instance on Room 212 | Inspected |
| Instance on Room 193 - I, 1st Floor - Baseball | Inspected |
| Instance on 1st Floor - Football | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room G114 | Inspected |
| Instance on Room 212 | Inspected |
| Instance on Room 193 - I, 1st Floor - Baseball | Inspected |
| Instance on 1st Floor - Football | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|------------------------------------|
| LOCKER ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | Does not Exist |
| Instance on Room G114 | Does not Exist |
| Instance on Room 212 | Does not Exist |
| Instance on Room 193 - I, 1st Floor - Baseball | Does not Exist |
| Instance on 1st Floor - Football | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Room G114 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 212 | Does not Exist |
| Instance on Room 193 - I, 1st Floor - Baseball | Does not Exist |
| Instance on 1st Floor - Football | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Instance on Room G114 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 212 | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance on Room 193 - I, 1st Floor - Baseball | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 1st Floor - Football | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room G114 | Does not Exist |
| Instance on Room 212 | Does not Exist |
| Instance on Room 193 - I, 1st Floor - Baseball | Does not Exist |
| Instance on 1st Floor - Football | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room G114 | Does not Exist |
| Instance on Room 212 | Does not Exist |
| Instance on Room 193 - I, 1st Floor - Baseball | Does not Exist |
| Instance on 1st Floor - Football | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor - Football | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|-------------------------------------|
| LOCKER ROOM | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Surface Mounted | Inspected |
| Instance on 1st Floor - Football | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor - Football | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room G114 | Does not Exist |
| Instance on Room 212 | Does not Exist |
| Instance on Room 193 - I, 1st Floor - Baseball | Does not Exist |
| Instance on 1st Floor - Football | Does not Exist |
| MULTIPURPOSE ROOM | Does not Exist |
| SCIENCE DEMO ROOM | Inspected |
| Instance on Room 668 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Instance on Rooms 634, 638 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Instance on Rooms 606, 672, 676 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Instance on Room 648 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Instance on Rooms 626, 628 | Inspected |
| Power Panel | No |
| Alternative use | Yes |
| Instance on Room 612 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Instance on Rooms 604, 662 | Inspected |
| Power Panel | No |
| Alternative use | Yes |
| Instance on Room 630 | Inspected |
| Power Panel | No |
| Alternative use | Yes |
| Lighting | Inspected |
| Instance on Room 630 | Inspected |
| Instance on Rooms 604, 662 | Inspected |
| Instance on Room 612 | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---------------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Instance on Rooms 626, 628 | Inspected |
| Instance on Room 648 | Inspected |
| Instance on Rooms 606, 672, 676 | Inspected |
| Instance on Rooms 634, 638 | Inspected |
| Instance on Room 668 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 630 | Inspected |
| Instance on Rooms 604, 662 | Inspected |
| Instance on Room 612 | Inspected |
| Instance on Rooms 626, 628 | Inspected |
| Instance on Room 648 | Inspected |
| Instance on Rooms 606, 672, 676 | Inspected |
| Instance on Rooms 634, 638 | Inspected |
| Instance on Room 668 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room 630 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 648 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 606, 672, 676 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on Room 630 | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 668 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 630 | Inspected |
| Instance on Rooms 604, 662 | Inspected |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Inspected |
| Instance on Room 648 | Inspected |
| Instance on Rooms 606, 672, 676 | Inspected |
| Instance on Rooms 634, 638 | Inspected |
| Instance on Room 668 | Inspected |
| Pendant Mounted | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| Surface Mounted | |
| Instance on Room 630 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 604, 662 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|--------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Surface Mounted | |
| Instance on Rooms 626, 628 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 648 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 606, 672, 676 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 634, 638 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 668 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| Projection System | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 630 | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|-------------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Emergency Gas Shut-Off Valve | |
| Instance on Rooms 604, 662 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 612 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 626, 628 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 634, 638 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 668 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 668 | Does not Exist |
| Power Supply | |
| Instance on Room 630 | Inspected |
| Instance on Rooms 604, 662 | Inspected |
| Instance on Room 612 | Inspected |
| Instance on Rooms 626, 628 | Inspected |
| Instance on Room 648 | Inspected |
| Instance on Rooms 606, 672, 676 | Inspected |
| Instance on Rooms 634, 638 | Inspected |
| Instance on Room 668 | Inspected |
| Instructor Unit | |
| Instance on Room 630 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 604, 662 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 612 | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---|--------------------------|
| SCIENCE DEMO ROOM | |
| Power Supply | |
| Instructor Unit | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 626, 628 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 648 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 606, 672, 676 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 634, 638 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 668 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Meter Demonstration Unit | |
| Instance on Room 630 | Does not Exist |
| Instance on Rooms 604, 662 | Does not Exist |
| Instance on Room 612 | Does not Exist |
| Instance on Rooms 626, 628 | Does not Exist |
| Instance on Room 648 | Does not Exist |
| Instance on Rooms 606, 672, 676 | Does not Exist |
| Instance on Rooms 634, 638 | Does not Exist |
| Instance on Room 668 | Does not Exist |
| SCIENCE LAB | |
| | Inspected |
| Instance on Room 554 | Inspected |
| Power Panel | Yes |
| Alternative use | No |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Power Panel | Yes |
| Alternative use | No |
| Lighting | |
| | Inspected |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Instance on Room 554 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Instance on Room 554 | Inspected |
| Pendant Mounted | |
| | Does not Exist |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Instance on Room 554 | Does not Exist |
| Surface Mounted | |
| | Does not Exist |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Instance on Room 554 | Does not Exist |
| Recessed Mounted | |
| | Inspected |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---|---------------------------|
| SCIENCE LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 554 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Instance on Room 554 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Instance on Room 554 | Does not Exist |
| Pendant Mounted | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Surface Mounted | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Instance on Room 554 | Does not Exist |
| Emergency Gas Shut-Off Valve | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 554 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Instance on Room 554 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Power Supply | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Instance on Room 554 | Does not Exist |
| Instructor Unit | |
| Instance on Rooms 614, 620, 622, 640, 646 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Student Unit | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Meter Demonstration Unit | |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---|--------------------------|
| SCIENCE LAB | |
| Power Supply | Inspected |
| Meter Demonstration Unit | |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Rooms 614, 620, 622, 640, 646 | Does not Exist |
| Instance on Room 554 | Does not Exist |
| SCIENCE PREP ROOM | Inspected |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Lighting | Inspected |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| Emergency Gas Shut-Off Valve | Inspected |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | Inspected |
| Instance on Rooms 616, 618, 642, 644 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Power Supply | Does not Exist |
| Instance on Rooms 616, 618, 642, 644 | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---|----------------------------|
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 415,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Inspected |
| Automatic Transfer Switch (ATS) | Inspected |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | ATS-2 |
| Capacity/Size Quantity | 150 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | ATS-3 |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|--|-------------------------------|
| EMERGENCY GENERATOR SET | |
| Automatic Transfer Switch (ATS) | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | ATS -FA |
| Capacity/Size Quantity | 100 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | MTS-1 |
| Capacity/Size Quantity | 200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | ASCO |
| Equipment | ATS-1 |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Battery Charger | Inspected |
| Instance | Outdoor - Generator Enclosure |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | MTU onsite energy |
| Equipment | Battery Charger |
| Capacity/Size Quantity | 10 |
| Capacity/Size UOM | AmpsDC |
| Capacity/Size2 Quantity | 24 |
| Capacity/Size2 UOM | VDC |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2010 |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---|---|
| EMERGENCY GENERATOR SET | |
| Battery Charger | Inspected |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Diesel | Inspected |
| Instance | Outdoor - Generator Enclosure |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | MTU onsite energy |
| Equipment | Emergency Generator |
| Capacity/Size Quantity | 687 |
| Capacity/Size UOM | KVA |
| Capacity/Size2 Quantity | 550 |
| Capacity/Size2 UOM | KW |
| Capacity/Size3Quantity | 1,908 |
| Capacity/Size3 UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Natural Gas | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not Exist |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | By Staircase C & D (2nd, 5th & 8th Floor), By Staircase E & F (2nd, 5th & 8th Floor), Auditorium - Left Upper Balcony, Outside Room 228 |
| Deficiency Quantity | 9 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 1 - Good |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | 5th Floor Cafeteria |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---------------------------------------|---|
| EXIT LIGHT | |
| Battery Pack | Inspected |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Girls Locker Room 212, Locker Room G114 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EXIT/EMERGENCY LIGHT | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CITY FIRE ALARM SYSTEM | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | |
| Replacement Quantity | 415,000 |
| Replacement Uom | S.F. |
| Bell/Horn | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Strobe | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| CO Detector | |
| Condition | Does not Exist |
| Heat Detector | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Elevator Recall | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | |
| Condition | Does not Exist |
| Fused Cutout Panel | |
| Condition | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|--|---------------------------------|
| FIRE ALARM SYSTEM | |
| Fused Cutout Panel | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | 4th Floor - Main Entrance Lobby |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | General Electric |
| Equipment | Fire Alarm Control Panel |
| Model | EST 3 |
| Capacity/Size Quantity | 12 |
| Capacity/Size UOM | Zones |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2013 |
| Source of Installation | Custodial Staff |
| Deficiency | SYSTEM DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR SYSTEM |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fire Alarm Control Panel (Standard) | Does not Exist |
| Sub-Panel | Does not Exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not Exist |
| Panel | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---|--|
| GROUNDING SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not Exist |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Penthouse Fan Room (West), 1st Floor Fan Rooms (East, West), Boiler Room, Electrical Closet C491 |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Penthouse - Elevator Machine Rooms (East, West), Kitchen (4th Floor, 5th Floor, 8th Floor), Inside Rooms 554, 566, Boiler Room, By Auditorium Balcony, Gymnasium, By Rooms 100, A160, G112, A176, 208, 224, 228, 308B, 328, 332, 334, 342, 344, 364, 406, 428, 438, 464B, 504, 510B, 528, 564, 608, 610, 622, 628, 704, 708B, 728, 746, 762, 828 |
| Deficiency Quantity | 53 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|---|---|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | 3rd Floor Kitchen, By Rooms G112, 100, 228, 364, Penthouse - East Elevator Machine Room, Boiler Room, Gymnasium |
| Deficiency Quantity | 11 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Penthouse Elevator Machine Room (East, West) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | By Rooms 342, 428 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | By Rooms 546, 808, 864 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|-------------------------------|-------------------------------|
| PUBLIC ADDRESS SYSTEM | |
| Replacement Quantity | 415,000 |
| Replacement Uom | S.F. |
| Instance | Room 424I |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Biamp MPA 250 |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Classrooms and Corridors |
| Deficiency Quantity | 50 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | |
| | Inspected |
| IPDVS/CCTV System | |
| | Inspected |
| Replacement Quantity | 415,000 |
| Replacement Uom | S.F. |
| Installation Year | 2007 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | |
| | Inspected |
| Replacement Quantity | 415,000 |
| Replacement Uom | S.F. |
| Central Control Panel | |
| | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 1 - Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128BPT |
| Installation Year | 2014 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | |
| | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| | Inspected |
| Condition | 5 - Poor |
| Deficiency | SWITCH NOT OPERATIONAL |
| Deficiency Location/Instance | Principal's Office (Room 426) |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|-------------------------------------|---------------------------|
| SECURITY | |
| Intrusion Alarm System | |
| Panic Switch | |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Remote Annunciator | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Siren/Strobe | |
| Condition | Inspected |
| Deficiency | 1 - Good |
| Ultrasonic Sensor | |
| Condition | Does not Exist |
| Lighting - Security | |
| Condition | Inaccessible |
| SERVICE SWITCH | |
| Instance | Inspected |
| Instance Condition | Electrical Room |
| Instance Quantity | 2 - Between Good and Fair |
| Instance Quantity Uom | 1 |
| Instance Manufacturer | EACH |
| Equipment | All City Switchboard |
| Capacity/Size Quantity | Service Switch #1 |
| Capacity/Size UOM | 4,000 |
| Source of Capacity/Size | Amps |
| Installation Year | Nameplate |
| Source of Installation | 2010 |
| Deficiency | Custodial Staff |
| Instance | No deficiencies recorded |
| Instance Condition | Electrical Room |
| Instance Quantity | 2 - Between Good and Fair |
| Instance Quantity Uom | 1 |
| Instance Manufacturer | EACH |
| Equipment | All City Switchboard |
| Capacity/Size Quantity | Service Switch #1 SWB#2 |
| Capacity/Size UOM | 4,000 |
| Source of Capacity/Size | Amps |
| Installation Year | Nameplate |
| Source of Installation | 2010 |
| Deficiency | Custodial Staff |
| Instance | No deficiencies recorded |
| SWITCHBOARD | |
| Number of Spares | Inspected |
| Instance | 1 |
| Air Circuit Breaker Type | |
| Instance | Does not Exist |
| Fused Disconnect Switch Type | |
| Instance | Inspected |
| Instance Condition | Electrical Room |
| Instance Quantity | 2 - Between Good and Fair |
| Instance Quantity Uom | 1 |
| Instance Manufacturer | EACH |
| Equipment | All City Switchboard |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|---|---|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Equipment | N/A |
| Capacity/Size Quantity | 4,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 6 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | All City Switchboard |
| Equipment | Service and Distribution Switchboard #1 |
| Capacity/Size Quantity | 4,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 3 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | All City Switchboard |
| Equipment | EM SWBD (Emergency Generator Switchboard) |
| Capacity/Size Quantity | 2,000 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Does not Exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X475

| Question | Response |
|------------------------------|----------------------------|
| TRANSFORMER | |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Jefferson Electric |
| Equipment | N/A |
| Capacity/Size Quantity | 300 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1972 |
| Source of Installation | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Instance | Electrical Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Hammond |
| Equipment | N/A |
| Capacity/Size Quantity | 500 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Hammond |
| Equipment | XFMR-6 225KVA |
| Capacity/Size Quantity | 225 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Generator Switchboard Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X475

| Question | Response |
|-------------------------|--|
| TRANSFORMER | |
| Instance Manufacturer | Hammond |
| Equipment | XFMR-7 225KVA |
| Capacity/Size Quantity | 75 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2010 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Penthouse - East Elevator Machine Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Warner Power |
| Equipment | N/A |
| Capacity/Size Quantity | 63 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2003 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| TV SYSTEM | Does not Exist |