

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Asset: I.S. 201 - BROOKLYN, 8010 12 AVENUE, New York, 11228

Inspection Id	Inspection Type	Time In	Last Edited
EE : K201	Electrical	2017-10-13 8:06 AM	2017-11-22 5:39 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Security Lights
	Years: Under construction
	Systems: Interior Lighting (Except Auditorium, Library, Staff and Student Toilet Rooms)
	Years: 2016
	Systems: Fire Alarm System (Except Sprinkler Flow/Air Pressure Switch), Public Address System, Local Sound System, Exit Lights (Battery Pack)
	Years: 2015
	Systems: Telephone System
	Years: 2012
	Systems: Intercom System (Elevator), Surface Fluorescent Lighting (Students Toilet Rooms)
	Years: 2011
	Systems: Auditorium
	Years: 2010
	Systems: LAN, Library
	Years: 2007
	Systems: Emergency Light/Exit Light Panel, Fused Disconnect Switch Type Panel Board
	Years: 2000
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1995, 2000
	Systems: Staff Toilet Lighting, Pendent Fluorescent Lighting (Students Toilet Rooms)
	Years: 1995
	Systems: Intrusion Alarm System
	Years: 1993

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms (201, 301, 401, 501)

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	John Troy	Custodian	Sent to DSF	
Yes	Intercom - Does Not Exist	N/A	Intercom System - Holding/Fire Rescue Area	Rooms (201, 301, 401, 501)	JOHN TROY	Custodian	Sent to DSF	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	Yes
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 206	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 206	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 206	Inspected
Pendant Mounted	Inspected
Instance on Room 206	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 206	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 206	Does not Exist
Lighting Fixture - HID	
Instance on Room 206	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 206	Does not Exist
Lighting Fixture - LED	
Instance on Room 206	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 206	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 3rd Floor, 5th Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor, 5th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor, 5th Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor, 5th Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor, 5th Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor, 5th Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor, 5th Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 3rd Floor, 5th Floor	Does not Exist
Recessed Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Question	Response
GYMNASIUM	
Lighting	Inspected
Lighting Fixture - LED	
Recessed Mounted	
Instance on 3rd Floor, 5th Floor	Does not Exist
Local Sound System	Inspected
Instance on 3rd Floor, 5th Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 3rd Floor, 5th Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 3rd Floor, 5th Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor, 5th Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 301	Inspected
Lighting	Inspected
Instance on Room 301	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 301	Inspected
Pendant Mounted	Does not Exist
Instance on Room 301	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 301	Does not Exist
Recessed Mounted	Inspected
Instance on Room 301	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 301	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 301	Does not Exist
Lighting Fixture - LED	
Instance on Room 301	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 301	Does not Exist
Projection System	Does not Exist
Instance on Room 301	Does not Exist
LOCKER ROOM	Inspected
Instance on 4th Floor	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Surface Mounted	Inspected
Instance on 4th Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 405, 407, 408,409	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Rooms 405, 407, 408,409	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 405, 407, 408,409	Inspected
Pendant Mounted	Inspected
Instance on Rooms 405, 407, 408,409	Inspected
Condition	1 - Good

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 405, 407, 408,409	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 405, 407, 408,409	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 405, 407, 408,409	Does not Exist
Projection System	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
Power Supply	Does not Exist
Instance on Rooms 405, 407, 408,409	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 452	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 452	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 452	Inspected
Pendant Mounted	Inspected
Instance on Room 452	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 452	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 452	Does not Exist
Lighting Fixture - HID	
Instance on Room 452	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 452	Does not Exist
Lighting Fixture - LED	
Instance on Room 452	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 452	Does not Exist
Emergency Shut-Off Power	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
SCIENCE PREP ROOM	Inspected
Emergency Shut-Off Power	Does not Exist
Instance on Room 452	Does not Exist
Power Supply	Does not Exist
Instance on Room 452	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	108,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, 5th Floor Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	108,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1 - Good

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
FIRE ALARM SYSTEM	
CO Detector	Inspected
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST
Capacity/Size Quantity	16
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	12061622R
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
MOTOR CONTROL CENTER	
MOTOR STARTER/CONTACTOR	
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (211, 411, 415), By Cafeteria
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (202, 254, 356, 302, 402, 453, 457, 417, 557, 553, 502), Room 313, Cafeteria, Kitchen, Auditorium
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, By Rooms (112, 306A, 402)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	By Cafeteria, Gymnasium, Auditorium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
Replacement Quantity	Inspected
Replacement Uom	108,000
Replacement Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance	General Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	108,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1993
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Under Construction
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Serv. Sw
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1965
Source of Installation	Documented

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K201

Question	Response
SERVICE SWITCH	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	3
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K201

Question	Response
TV SYSTEM	
Main Equipment Rack	Does not Exist
