

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Asset: PS 310 THE SCHOOL FOR FUTURE LEADERS - BROOKLYN, 942 62 STREET, New York, 11219

Inspection Id	Inspection Type	Time In	Last Edited
EE : K310	Electrical	2018-12-21 9:20 AM	2019-06-03 1:57 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components
	Years: 2012

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Electrical Room Used as Storage	N/A	Electrical Equipment	Electrical Room C13, ATS Room C11	James Frammarino	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
CAFETERIA	
Local Sound System	
Instance on Basement	Inspected
Installation Year	2012
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
GYMNASIUM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2012
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Scoreboard	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Does not Exist
Recessed Mounted	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 401	Inspected
Lighting	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K310

Question	Response
LIBRARY	
Lighting	
Instance on Room 401	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 401	Inspected
Pendant Mounted	
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 401	Does not Exist
Recessed Mounted	
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 401	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 401	Does not Exist
Lighting Fixture - LED	
Instance on Room 401	Does not Exist
Raceway With Receptacles	
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 401	Does not Exist
LOCKER ROOM	
	Does not Exist
MULTIPURPOSE ROOM	
	Does not Exist
SCIENCE DEMO ROOM	
	Does not Exist
SCIENCE LAB	
Instance on Room 501	Inspected
Power Panel Alternative use	Yes No
Lighting	
Instance on Room 501	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 501	Inspected
Pendant Mounted	
Instance on Room 501	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 501	Does not Exist
Recessed Mounted	
Instance on Room 501	Does not Exist
Lighting Fixture - HID	
Instance on Room 501	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 501	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Does not Exist
Instance on Room 501	Does not Exist
Surface Mounted	Inspected
Instance on Room 501	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 501	Does not Exist
Lighting Fixture - LED	
Instance on Room 501	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 501	Does not Exist
Emergency Shut-Off Power	Inspected
Instance on Room 501	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 501	Inspected
Instructor Unit	
Instance on Room 501	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 501	Does not Exist
Meter Demonstration Unit	
Instance on Room 501	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 501	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 501A	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 501A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 501A	Inspected
Pendant Mounted	Inspected
Instance on Room 501A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 501A	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 501A	Does not Exist
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Room 501A	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 501A	Does not Exist
Lighting Fixture - LED	
Instance on Room 501A	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 501A	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 501A	Does not Exist
Power Supply	Does not Exist
Instance on Room 501A	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	ATS Room C11
Instance Condition	2 - Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K310

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room C11
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room C11
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room C01b
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Firetrol
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof Generator Enclosure

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
EMERGENCY GENERATOR SET	
Battery Charger	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Room Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	303
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	242
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	840
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
FIRE ALARM SYSTEM	
Replacement Quantity	52,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 3
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K310

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	Inspected
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Instance	Telecom Room 205
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
SECURITY	Inspected
Lighting - Security	
Replacement Quantity	29
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Switch #1
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Switch #2
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Switch #3, Fire Pump
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	12
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	ATS Room C11
Instance Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A (Emergency Generator Switchboard)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room R01
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MDB
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K310

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	Elevator Machine Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Jefferson Electric
Equipment	A
Capacity/Size Quantity	42
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Elevator Machine Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Jefferson Electric
Equipment	B
Capacity/Size Quantity	42
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded