

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Asset: P.S. 15 - MANHATTAN, 333 EAST 4 STREET, New York, 10009

Inspection Id	Inspection Type	Time In	Last Edited
EE : M015	Electrical	2018-01-22 11:15 AM	2018-06-06 4:34 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System, Intrusion Alarm System (Partial Remote Annunciator)
	Years: 2017
	Systems: Interior Lighting - Except (Cafeteria, Library, Toilet Rooms, Girls Locker Room), Public Address System, Local Sound System, Telephone System, LAN
	Years: 2016
	Systems: Fluorescent Lighting (Girls Locker Room, Toilet Rooms)
	Years: 2009
	Systems: Partial Security Lights, Partial Molded Case Circuit Breaker Panel Board, Service Switch, Switchboard, Grounding System
	Years: 2008
	Systems: Library
	Years: 2006
	Systems: Emergency Light/Exit Light Panel
	Years: 2004
	Systems: Intrusion Alarm System
	Years: 2001
	Systems: Interior Fluorescent Lighting
	Years: 1995, 2009, 2016
	Systems: Cafeteria (Fluorescent Lighting)
	Years: 1995

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Exit Light - Not Operational	N/A	EXIT LIGHT Battery Pack	Gymnasium, Auditorium, Boiler Room, By Rooms 120, 217, 417	Angelo Pastore	Fireman	Sent to DSF	
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Auditorium	Angelo Pastore	Fireman	Sent to DSF	
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Meter Room	Angelo Pastore	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
AUDITORIUM	Inspected
Theater Lighting System	
Theater Lighting	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Does not Exist
Lighting Fixture - HID	
Condition	Does not Exist
Lighting Fixture - Incandescent	
Condition	Does not Exist
Lighting Fixture - LED	
Pendant Mounted	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Does not Exist
Recessed Mounted	
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	
Condition	Does not Exist
GYMNASIUM	
Condition	Inspected
Instance on 3rd Floor	Inspected
Lighting	
Condition	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Inspected
Condition	Inspected
Deficiency	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor	Does not Exist
Recessed Mounted	
Instance on 3rd Floor	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not Exist
Local Sound System	
Condition	Inspected
Instance on 3rd Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
GYMNASIUM	
Local Sound System	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 3rd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 308	Inspected
Lighting	Inspected
Instance on Room 308	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 308	Inspected
Pendant Mounted	Inspected
Instance on Room 308	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 308	Does not Exist
Recessed Mounted	Inspected
Instance on Room 308	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - HID	
Instance on Room 308	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 308	Does not Exist
Lighting Fixture - LED	
Instance on Room 308	Does not Exist
Raceway With Receptacles	
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 308	Does not Exist
LOCKER ROOM	
Instance on 3rd Floor - Boys	Inspected
Alternative use	Yes
Instance on 4th Floor - Girls	Inspected
Alternative use	Yes
Lighting	
Instance on 4th Floor - Girls	Inspected
Instance on 3rd Floor - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor - Girls	Inspected
Instance on 3rd Floor - Boys	Inspected
Pendant Mounted	
Instance on 4th Floor - Girls	Does not Exist
Instance on 3rd Floor - Boys	Does not Exist
Surface Mounted	
Instance on 4th Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Boys	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 4th Floor - Girls	Does not Exist
Instance on 3rd Floor - Boys	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor - Girls	Does not Exist
Instance on 3rd Floor - Boys	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor - Girls	Does not Exist
Instance on 3rd Floor - Boys	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor - Girls	Does not Exist
Instance on 3rd Floor - Boys	Does not Exist
MULTIPURPOSE ROOM	
Does not Exist	
SCIENCE DEMO ROOM	
Does not Exist	

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	60,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Auditorium, Boiler Room, By Rooms 120, 217, 417
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
	Does not Exist
CITY FIRE ALARM SYSTEM	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Replacement Quantity	60,000
Replacement Uom	S.F.
Bell/Horn	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2017
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Electrical Meter Room, Cafeteria, Pump Room (Basement)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Basement Corridor - By Supply Room, Basement - By Electrical Cage
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen, Basement - By Electrical Cage
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	60,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor XL
Installation Year	2016
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SECURITY	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
SECURITY	
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	60,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	2001
Source of Installation	Inspector Estimate
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not Exist
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	24
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Canopy (Exit 2 Entrance), Exterior Walls facing 5th Avenue
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Canopy (Main Entrance, Exit 2 Entrance)
Deficiency Quantity	8
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M015

Question	Response
SECURITY	
Lighting - Security	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Meter Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	17
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Basement - Electrical Cage
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Switchboard MDS
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M015

Question	Response
TV SYSTEM	
Cable System Exist? Operational?	Yes No
Main Equipment Rack	Does not Exist
