

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Asset: P.S. 33 - MANHATTAN, 281 9TH AVENUE, New York, 10001

Inspection Id	Inspection Type	Time In	Last Edited
EE : M033	Electrical	2018-01-23 8:32 AM	2018-01-30 2:50 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Interior Lighting, Emergency Lighting (Non Battery Pack), Telephone System, LAN
	Years: 2015
	Systems: Auditorium (Projection System)
	Years: 2012
	Systems: Fire Alarm System
	Years: 2010
	Systems: Intercom System, Most Motor Starters
	Years: 2009
	Systems: Public Address System, Local Sound System, Auxiliary Signal/Bell System, Emergency Light/Exit Light Panel, Exit Lights (Battery Pack), Most Molded Case Circuit Breaker Panel Board
	Years: 2008
	Systems: Service Switch, Switchboard, Grounding System
	Years: 2007
	Systems: Intrusion Alarm System
	Years: 2006
	Systems: Most Security Lights
	Years: 2005, 2007

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Security Lights	Canopy (Exit 2, 4)	George Madine	Custodian	Sent to DSF	
Yes	Intercom - Not Operational	N/A	INTERCOM SYSTEM Elevator	Elevator - Device ID: 1P32606	George Madine	Custodian	Sent to DSF	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	George Madine	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2008
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	46
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	2008
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Recessed Mounted	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2008
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
GYMNASIUM	
Local Sound System	
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on 1st Floor	Does not Exist
Scoreboard	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 201	Inspected
Lighting	
Instance on Room 201	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 201	Inspected
Pendant Mounted	
Instance on Room 201	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 201	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Does not Exist
Instance on Room 201	Does not Exist
Lighting Fixture - HID	
Instance on Room 201	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 201	Does not Exist
Lighting Fixture - LED	
Instance on Room 201	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 201	Does not Exist
Projection System	Does not Exist
Instance on Room 201	Does not Exist
LOCKER ROOM	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	
Lighting Fixture - Fluorescent	Inspected
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	83,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	
	Does not Exist
CITY FIRE ALARM SYSTEM	
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor - By Room 102
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
FIRE ALARM SYSTEM	
Replacement Quantity	83,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	4 - Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator - Device ID: 1P32606
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	PVT597281
Holding Area	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Boiler Room, 3rd Floor Corridor - By Room 344
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 022 (MDF Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Room B1, Mechanical Room 208
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	83,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	83,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M033

Question	Response
SECURITY	
Lighting - Security	
Replacement Quantity	57
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Canopy (Main Entrance, Exit 2, 3, 4), Plaza deck
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electric Switchboard
Equipment	1600 Amp Switch
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDB Section 1, 2, 3
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M033

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Does not Exist
Cable System Exist?	Yes
Operational?	No