

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Asset: P.S. 38 (OLD M121) - MANHATTAN, 232 EAST 103 STREET, New York, 10029

Inspection Id	Inspection Type	Time In	Last Edited
EE : M121	Electrical	2017-10-02 8:05 AM	2017-10-16 2:58 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Interior Fluorescent Lighting (Except Auditorium), Gymnasium (LED Lighting), Emergency Lighting (Non Battery Pack)
	Years: 2017
	Systems: Auditorium, Telephone System, LAN
	Years: 2015
	Systems: Most Exit Lights (Battery Pack)
	Years: 2012
	Systems: Security Lights
	Years: 2010
	Systems: Most Molded Case Circuit Breaker Panel Board
	Years: 2006, 2000, 1990
	Systems: Fused Disconnect Switch Type Panel Board, Switchboard, Fire Alarm System, Public Address System, Local Sound System (Gymnasium, Cafeteria), Emergency Light/Exit Light Panel
	Years: 2006
	Systems: Intrusion Alarm System
	Years: 1992

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2015
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M121

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
	Inspected
Instance on Room 311	Inspected
Power Panel	Yes
Lighting	
Instance on Room 311	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 311	Inspected
Pendant Mounted	Inspected
Instance on Room 311	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 311	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 311	Does not Exist
Lighting Fixture - HID	
Instance on Room 311	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 311	Does not Exist
Lighting Fixture - LED	
Instance on Room 311	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 311	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
LIBRARY	
Instance on Room 214	Inspected
Lighting	Inspected
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 214	Inspected
Pendant Mounted	Inspected
Instance on Room 214	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 214	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 214	Does not Exist
Lighting Fixture - HID	
Instance on Room 214	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 214	Does not Exist
Lighting Fixture - LED	
Instance on Room 214	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 214	Does not Exist
Projection System	Does not Exist
Instance on Room 214	Does not Exist
LOCKER ROOM	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M121

Question	Response
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	72,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	BELL NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Room 134
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BELL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M121

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	
Condition	Inspected
Deficiency	1 - Good
Deficiency Location/Instance	FIXTURE NOT OPERATIONAL
Deficiency Quantity	Auditorium
Quantity Uom	2
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 5
Deficiency Photo1	LEVEL 4
Violations	No photo recorded
	35267472Z
EXIT LIGHT	
Condition	Inspected
Battery Pack	
Condition	Inspected
Deficiency	1 - Good
	No deficiencies recorded
Non Battery Pack	
	Does not Exist
EXIT/EMERGENCY LIGHT	
	Does not Exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	5 - Poor
Deficiency Location/Instance	NOT OPERATIONAL
Deficiency Quantity	Main Entrance Lobby
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 5
Deficiency Photo1	LEVEL 2
Violations	No photo recorded
	No violations recorded.
FIRE ALARM SYSTEM	
Replacement Quantity	Inspected
Replacement Uom	72,000
	S.F.
Bell/Horn	
Condition	Inspected
Deficiency	2 - Between Good and Fair
	No deficiencies recorded
Strobe	
Condition	Inspected
Deficiency	2 - Between Good and Fair
	No deficiencies recorded
Manual Pull Station	
Condition	Inspected
Deficiency	2 - Between Good and Fair
	No deficiencies recorded
Fan Shutdown Control	
Condition	Inspected
Deficiency	2 - Between Good and Fair
	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M121

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Interior Fire Alarm System
Model	AFP - 300
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2006
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Mechanical Room - 2nd Floor (GYM.EXH.), Fan Room - Basement (AUD.BLOWER)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Gymnasium, Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen, Gymnasium, Boiler Room, Projection Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	72,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	72,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	41440XMPT
Installation Year	1992
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	Inspected
Deficiency	5 - Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Principal's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Remote Annunciator	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Condition	Does not Exist
Lighting - Security	
Replacement Quantity	Inspected
Replacement Uom	30
Condition	EACH
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Room
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Standard Switchboard
Capacity/Size Quantity	Service A
Capacity/Size UOM	600
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation	1953
Deficiency	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M121

Question	Response
SERVICE SWITCH	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Standard Switchboard
Equipment	Service B
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1953
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	Inspected
Number of Spares	1
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Switchboard A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M121

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Equipment	Switchboard B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist