

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Asset: P.S. 94 - QUEENS, 41-77 LITTLE NECK PKWY, New York, 11363

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q094	Electrical	2018-12-17 12:18 PM	2019-04-11 4:25 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Telephone System
	Years: 2018
	Systems: Interior Lighting
	Years: 2016
	Systems: Most Emergency Lighting (Battery Pack), Security Lights
	Years: 2014
	Systems: Auditorium (Local Sound System, Projection System)
	Years: 2011
	Systems: Gymnasium (Local Sound System)
	Years: 2007
	Systems: Cafeteria (Local Sound System), Public Address System
	Years: 1998
	Systems: Intrusion Alarm System
	Years: 1996
	Systems: Fused Disconnect Switch Type Panel Board, Emergency Light/Exit Light Panel
	Years: 1993
	Systems: Most Molded Case Circuit Breaker Panel Board
	Years: 1985, 1990, 2000, 2008

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Local Sound System - Not Connected to Public Address System	N/A	AUDITORIUM Local Sound System	1st Floor	Kevin Hunery	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2011
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q094

Question	Response
CAFETERIA	
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	1998
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 203	Inspected
Power Panel	Yes

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
COMPUTER LAB	
Lighting	Inspected
Instance on Room 203	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 203	Inspected
Pendant Mounted	Inspected
Instance on Room 203	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 203	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 203	Does not Exist
Lighting Fixture - HID	
Instance on Room 203	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 203	Does not Exist
Lighting Fixture - LED	
Instance on Room 203	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 203	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q094

Question	Response
GYMNASIUM	
Projection System	Does not Exist
Instance on Basement	Does not Exist
Scoreboard	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
KITCHEN	
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q094

Question	Response
MULTIPURPOSE ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Does not Exist
Instance on Basement	Does not Exist
Projection System	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	38,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Multipurpose Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Room B27, 1st Floor Corridor by Staircase 1
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	38,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
FIRE ALARM SYSTEM	
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm
Capacity/Size Quantity	4
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	38,000
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q094

Question	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Room 203
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors by Rooms 208, 161, 108, Cafeteria, Gymnasium, Boiler Room, Electrical Room
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	38,000

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q094

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	1998
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	38,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1996
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	17
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor By Room 104
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
SECURITY	Inspected
Lighting - Security	
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	I.T.E.
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	Inspected
Number of Spares	5
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Equipment Room (Inside Boiler Room)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	I.T.E. Imperial Corp.
Equipment	MDP
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Equipment Room (Inside Boiler Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q094

Question	Response
SWITCHBOARD	Inspected
Fused Disconnect Switch Type	Inspected
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not Exist