

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Asset: P.S. 127 - QUEENS, 98-01 25 AVENUE, New York, 11369

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q127	Electrical	2019-02-06 8:27 AM	2019-02-25 12:05 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Gymnasium (LED Lighting)
	Years: 2016
	Systems: Interior Lighting (Except Cafeteria, Kitchen)
	Years: 2015
	Systems: Public Address System (Amplifier), Kitchen (Lighting)
	Years: 2014
	Systems: Auditorium (Except Local Sound System), Cafeteria, Telephone System, LAN
	Years: 2011
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 2009
	Systems: Auditorium (Local Sound System)
	Years: 2006
	Systems: Security Lights
	Years: 2006
	Systems: Intrusion Alarm System
	Years: 1996
	Systems: Emergency Light/Exit Light Panel
	Years: 1995
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1992, 2000, 2009

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Main Electrical Switch Room	John Harley	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2011
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
GYMNASIUM	
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Local Sound System	Inspected
Instance on 3rd Floor	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Scoreboard	Inspected
Instance on 3rd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
KITCHEN	
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 301	Inspected
Lighting	Inspected
Instance on Room 301	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 301	Inspected
Pendant Mounted	Inspected
Instance on Room 301	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 301	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - HID	
Instance on Room 301	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 301	Does not Exist
Lighting Fixture - LED	
Instance on Room 301	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 301	Does not Exist
Projection System	Does not Exist
Instance on Room 301	Does not Exist
LOCKER ROOM	Inspected
Instance on 4th Floor	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q127

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 4th Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Surface Mounted	Inspected
Instance on 4th Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 408	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 408	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 408	Inspected
Pendant Mounted	Inspected
Instance on Room 408	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 408	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 408	Does not Exist
Lighting Fixture - HID	
Instance on Room 408	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 408	Does not Exist
Lighting Fixture - LED	
Instance on Room 408	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 408	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Room 408	Does not Exist
Power Supply	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
SCIENCE LAB	Inspected
Power Supply	Does not Exist
Instance on Room 408	Does not Exist
Projection System	Does not Exist
Instance on Room 408	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Exist J, 2nd Floor Corridor by Exit A, Gymnasium, Auditorium, Cafeteria

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35207352J
Non Battery Pack	
Condition	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Cafeteria
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35207352J
EXIT LIGHT	
Inspected	
Battery Pack	
Inspected	
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor By Exit 11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	
Inspected	
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor By Exit 3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	
Does not Exist	
CITY FIRE ALARM SYSTEM	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
Inspected	
Replacement Quantity	94,000
Replacement Uom	S.F.

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm Control Board
Capacity/Size Quantity	8
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1966
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	94,000
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q127

Question	Response
FIRE ALARM SYSTEM	Inspected
Tamper Flow Switch/Chain	
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Gymnasium Fan Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	Inspected
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Auditorium Protection Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by Room 305, Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
Replacement Quantity	94,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp 301
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	14

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
PUBLIC ADDRESS SYSTEM	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office
Deficiency Quantity	94,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1996
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	38
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof Lights Facing Backyard

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q127

Question	Response
SECURITY	
Lighting - Security	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Main Electrical Switch Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Switch Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	
	Does not Exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q127

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	
	Does not Exist