

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

Asset: **PRE-K CENTER @ 56-01 61ST STREET - QUEENS, 56-01 61ST STREET, New York, 11378**

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q348	Electrical	2018-12-13 11:26 AM	2018-12-13 4:27 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Other Electrical Systems and Components
	Years: 2016
	Systems: Multipurpose Room (Local Sound System)
	Years: 2000

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on Basement	Inspected
Installation Year	2000
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

<b>Question</b>	<b>Response</b>
<b>MULTIPURPOSE ROOM</b>	
<b>Local Sound System</b>	
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting System</b>	
Instance on Basement	Inspected
<b>Dimming System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting</b>	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SCIENCE DEMO ROOM</b>	
Does not Exist	
<b>SCIENCE LAB</b>	
Does not Exist	
<b>SCIENCE PREP ROOM</b>	
Does not Exist	
<b>SWIMMING POOL</b>	
Does not Exist	
<b>TOILET ROOM - STAFF</b>	
Inspected	
<b>Lighting</b>	
Inspected	
<b>Lighting Fixture - Fluorescent</b>	
Inspected	
<b>Pendant Mounted</b>	
Does not Exist	
<b>Surface Mounted</b>	
Inspected	
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Inspected	
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Does not Exist	
<b>Lighting Fixture - Incandescent</b>	
Does not Exist	
<b>Lighting Fixture - LED</b>	
Does not Exist	
<b>TOILET ROOM - STUDENT</b>	
Inspected	
<b>Lighting</b>	
Inspected	
<b>Lighting Fixture - Fluorescent</b>	
Inspected	
<b>Pendant Mounted</b>	
Does not Exist	
<b>Surface Mounted</b>	
Does not Exist	
<b>Recessed Mounted</b>	
Inspected	
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

Question	Response
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Heat Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Does not Exist
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	Fire Alarm Control
Model	FX - 2000
Capacity/Size Quantity	9
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

<b>Question</b>	<b>Response</b>
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Does not Exist
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Instance	Room 106
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Installation Year	2016
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Room 106
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BPT
Installation Year	2016
Source of Installation	Documented

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q348

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	Inspected
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	9
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Disconnect
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	MDB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size

NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q348

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	Inspected
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Does not Exist