

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

**Asset: DISTRICT 27 PRE-K CENTER @ 101-49 WOODHAVEN BOULEVARD - QUEENS,  
 101-49 WOODHAVEN BOULEVARD, New York, 11416**

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q439	Mechanical	2020-07-16 11:39 AM	2020-07-30 7:29 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not Exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not Exist
<b>Cooling Coil in Ductwork</b>	Does not Exist
<b>Cooling Tower</b>	Does not Exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not Exist
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Source of Heating	N/A
Instance Manufacturer	Daikin
Equipment	RTU-S-1-1, RTU-S-1-2
Capacity/Size Quantity	3
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

Question	Response
<b>AIR CONDITIONING</b>	
<b>Packaged / Rooftop Unit</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	N/A
Instance Manufacturer	Daikin
Equipment	RTU-S-2
Capacity/Size Quantity	7
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Lower Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	N/A
Instance Manufacturer	Daikin
Equipment	RTU-N
Capacity/Size Quantity	7
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Packaged Terminal A/C</b>	Does not Exist
<b>Refrigerant Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not Exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not Exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Pneumatic System</b>	Does not Exist
<b>Hybrid System</b>	Does not Exist
<b>Electric System</b>	Does not Exist
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiter</b>	Does not Exist
<b>Elevator</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

Question	Response
<b>CONVEYING</b>	
<b>Elevator</b>	Inspected
Are all the existing elevators operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not Exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Inspected
Are all the existing non-auditorium vertical handicap lifts operable?	Yes
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non-auditorium Handicap Lift - Stair</b>	Does not Exist
<b>Ash Hoist</b>	Does not Exist
<b>Sidewalk Elevator</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not Exist
<b>Pressure Booster System</b>	Does not Exist
<b>Water Service</b>	Inspected
Instance	Room C10
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Instance	Room C01B
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not Exist
<b>Domestic Water Heat Exchanger</b>	Does not Exist
<b>Electric Domestic Water Heater</b>	Does not Exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Room C08
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	A.O. Smith
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	74
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Does not Exist
<b>Sump Pump</b>	Does not Exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not Exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Does not Exist
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not Exist
<b>GAS FIRED FURNACE</b>	Does not Exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not Exist
<b>Gas Meter Room Vent</b>	Inspected
Condition	1 - Good

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

Question	Response
<b>GAS SERVICE</b>	
<b>Gas Meter Room Vent</b>	Inspected
Deficiency	No deficiencies recorded
<b>Gas Pressure Booster</b>	Does not Exist
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not Exist
<b>Hydronic Heating</b>	Inspected
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Does not Exist
<b>Hot Water Heat Exchanger</b>	Does not Exist
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Does not Exist
<b>Steam supplied by External Sources</b>	Does not Exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	522
Replacement Uom	MBH Net
Instance on Basement	Inspected
Burner Type	Gas
Heating Plant Oil Number	N/A
<b>Boiler Auxiliaries</b>	Inspected
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Does not Exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Does not Exist
<b>Boiler Flue Exhaust</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Does not Exist
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Does not Exist
<b>Boiler Safety Valve</b>	
Instance on Basement	Does not Exist
<b>Boiler System</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not Exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not Exist
<b>Modular Boiler</b>	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	522
Instance Quantity Uom	MBH Net
Instance Manufacturer	Clever Brooks
Equipment	B-1
Capacity/Size Quantity	750
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Steam Boiler</b>	
Instance on Basement	Does not Exist
<b>Fuel System</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Does not Exist
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Does not Exist
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Does not Exist
<b>Enclosed IDF Room</b>	
Instance on 1st Floor	Does not Exist
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

Question	Response
<b>KITCHEN</b>	
<b>CO Detector</b>	Not Required
Instance on 1st Floor	Not Required
<b>Gas System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Grease Trap</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hood Fire Suppression System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hot Water Temperature Booster</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Kitchen Sink</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	Inspected
Instance on Room 124	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Room 124	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Wet Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Fire Booster Pump Assembly</b>	Does not Exist
<b>Roof Tank</b>	Does not Exist
<b>Siamese Connection</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2019 - 2020**

Mechanical Inspection

Q439

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Sprinkler Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Does not Exist
<b>Water Gong</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Approximate Total # of Fans	1-25
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not Exist
<b>Metal Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not Exist
<b>Unit Ventilator</b>	Does not Exist