

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Asset: MIDDLE COLLEGE CAMPUS - QUEENS, 45-35 VAN DAM STREET, New York, 11101

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q520	Electrical	2018-04-17 12:19 PM	2018-04-19 4:21 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Security Lights
	Years: 2012, 2018
	Systems: All Other Electrical Systems and Components
	Years: 2012
	Systems: Switchboard, Molded Case Circuit Breaker Panel Board, Fused Disconnect Switch Type Panel Board
	Years: 1980, 2012

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Exit Light - Not Operational	N/A	EXIT LIGHT Battery Pack	2nd Floor Corridor	Gus Vidhja	Handyman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2012
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
Instance on Rooms 210, 252	Inspected
Power Panel	Yes
Lighting	
Instance on Rooms 210, 252	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 210, 252	Inspected
Pendant Mounted	
Instance on Rooms 210, 252	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 210, 252	Does not Exist
Recessed Mounted	
Instance on Rooms 210, 252	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 210, 252	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 210, 252	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
COMPUTER LAB	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Rooms 210, 252	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 210, 252	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GYMNASIUM	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Rooms 223, 224, 253, 258	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 243	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 243	Inspected
Instance on Rooms 223, 224, 253, 258	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 243	Inspected
Instance on Rooms 223, 224, 253, 258	Inspected
Pendant Mounted	Inspected
Instance on Room 243	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q520

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Lighting Fixture - HID	
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 243	Inspected
Instance on Rooms 223, 224, 253, 258	Inspected
Pendant Mounted	Does not Exist
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Surface Mounted	Inspected
Instance on Room 243	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Lighting Fixture - LED	
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 243	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 243	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	Inspected
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 243	Inspected
Instance on Rooms 223, 224, 253, 258	Inspected
Instructor Unit	
Instance on Room 243	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
Meter Demonstration Unit	
Instance on Room 243	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Rooms 223, 224, 253, 258	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 243	Does not Exist
Instance on Rooms 223, 224, 253, 258	Does not Exist
SCIENCE PREP ROOM	
Instance on Rooms 221, 256	Inspected
Power Panel	No
Alternative use	No
Lighting	
Instance on Rooms 221, 256	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 221, 256	Inspected
Pendant Mounted	
Instance on Rooms 221, 256	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 221, 256	Does not Exist
Recessed Mounted	
Instance on Rooms 221, 256	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 221, 256	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 221, 256	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 221, 256	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 221, 256	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Rooms 221, 256	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Rooms 221, 256	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room 124A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #1 400A to EDP
Capacity/Size Quantity	400

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q520

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 124A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #2 to PR-TR
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 124A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	Fire Alarm ATS #3
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	12
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Roof Generator Enclosure
Instance Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	156
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	125
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	434
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	4 - Between Fair and Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (105, 152)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
CITY FIRE ALARM SYSTEM	Inspected
Violations	No violations recorded.
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Fire Alarm Control Panel
Model	N/A
Capacity/Size Quantity	8

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
FIRE ALARM SYSTEM	Inspected
Main Panel	
Fire Alarm Control Panel (Electronic)	
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Instance	Main Telecom Room 122
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	52,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	41
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Electrical Room 135
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Pringle
Equipment	Service Switch #1
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Pringle
Equipment	Service Switch #2
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Eaton
Equipment	Spare
Capacity/Size Quantity	600

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	11
Air Circuit Breaker Type	
	Does not Exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room 135
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Atlas Switch
Equipment	MDSB-1
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Eaton
Equipment	MDSB 1A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Atlas Switch
Equipment	MDSB-2
Capacity/Size Quantity	1,800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

Q520

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Eaton
Equipment	MDSB #2A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 124A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Eaton
Equipment	Emergency Distribution Panel EDP (Emergency Generator Switchboard)
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist