

**NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q906

**Asset:** P.S. 16 TRANSPORTABLE - Q, 41-15 104 STREET, New York, 11368

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q906	Electrical	2021-01-12 8:32 AM	2021-01-21 3:14 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Other Electrical Systems and Components
	Years: 2015
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1997

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Electrical</b>	
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q906

Question	Response
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	5,600
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Does not Exist
<b>Duct Smoke Detector</b>	Does not Exist
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Fused Cutout Panel</b>	Does not Exist
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	TC-1
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	Fire Alarm Control Panel
Model	FX - 2000
Capacity/Size Quantity	4
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Does not Exist
<b>GROUNDING SYSTEM</b>	Does not Exist
<b>LAN</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2020 - 2021**

Electrical Inspection

Q906

Question	Response
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Does not Exist
<b>PANEL BOARD</b>	Inspected
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	5,600
Replacement Uom	S.F.
Instance	Connected to Main Asset Q721
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	5,600
Replacement Uom	S.F.
Installation Year	2015
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	5,600
Replacement Uom	S.F.
<b>Central Control Panel</b>	Does not Exist
<b>Infrared Sensor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Does not Exist
<b>Remote Annunciator</b>	Does not Exist
<b>Siren/Strobe</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	6
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Does not Exist
<b>SWITCHBOARD</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

NYC Department of Education  
Building Condition Assessment Survey 2020 - 2021

Electrical Inspection

Q906

Question	Response
<b>TELEPHONE SYSTEM</b>	
Standard	Does not Exist