

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q943

Asset: B. N. CARDOZO HS TRANSPORTABLE - Q, 57-00 223 STREET, New York, 11364

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : Q943 | Electrical | 2019-05-06 1:43 PM | 2019-05-14 4:46 PM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | No |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: LAN, Telephone System |
| | Years: 2010 |
| | Systems: Surface Fluorescent Lighting (Except Students Toilet Rooms) |
| | Years: 1997, 2016 |
| | Systems: All Other Electrical Systems and Components |
| | Years: 1997 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded | | | | | | | | |

Inspection

| Question | Response |
|--|---------------------------|
| Electrical | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| COMPUTER LAB | Does not Exist |
| TOILET ROOM - STAFF | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q943

| Question | Response |
|--|---------------------------|
| EMERGENCY LIGHTING | Does not Exist |
| EXIT LIGHT | Does not Exist |
| EXIT/EMERGENCY LIGHT | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 2,600 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not Exist |
| Duct Smoke Detector | Does not Exist |
| Area Smoke Detector | Does not Exist |
| CO Detector | Does not Exist |
| Fused Cutout Panel | Does not Exist |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | T-1 |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Edwards System Technology |
| Equipment | Fire Alarm Control Panel |
| Model | EST |
| Capacity/Size Quantity | 4 |
| Capacity/Size UOM | Zones |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Diagram |
| Installation Year | 1997 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Does not Exist |
| GROUNDING SYSTEM | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q943

| Question | Response |
|---|------------------------------|
| LAN | Inspected |
| Main Equipment Rack (MDF) | Does not Exist |
| PANEL BOARD | Inspected |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 2,600 |
| Replacement Uom | S.F. |
| Instance | Connected to Main Asset Q415 |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | N/A |
| Installation Year | 1997 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | Inspected |
| IPDVS/CCTV System | Does not Exist |
| Intrusion Alarm System | Does not Exist |
| Lighting - Security | Inspected |
| Replacement Quantity | 4 |
| Replacement Uom | EACH |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Does not Exist |
| SWITCHBOARD | Does not Exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | Does not Exist |