

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

School: P.S. 16 - STATEN ISLAND, 80 MONROE AVENUE, STATEN ISLAND, NY, 10301

InspectionId	Inspection Type	Time In	Last Edited
3950	ELECTRICAL	2019-04-22 08:09AM	2019-04-22 03:47PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Gymnasium (Scoreboard), Fused Disconnect Switch Type Panel Board Years: Under Construction Systems: Public Address System (Amplifier), Partial Molded Case Circuit Breaker Panel Board, Emergency Generator Set Years: 2018 Systems: Interior Lighting (Except Library), Emergency Lighting (Non Battery Pack) Years: 2015 Systems: Emergency Lighting (Battery Pack) Years: 2014 Systems: IPDVS/CCTV System Years: 2013 Systems: Auditorium (Local Sound System) Years: 2012 Systems: LAN, Telephone System Years: 2010 Systems: Auditorium (Projection System) Years: 2008 Systems: Lighting - Security Years: 2000, 2006 Systems: Fire Alarm System (Air Pressure Switch, Strobe, Control Panel) Years: 2006 Systems: Emergency Light/Exit Light Panel Years: 2000 Systems: Library (Lighting) Years: 2004 Systems: Intrusion Alarm System Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Sprinkler Flow/Air Pressure Switch	Sprinkler Room B1	Denis Wanamaker	Fireman	No Photo Taken

Inspection

Question	Response
Electrical ATHLETIC FIELD	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
AUDITORIUM	
Instance on 3rd Floor	Inspected
House Lighting	
Instance on 3rd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 3rd Floor	Inspected
Dimming System	
Instance on 3rd Floor	Does not exist
Theater Lighting	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Basement Corridor by Boiler Room B4
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Battery Charger	Does not exist
Diesel	Does not exist
Natural Gas	Inspected
Instance	Outside Generator Enclosure
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Emergency Generator
Capacity/Size Quantity	32
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	25
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	86
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
EXIT LIGHT	
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Corridor by Room B8, 1st Floor Corridor by Exit 9
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
Model	MPC - 6000
EquipmentId	N/A
Capacity/Size Quantity	7
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Violations	No violations recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	5- Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Sprinkler Room B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	92,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 3rd Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
GYMNASIUM	
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Under construction
Theater Lighting System	
Instance on 3rd Floor	Does not exist
INTERCOM SYSTEM	
	Does not exist
KITCHEN	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
LAN	
Local Distribution Frame (I/LDF)	Inspected
Main Equipment Rack (MDF)	Does not exist
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
LIBRARY	
Instance on Room 324/326/328	Inspected
Lighting	
Instance on Room 324/326/328	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 324/326/328	Inspected
Pendant Mounted	
Instance on Room 324/326/328	Does not exist
Recessed Mounted	
Instance on Room 324/326/328	Does not exist
Surface Mounted	
Instance on Room 324/326/328	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 324/326/328	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 324/326/328	Inspected
Pendant Mounted	
Instance on Room 324/326/328	Does not exist
Recessed Mounted	
Instance on Room 324/326/328	Does not exist
Surface Mounted	
Instance on Room 324/326/328	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 324/326/328	Does not exist
Projection System	
Instance on Room 324/326/328	Does not exist
Raceway With Receptacles	
Instance on Room 324/326/328	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not exist
LOCKER ROOM	
	Does not exist
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
Condition	Inspected
Deficiency	3- Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room (House Exhausts 2H, 6H, 7H, 8H, 10H)
Deficiency Quantity	5

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
MOTOR STARTER/CONTACTOR	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	
	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Under construction
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms 323, 405
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Auditorium, Gymnasium, Kitchen, Boiler Room, Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 121
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp Advantage 301
Installation Year	1965
Source of Installation Year	Documented
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	General Office - Room 121
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms, Corridors
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 121
Deficiency Quantity	92,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 112
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Condition	Does not exist
IPDVS/CCTV System	
Condition	Inspected
Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	
Condition	Inspected
Condition	3- Fair
Replacement Quantity	41
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof Perimeter
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
Condition	Inspected
Instance	Electrical Room B5
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Lighting Service
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B5
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
SERVICE SWITCH	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room B5
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B5
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R016

Question	Response
SWITCHBOARD	
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	
	Does not exist
TV SYSTEM	
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist