

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

School: **P.S. 60 - STATEN ISLAND, 55 MERRILL AVENUE, STATEN ISLAND, NY, 10314**

InspectionId	Inspection Type	Time In	Last Edited
2798	ELECTRICAL	2019-03-06 07:59AM	2019-05-01 11:45AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Gymnasium (Scoreboard) Years: 2018 Systems: Interior Fluorescent Lighting, Partial Emergency Lighting (Non Battery Pack) Years: 2012 Systems: Local Sound System, Auditorium (Projection System) Years: 2013 Systems: Public Address System (Amplifier, Tuner) Years: 2002 Systems: Partial Fused Disconnect Switch Type Panel Board Years: 2008 Systems: IPDVS/CCTV System, Telephone System Years: 2010 Systems: Intrusion Alarm System Years: 2011 Systems: Most Lighting - Security Years: 2016 Systems: Emergency Light/Exit Light Panel Years: 1999, 2019 Systems: Battery Pack Emergency Lights Years: 2019
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
Projection System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Theater Lighting System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Inspected	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Does not exist	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	9
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Sprinkler Alarm Control Board
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
EquipmentId	N/A
Capacity/Size Quantity	8
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
GYMNASIUM	
Scoreboard	
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
INTERCOM SYSTEM	
	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 222	Inspected
Lighting	
Instance on Room 222	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 222	Inspected
Pendant Mounted	
Instance on Room 222	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 222	Does not exist
Surface Mounted	
Instance on Room 222	Does not exist
Lighting Fixture - HID	
Instance on Room 222	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 222	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - LED	
Instance on Room 222	Does not exist
Projection System	
Instance on Room 222	Does not exist
Raceway With Receptacles	
Instance on Room 222	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E. Imperial Corp
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	NO SPARE
Deficiency Quantity	Corridor by Room 109
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE PANEL BOARD
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Corridors by Rooms 220, 234
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium, Cafeteria, Electrical Room, Mechanical Room 154, Corridors
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
Instance	Inspected
Instance Condition	General Office - Room 106
Instance Quantity	3- Fair
Instance Quantity Uom	1
Model	EACH
Installation Year	Rauland AP4611
Source of Installation Year	1974
Deficiency	Documented
Deficiency Location/Instance	CLOCK NOT OPERATIONAL
Deficiency Quantity	Corridors, Classrooms
Quantity Uom	25
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 106
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
PUBLIC ADDRESS SYSTEM	
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Replacement Quantity	27
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Canopy by Main Entrance, Bulkheads
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	Main Dist.
Capacity/Size Quantity	2000

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	AC PNL
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	PP HTT
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R060

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2012
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

R060

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist