

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**


School: **P.S. 34 - BRONX, 760 GROTE STREET, BRONX, NY, 10460**

InspectionId	Inspection Type	Time In	Last Edited
1504	MECHANICAL	2019-01-16 07:07AM	2019-02-19 10:37AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Domestic Hot Water System; Boiler Make-up Water Backflow Preventer Years: 2010 Systems: Steam Condensate Return Pumping System Years: 2012 Systems: Boiler refurbished (re-tubed and new refractory) Years: 2013 Systems: DX Split System for Telecom Room 304 (1 of 2); MDF Room - Dedicated A/C Equipment (DX Split System); Sump Pumps Years: 2017 Systems: Electric Pressure Booster System; CO/Gas Leak Detection; F&T/Steam Drip Traps; Kitchen - Hot Water Temperature Booster Years: 2018
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	7,797
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Basement - MER 9, Ejector Pump Room 12, Boiler Room Mechanical Area
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Defective Kitchen Gas System	Defective Shut-Off Switch	Gas System	Kitchen	Jay Gomez	Fireman	

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Inspected
<b>Absorption Chiller</b>	Does not exist
<b>Air Cooled Chiller</b>	Inspected
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	Chiller #1
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	1996
Source of Installation Year	Documented

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X034**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Air Cooled Chiller</b>	
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	Chiller #2
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	Chiller #3
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Air Cooled Condenser</b>	Inspected
Instance	Main Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	ACC-1
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	ACC-2
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X034**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Air Cooled Condenser</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	ACC-3
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Does not exist
<b>Central Station Air Handler</b>	Inspected
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	AHU-1, AHU-3
Capacity/Size Quantity	10
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	AHU-4
Capacity/Size Quantity	15
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
EquipmentId	AHU-5
Capacity/Size Quantity	8
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Central Station Air Handler</b>	
Manufacturer	McQuay
EquipmentId	AHU-6
Capacity/Size Quantity	30
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Chilled Water Distribution: Piping, Pumps and Auxiliaries</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Location/Instance	PIPING:DEFECTIVE/LEAKS
Deficiency Quantity	Basement - MER 9 @ AHU-6
Quantity Uom	10
Potential Action	L.F.
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
	No violations recorded
<b>Fan Coil Unit</b>	
	Does not exist
<b>Packaged Air Cooled Chiller</b>	
	Does not exist
<b>Water Cooled Chiller</b>	
	Does not exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	
	Does not exist
<b>Cooling Coil in Ductwork</b>	
	Does not exist
<b>Cooling Tower</b>	
	Does not exist
<b>Dry Cooler</b>	
	Does not exist
<b>DX Split System</b>	
<b>Indoor Unit</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Outdoor Unit</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Packaged / Rooftop Unit</b>	
	Does not exist
<b>Packaged Terminal A/C</b>	
	Does not exist
<b>Refrigerant Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Return Fan</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DEFECTIVE MOTOR
Deficiency Quantity	Basement - MER 9 / RF #6
Quantity Uom	1
Potential Action	EACH
Urgency of Action	MAINTENANCE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
	No violations recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	
	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	
	Inspected
<b>BMS</b>	
	Inspected
Instance	Throughout
Instance Condition	5- Poor

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

Question	Response
<b>CLIMATE CONTROL SYSTEM</b>	
<b>BMS</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Installation Year	1996
Source of Installation Year	Documented
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Throughout
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Electric System</b>	Does not exist
<b>Hybrid System</b>	Does not exist
<b>Pneumatic System</b>	Does not exist
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Inspected
<b>Ash Hoist</b>	Does not exist
<b>Dumbwaiter</b>	Does not exist
<b>Elevator</b>	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not exist
<b>Non-auditorium Handicap Lift - Stair</b>	Does not exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Does not exist
<b>Sidewalk Elevator</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Inspected
Instance	Basement - MER 9
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	N/A
Capacity/Size Quantity	3
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	9
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Hydraulic/Pneumatic Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
Instance	Basement - Water Meter Room 18, MER - Sprinkler/Gas/Water Meter Room 10
Instance Condition	2- Between Good and Fair
Instance Quantity	3

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X034**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Cold Water System</b>	
<b>Water Service</b>	
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	645
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Under construction
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Inspected
<b>Dual Temperature Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Dual Temperature Terminal Fan Coil Unit</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Enclosed IDF Room</b>	
Instance on Rooms 131, 225, 323, 427	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Rooms 131, 225, 323, 427	Not required
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X034**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Staff And Other</b>	
<b>Janitor Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Does not exist
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Room 210
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Toilet Room 133
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

<b>Question</b>	<b>Response</b>
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Basement - Boiler Room, MER 9 - Sprinkler/Gas/Water Meter Room 10
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Gas Distribution Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Vent</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Pressure Booster</b>	Inspected
Instance	Basement - MER 9 - Sprinkler/Gas/Water Meter Room 10
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	N/A
Capacity/Size Quantity	15000
Capacity/Size UOM	SCFH
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not exist
<b>Hydronic Heating</b>	Inspected
<b>Backflow Preventer</b>	Does not exist
<b>Hot Water Heat Exchanger</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement - MER 9



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>MER Steam and Condensate Piping</b>	
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Condensate Return Pumping System</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Steam Piping</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	
	Does not exist
<b>Steam supplied by External Sources</b>	
	Does not exist
<b>Unit Heater/Cabinet Heater</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	
Replacement Quantity	6,608
Replacement Uom	MBH NET
Instance on Basement	Inspected
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
<b>Boiler Auxiliaries</b>	
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Does not exist
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X034**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Safety Valve</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler System</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not exist
<b>Modular Boiler</b>	
Instance on Basement	Does not exist
<b>Steam Boiler</b>	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	3,304
Instance Quantity Uom	MBH NET
Manufacturer	Cleaver Brooks
EquipmentId	108332-1
Capacity/Size Quantity	38
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	3,304
Instance Quantity Uom	MBH NET
Manufacturer	Cleaver Brooks
EquipmentId	108332-2
Capacity/Size Quantity	38
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Steam Boiler</b>	
Violations	No violations recorded
<b>Fuel System</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>CO Detector</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE SHUT-OFF SWITCH
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Grease Trap</b>	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/CLOGGED
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Hood</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X034**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>Hood Exhaust Ductwork</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Kitchen Sink</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MDF Room</b>	
Instance on Room 431	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Room 431	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
	Does not exist
<b>SCIENCE PREP ROOM</b>	
	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>Fire Booster Pump Assembly</b>	
	Does not exist
<b>Roof Tank</b>	
	Does not exist
<b>Siamese Connection</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sprinkler Head</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sprinkler Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Standpipe System</b>	
	Inspected
<b>Hose Valve Assembly</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Water Gong</b>	
	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>SWIMMING POOL</b>	
	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2018-2019

*Mechanical Inspection*

**X034**

Question	Response
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Metal Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not exist
<b>Unit Ventilator</b>	Does not exist