

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

School: **P.S. 57 - BRONX, 2111 CROTONA AVENUE, BRONX, NY, 10457**

InspectionId	Inspection Type	Time In	Last Edited
4987	MECHANICAL	2019-05-22 11:05AM	2019-06-01 12:56PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Gas Fired Domestic Water Heater; Science Lab Years: 2009 Systems: CO/Gas Leak Detection; Kitchen - Grease Trap; DX Split Systems for Kitchen Years: 2010 Systems: Kitchen - Gas System, Hood, Hood Exhaust Ductwork, Hood Fire Suppression System, Hood Exhaust Fan Years: 2014 Systems: Hydraulic/Pneumatic Booster System - Pressure Booster Pump (1 of 2); MDF Room - Dedicated A/C Equipment (1 of 2, DX Split System) Years: 2015
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Basement - Boiler Room Mechanical Area, North MER, South MER; Penthouse Fan Room above Auditorium; Main Roof - Penthouse Fan Room, Bulkhead Fan Room
Are there any spaces with Missing or Defective CO Detectors?	Kitchen, Science Lab
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	(1)	Boiler Safety Valve	Boiler Room @ Boiler #1	Greg Bracco	Fireman	No Photo Taken

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
Dry Cooler	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	
	Does not exist
CLIMATE CONTROL SYSTEM	
	Inspected
BMS	Does not exist
Electric System	Does not exist
Hybrid System	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	South Multi-purpose Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	
	Does not exist
CONVEYING	
	Does not exist
DOMESTIC WATER SYSTEM	
	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Pressure Booster Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Water Pressure Booster - Compressor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Service	Inspected
Instance	Basement - 188th Street Side
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - 188th Street Side
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Storage Room (Crotona Avenue Side)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Storage Room (Crotona Avenue Side)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	275
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	100
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room Mechanical Area @ Domestic Cold Water Tank
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement Storage Room, Boiler Room Mechanical Area, Oil Tank Room
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	VENT PIPING:DETERIORATED
Deficiency Location/Instance	Building Exterior near Main Entrance
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE
Deficiency Location/Instance	3rd Floor Boy's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
Enclosed IDF Room	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Condition	2- Between Good and Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	1st Floor Girl's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, Gas Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Basement - Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	N/A
Capacity/Size Quantity	29500
Capacity/Size UOM	SCFH
Source of Capacity/Size	Documented
Installation Year	1998
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convactor/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Stair "H" between 5th Floor and Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Room inside Library
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	South MER @ AHU-2
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	South MER @ AHU-2; North MER @ AHU-3
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE TANK
Deficiency Location/Instance	South MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
HEATING	
Steam Heating	
Steam Condensate Return Pumping System	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	South MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Various locations
Deficiency Quantity	80
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING PLANT	
Replacement Quantity	12,996
Replacement Uom	MBH NET
Instance on Basement	Inspected
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Feedwater Treatment(Automatic)	
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Manufacturer	Kewanee Boiler Corporation
EquipmentId	5469-01
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1998
Source of Installation Year	Inspector Estimate
Deficiency	LEAKY/PLUGGED TUBES

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RUSTED CASING
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Manufacturer	Kewanee Boiler Corporation
EquipmentId	5469-02
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1998
Source of Installation Year	Inspector Estimate
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED REFRACTORY
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RUSTED CASING
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
HEATING PLANT	
Fuel System	
Burner/Burner Control Panel	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	OIL LEAK DETECTOR IN TANK ROOM:DEFECTIVE
Deficiency Location/Instance	Oil Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FUEL OIL PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room near Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
KITCHEN	
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
KITCHEN	
Hood Exhaust Ductwork	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	
Instance on Room 102B	Inspected
Dedicated A/C Equipment	
Instance on Room 102B	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 513	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 513	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	
Instance on Room 513	Inspected
Instance Condition	5- Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Room 513
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Emergency Shower	
Instance on Room 513	Does not exist
Eye Wash	
Instance on Room 513	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 513
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
SCIENCE LAB	
Eye Wash	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fixed Laboratory Hood	
Instance on Room 513	Does not exist
Hood Exhaust Ductwork	
Instance on Room 513	Does not exist
Hood Exhaust Fan	
Instance on Room 513	Does not exist
Laboratory Sink	
Instance on Room 513	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 513	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Penthouse Fan Room / EF-4A (belt)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	North MER / AHU-4 (belt)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X057

Question	Response
VENTILATION	
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Multi-purpose Rooms, Auditorium
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist