

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

School: **P.S. 333 - BRONX, 888 REV. J.A. POLITE AVENUE, BRONX, NY, 10459**

InspectionId	Inspection Type	Time In	Last Edited
3325	ELECTRICAL	2019-03-26 09:12AM	2019-04-25 02:40PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Molded Case Circuit Breaker Type Panel Boards Years: 2017, 2001, 1998, 1993 Systems: Telephone System, LAN, Partial Intrusion Alarm System (Panic Switches) Years: 2017 Systems: Fire Alarm System (Digital Communicator) Years: 2014 Systems: Fire Alarm System (Sub-Panels) Years: 2014, 1997 Systems: Interior Lighting Except Library and Student Toilet Rooms (Pendant Fluorescent Lights) Years: 2013 Systems: Auditorium (Local Sound System and Projection System) Years: 2012 Systems: Library, Student Toilet Rooms (Pendant Fluorescent Lights), Battery Pack Exit Lights Years: 2010 Systems: Intrusion Alarm System (Remote Annunciators) Years: 2008 Systems: Intrusion Alarm System (Except Panic Switches and Remote Annunciators) Years: 2003 Systems: Most Security Lights Years: 2000 Systems: Most Emergency Lighting, Partial Service Switches Years: 2018 Systems: Partial Service Switches, Emergency Light/Exit Light Panel Years: 1993
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Gjergj Markaj	Custodian	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
AUDITORIUM	
House Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Does not exist
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor By General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Does not exist
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Condition	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Silent Knight
EquipmentId	Transmitter
Capacity/Size Quantity	5

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
FIRE ALARM SYSTEM	
Fire Alarm Digital Communicator	
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Cutout Panel	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	
	Does not exist
Magnetic Door Holder/Contactor	
	Does not exist
Main Panel	
	Inspected
Bell At Panel	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
	Does not exist
Fire Alarm Control Panel (Standard)	
	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Capacity/Size Quantity	8
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	113,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
	Does not exist
Strobe	
	Does not exist
Sub-Panel	
	Inspected
Bell At Panel	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	Series 1000
EquipmentId	Fire Alarm Control Panel

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	
Capacity/Size Quantity	14
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	PAD-3
EquipmentId	BPS
Capacity/Size Quantity	8
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 3rd Floor - Annex	Inspected
Lighting	
Instance on 3rd Floor - Annex	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor - Annex	Inspected
Pendant Mounted	
Instance on 3rd Floor - Annex	Does not exist
Recessed Mounted	
Instance on 3rd Floor - Annex	Does not exist
Surface Mounted	
Instance on 3rd Floor - Annex	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 3rd Floor - Annex	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor - Annex	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor - Annex	Inspected
Pendant Mounted	
Instance on 3rd Floor - Annex	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on 3rd Floor - Annex	Does not exist
Surface Mounted	
Instance on 3rd Floor - Annex	Does not exist
Local Sound System	
Instance on 3rd Floor - Annex	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor - Annex	Does not exist
Scoreboard	
Instance on 3rd Floor - Annex	Does not exist
Theater Lighting System	
Instance on 3rd Floor - Annex	Does not exist
INTERCOM SYSTEM	
Does not exist	
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	
Inspected	
Local Distribution Frame (I/LDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
LIBRARY	
Instance on Room 306	Inspected
Lighting	
Instance on Room 306	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 306	Inspected
Pendant Mounted	
Instance on Room 306	Does not exist
Recessed Mounted	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 306	Does not exist
Lighting Fixture - HID	
Instance on Room 306	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 306	Does not exist
Lighting Fixture - LED	
Instance on Room 306	Does not exist
Projection System	
Instance on Room 306	Does not exist
Raceway With Receptacles	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Instance on Basement - Annex	Inspected
Lighting	
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Instance on Basement - Annex	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Instance on Basement - Annex	Inspected
Pendant Mounted	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Recessed Mounted	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Surface Mounted	
Instance on 1st Floor - North	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Annex	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
Theater Lighting System	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
MULTIPURPOSE ROOM	
Theater Lighting System	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Instance on Basement - Annex	Does not exist
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement, Auditorium and Penthouse Fan Rooms
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor By Room 261, Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Multipurpose Room South; Corridor By Auditorium, Corridors By Rooms 261, 410, and 508
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Multipurpose Room South; Corridors By Rooms 261, 410, 508; Corridors By Auditorium
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Annex Multipurpose Room; Corridors By Rooms 161, 310, 361, 505; Corridor By Auditorium
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 211
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 211
Deficiency Quantity	113,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Basement - Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor (sensor #15)
Deficiency Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
	Does not exist
Lighting - Security	
	Inspected
Condition	4- Between Fair and Poor
Replacement Quantity	39
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Ramp Under Lighting, Roof on Rogers Place Side of Building, Wall on North Play Yard
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE PHOTOCCELL NOT OPERATIONAL
Deficiency Location/Instance	Roof
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Service Switch

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	Disconnect for Emergency Light Panel
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	CPP-301
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	CPP
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	ACPP-5A

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	ACPP-1A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eaton
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Switch Gear
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X060

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	
	Does not exist
TV SYSTEM	
Cable System Exist?	Inspected
Operational?	Yes
	No
Main Equipment Rack	Does not exist